

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cai Jie Feng

TK MOTOR WORKSHOP

1 KAKI BUKIT AVE 6 #02-56
SINGAPORE 417883
TEL: 9627 3323 FAX: 6844 2641
CO. REG NO: 53049097L

Date: 28/12/2020

Blk 196-C Punggol Field #11-493

Singapore 823196

TP China.

Veron.

Accident Date: 11/09/2020

Estimate Cost of Repair Bill To Toyota Car No: SJW9669Y

Model: Toyota Harrier G Sport Version

Chassis No: ZSU 600092263

1 pc Rear Bumper Deformed.	✓ S \$1406.40
1 pc Rear Bumper side LH Retainer Not New	X \$50.10
1 set Rear Bumper Reverse Sensor Not New	X \$200 S/Net
8 pc Rear Bumper Clip New	✓ \$30.40
1 pc Rear Bumper Lower Spoiler Cut	✓ \$712.60
8 pc Rear Bumper Lower Spoiler clip New	✓ \$36.00
1 pc Rear LH Tail Lamp Cut	48060 \$689.40
Labour charge For Panel Beating, Removing All Damage Parts & Replacing Of the New Parts Etc.	250 \$280.00
To check Wiring	30 \$50.00
To Spray Painting (Pearl White)	200 \$300.00
To Measure, Drill The Replaced Rear Bumper, Position & Reinstall Rear Reverse Sensor, Control unit & Test For Functioning	50 \$80.00
List: 266	Labour: 530
Len 25% 1999.50	total: 2529.50
	Total: S \$3834.90

A/S

2K

03 Days