Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20010210/R1GA3Q2

Date: 13/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015

Claimant SLR7/32D Insured Vehicle No: SHA700/IT

Vehicle No: SLR7432D Insured Vehicle No: SHA7004T

Date of Loss: 10/09/2020 Nature of Claim: TP Claim No: MCT20090135

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR7432D

 Make & Model:
 TOYOTA C-HR HYBRID, 1.8 S CVT (A)
 Engine No:
 2ZR8136839

 Reg. Date:
 25/08/2017 (Man. Year: 2017)
 Chassis No:
 ZYX102050999

 Colour:
 Red
 Odometer:
 26901 km

Engine Capacity: 1797 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|----------------------|------------|------------|--------|
| Parts | 1,407.80 | 965.82 | 441.98 | 31.40 |
| Miscellaneous Items | 11.00 | 11.00 | 0.00 | 0.00 |
| Labour | 295.00 | 210.00 | 85.00 | 28.81 |
| Paintwork Labour | 436.56 | 436.56 | 0.00 | 0.00 |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$ | 2,150.36 | 1,623.38 | 526.98 | 24.51 |
| Approved Total (Overridden) (S\$ |) | 1,612.38 | | |
| (S\$ | 2,150.36 | 1,612.38 | 537.98 | 25.02 |
| + GST 7.00/7.00% (S\$ | 150.53 | 112.87 | 37.66 | 25.02 |
| Nett Amount (S\$ | 2,300.89 | 1,725.25 | 575.64 | 25.02 |
| + Car Rental (3.0 x S\$140.00/day | + 7.00% GST) (S\$) | 449.40 | | |
| + Do | oc/Search Fee (S\$) | 7.49 | | |
| | Nett Liability (S\$) | 2,182.14 | | |

INSPECTION

Date of Assignment: 23/09/2020 Present Location: Mova Automotive Pte Ltd (Bukit

Merah)

Date Inspected: 14/10/2020 Inspected At: Mova Automotive Pte Ltd (Bukit

Merah)

Blk 1008, #01-04/06/08/94, Bukit

Merah Lane 3 Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Jan 2021)

Parts: M1-SUV TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR7432D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

0----

Danainania

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-------|---------|--------------|-------------------------------|----------------------------|------------|------------|
| 1 | 1 | NA | *BADGE MODEL | Serviceable | 54.60 FL | *- FL |
| 2 | 1 | NA | *CLIP FASTENING | Serviceable | 50.00 FL | *- FL |
| 3 | 1 | NA | *L/PARK SENS BRCKT (NPA) | Not Necessary | 0.00 FL | *- FL |
| 4 | 1 | NA | *L/R CTR SENSOR BRKT (NPA) | Not Necessary | 0.00 FL | *-FL |
| 5 | 1 | NA | *LOWER COVER LID | Serviceable | 52.30 FL | *- FL |
| 6 | 1 | NA | *MANUFACTURER BADGE | Not Necessary | 66.70 FL | *- FL |
| 7 | 1 | NA | *R/PARK SENS BRCKT (NPA) | Not Necessary | 0.00 FL | *- FL |
| 8 | 1 | NA | *R/R BUMPER COVER | Scratched | 95.30 FL | *95.30 FL |
| 9 | 1 | NA | *R/R CTR SENSOR BRKT (NPA) | Not Necessary | 0.00 FL | *- FL |
| 10 | 1 | NA | *REAR BADGE | Not Necessary | 66.20 FL | *- FL |
| 11 | 1 | NA | *REAR BUMPER | Deformed | 533.10 FL | *533.10 FL |
| 12 | 1 | NA | *RR KEYLESS GO AERIAL | Serviceable | 299.50 FL | *- FL |
| 13 | 1 | NA | *RR LWR BUMPER COVER | Deformed | 392.70 FL | *392.70 FL |
| 14 | 1 | NA | *SUNDRY PARTS (NPA) | Not Necessary | 0.00 FL | *- FL |
| 15 | 1 | NA | *REVERES SENSOR | Scratched | 200.00 FS | *200.00 FS |
| F=Fra | anchise | part. S=SpcN | ett. L=ListItemDisc. | _ | | |
| | | | | Sub Total (S\$) | 1,810.40 | 1,221.10 |
| | | | - List Item Discount on L | Items 25.00/25.00% (S\$) _ | 402.60 | 255.28 |
| | | | | Total Parts (S\$) | 1,407.80 | 965.82 |

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

| No | Qty | Particulars | | Repairer's | Amount |
|-----|-------|----------------------|-----------------|------------|--------|
| Mis | cella | neous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | | 11.00 | 11.00 |
| | | | Sub Total (S\$) | 11.00 | 11.00 |

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------|-------------------------------|-------------------------|------------|--------|
| Pair | ntwork Labour | | | |
| 1 | Total Paint Labour | New | 330.00 | 330.00 |
| 2 | Total Paint Materials | New | 106.56 | 106.56 |
| Lab | our Items | | | |
| 3 | Total Panel/Mechanical Labour | New | 295.00 | 210.00 |
| | | Gross Labour Cost (S\$) | 731.56 | 646.56 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >