DVA Automotive Pte Ltd Ak 1008, Bukit Merah Lane 3, #01-04/06/08. Singapore 159722

Insurer Reference:

Repairer Reference: CK139006

Date calculated: 15/09/2020 4:01 PM

Full Report Registration: SLR7432D Printed: 15/09/2020 4:01 PM

Summary Information

Claim

Location:

Singapore (SG)

Work Provider:

India International

Insurance

Printed by:

Claim Reference:

GOH CHAI HOCK

Currency:

SGD 10/09/20

Estimated Repair Time:

Actual Repair Days:

Date of Incident: Hire Car Start:

Hire Car End:

Vehicle Details

Vehicle

Manufacturer:

TOYOTA

Model:

C-HR

Sub Model: Model Sheet Number: BASE MODEL 70 CH 01

Registration:

SLR7432D

VIN number:

Odometer:

Model Specs

KEYLESS GO

INTELLIG PARKING SYS

PREPARE OFF VEHICLE

Vehicle Condition


Vehicle Status

Pre-Accident Damage: Date of Inspection:

Damage Areas

AII

Underbody



pour					
	Time Base 10 WU/	'h	Pr	ice = 50	0.00 SGD/h
ode	Description				Price SGD
550171	RENEW TAILGATE BADGE "VERSION"			5.0	25.00
750171	R + R MODEL BADGE			5.0	
750171	R + R REAR BADGE			5.0	25.00
B420	RENEW REAR BUMPER			15.0	75.00
	INCLUDES: BUMPER AND ALL				
2410)	REQUIRED ATTACHED PARTS R + R				
B410) NO NUMBER	R + R REAR BUMPER REINFORCEMENT			2.0	
NO NOMBER 2711	R + R REAR KEYLESS GO AERIAL END PANEL REPAIR			2.0	
2931	BOOTLID/TAILGATE REPAIR			5.0*	
2931	BOOTLID/TAILGATE REPAIR			20.0*	100.00
	Labour Cost		Hrs	wu	
	Panel / Mechanical Labour		5.90	59.0	295.00
	Total of Labour				295.00
Paint					
Paint Work	SYSTEM AZT		Ti	me Basi	s 10 WU/h
Code	Description			wu	- 1500 M
	REAR BUMPER NEW PART PAINT K1R			8.0	
	L/R PARK SYS SENSOR NEW PART PAINT K1R			3.0	
	R/R PARK SYS SENSOR NEW PART PAINT K1R			3.0	
	END PANEL REPAIR PAINTING <50%			11.0	
	BOOTLID/TAILGATE REPAIR PAINTING <50%			15.0	
	TAILGATE MOULDING SURFACE PAINT PLAST.			4.0	
aint Materia	Per Part				
Code	Description				Price SGD
581	REAR BUMPER NEW PART PAINT K1R				28.97
2673	L/R PARK SYS SENSOR NEW PART PAINT K1R				0.35
1674	R/R PARK SYS SENSOR NEW PART PAINT K1R				0.35
711 931	END PANEL REPAIR PAINTING <50%				11.50
1988	BOOTLID/TAILGATE REPAIR PAINTING <50%				21.00
-500	TAILGATE MOULDING SURFACE PAINT PLAST.				6.79
		*			
	Labour Cost - Paint		Hrs	WU	Price SGD
	Factor 50	0.00 SGD/h	1113	****	File Sup
	Time Paint			44.0	
	Preparation Main Work Metal		1.90	19.0	95.00
	Preparation Comp. Work Plastic Total		0.30	3.0	15.00
	iotai	10 WU/h	6.60	66.0	330.00

Material Cost - PaintPrice SGDNew Part Painting - Plastic K1R29.67Repair Painting32.50Surface Painting Plastic6.79Material-constant Metal Preparation28.60Material-constant Plastic9.00Total106.56

Spare Parts

Code	Description	Down Number	D	prices as at 2015-06-01/01
Code	Description	Part Number	Part Source	Price SGD
3019	BADGE MODEL	75442 F4011	Original	X 54.60
2685	CLIP FASTENING	52161 02030	Original	× 50.00
2679	L/PARK SENS BRCKT	89348 F4140C0	J	0.00
2677	L/R CTR SENSOR BRKT	89348 F4120		0.00
3415	LOWER COVER LID	52162 F4010	Original	× 52.30
3022	MANUFACTURER BADGE	75441 F4011	Original	× 66.70
2680	R/PARK SENS BRCKT	89348 F4140C0	3	0.00
2590	R/R BUMPER COVER	52163 F4020	Original	5ch 95.30
2678	R/R CTR SENSOR BRKT	89348 F4130		0.00
3015	REAR BADGE	90975 W2006	Original	×_66.20
2581	REAR BUMPER	52159 F4908	Original	de 533.10
2634	RR KEYLESS GO AERIAL	89997 30100	Original	× 299.50
2583	RR LWR BUMPER COVER	52453 F4021	Original	de/392.70
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			1,610.40
u: Used parts	Subtotal Discount(+	25.00%)		-402.60
				-402.80
	Total			1,207.80

Extras

Code	Description	Price SGD
1000	REVERES SENSOR SUL / Total Extras	200.00*

Audatex System Using Manufacturer Times

Page 3 of 4

PRINT DATE 15/09/2020

Tyre Size:

Ľ

n
п

li di	SGD	SGD
barts	1,610.40	
Total Discount(+25.00%)	-402.60	
Total Parts		1,207.80
Labour Time Base 10 WU/h		
Total 59.0 WU X 50.00 SGD/h	295.00	
Total of Labour		295.00
Total Of Extras		200.00
Paint Work Time Base 10 WU/h		
Labour Cost 66.0 WU X 50.00 SGD/h	330.00	
Material Cost	106.56	
Total Paint Including Material		436.56
Repair Cost Excludes GST		2,139.36
GST (+7.00%)		149.76
Repair Cost Included GST		2,289.12

Comments

Modi: Nil 18ftin 1 STD ARIM OF 235/55/19

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

LKK Auto Consultants hence notify

- the Repairer of the following:
- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
 Third parts are
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL
Hy 90010068
3 days
14/10/2020 @ 1210
4/8
Roay after repair

Audatex System Using Manufacturer Times

Page 4 of 4

PRINT DATE 15/09/2020

Stent?:Yestent?:Y







