Adjuster Report Page 1 of 3

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20010217/UES3Q2

Date: 02/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070112738 Claimant FBK1740J Insured Vehicle No: SMV818M Vehicle No:

Date of Loss: 30/08/2020 ΤP Nature of Claim: Claim No: 8663142331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

FBK1740J Reg No:

Make & Model: YAMAHA YBR125, 124cc (M) Engine No: E3F5E038570

Chassis No: Reg. Date: 13/04/2015 (Man. Year: 2015) LBPRE101000053644

Colour: Odometer: Red 44241 km

Engine Capacity: 124 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

CONDITION OF TYRES

Front Tyre Size: 2.75-18 Rear Tyre Size: 3.00-18 Front Left Side: Rear Left Side: Metzeler 6 mm Metzeler 6 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	902.00	61.20	840.80	93.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	182.00	50.00	132.00	72.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,084.00	111.20	972.80	89.74
+ GST 7.00/7.00% (S\$)	75.88	7.78	68.10	89.75
Nett Amount (S\$)	1,159.88	118.98	1,040.90	89.74

Global Sum Settlement (S\$) 0.00

INSPECTION

Date of Assignment: 23/09/2020

Ban Hock Hin Co. Pte Ltd (HQ) 23/09/2020 Inspected At: Date Inspected:

No. 6 Defu Lane 4 Singapore 539410

Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No	. Particulars	Condition	Repairer's	Amount
1	1		*CRASH BAR (BENT)	Not Consistent With The Impac	203.00 F	*- FL
2	1		*LAMP SIGNAL REAR LH (SCRATCHED)	Not Consistent With The Impac	16.00 F	*- FL
3	1		*MUDGUARD FRONT (RED) (CUT)	Not Consistent With The Impact	97.00 F	*- FL
4	1		*MUDGUARD REAR	Cracked	68.00 F	*68.00 FL
5	1		*RIM SPORT REAR (TUBELESS RIM)	Repair	518.00 F	*- FL
F=Fra	ınchise	part. L=List	tltemDisc.			
				Sub Total (S\$)	902.00	68.00
- List Item Discount on L Items 0.00/10.00% (S\$)					0.00	6.80
				Total Parts (S\$	902.00	61.20
			Report was unsubmitted	during this print-out.		

Adjuster Report Page 3 of 3

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR QUOTED FOR DISMANTLE AND INSTALLATION OF PARTS	New	126.00	50.00
2	TRANSPORT CHARGES	New	56.00	0.00
	Gross Labour Cost (S\$)		182.00	50.00
	Report was unsubmitted durin	a this print-out		

< END OF ESTIMATES >