

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010220/AGS3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2070064438

Claimant
Vehicle No : SGV3916P **Insured Vehicle No :** SFK32D

Date of Loss: 22/09/2020 Nature of Claim: TP Claim No: 6875949220SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGV3916P		
Make & Model:	TOYOTA AXIO, 1.5 X (A)	Engine No:	1NZC513480
Reg. Date:	13/06/2007 (Man. Year: 2007)	Chassis No:	NZE1416020525
Colour:	Silver	Odometer:	450587 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,513.75	2,066.05	3,447.70	62.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,980.00	1,540.00	440.00	22.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,493.75	3,606.05	3,887.70	51.88
Approved Total (Overridden) (S\$)		2,900.00		
(S\$)	7,493.75	2,900.00	4,593.75	61.30
+ GST 7.00/7.00% (S\$)	524.56	203.00	321.56	61.30
Nett Amount (S\$)	8,018.31	3,103.00	4,915.31	61.30
+ Loss of Use (60.0 x S\$8.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		3,614.00		

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 23/09/2020 Inspected At:

Ryder Auto Workshop LLP (HQ)
1 Kaki Bukit Ave 6, #01-56, Autobay
@ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	781.40 F	*655.10 FL
2	10		*REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
3	1		*REAR BUMPER O/S RETAINER	Necessary	81.35 F	*35.00 FL
4	2		*REAR BUMPER O/S & N/S SCREW	Not Necessary	10.00 FS	*- FS
5	1		*REAR BUMPER O/S STAY	Dented	86.30 F	*86.30 FL
6	1		*REAR BOOT COVER	Buckled	974.40 F	*801.00 FL
7	1		*REAR BOOT COVER AXIO EMBLEM	Necessary	61.70 F	*61.70 FL
8	1		*REAR BOOT COVER X EMBLEM	Necessary	59.50 F	*59.50 FL
9	1		*REAR BOOT COVER LOCK (UPPER)	Damaged	291.60 F	*185.00 FL
10	1		*REAR BOOT COVER WEATHERSTRIP	Cut	174.40 F	*174.40 FL
11	1		*REAR BOOT COVER EMBLEM	Necessary	61.50 F	*61.50 FL
12	1		*REAR END PANEL	Dented	581.90 F	*581.90 FL
13	1		*REAR END PANEL INNER TRIM	Not Necessary	253.50 F	*- FL
14	1		*REAR O/S TAIL LAMP	Not Necessary	984.40 F	*- FL
15	1		*REAR O/S TAIL LAMP SEAL	Not Necessary	60.00 F	*- FL
16	1		*REAR O/S TAIL LAMP PANEL	Repair	431.80 F	*- FL
17	1		*SET REAR REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
18	1		*SOUND PROOF STICKER	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,513.75	2,741.40
- List Item Discount on L Items 0.00/25.00% (\$)	0.00	675.35
Total Parts (\$)	5,513.75	2,066.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REPLACE REAR DAMAGE PARTS	New	1,000.00	800.00
2	TO SPRAY PAINTING	New	800.00	600.00
3	TO REMOVE AND REPLACE REAR REVERSE SENSOR	New	50.00	50.00
4	TO CHECK WIRING	New	50.00	30.00
5	TO RE-SEAL ANTI-RUST	New	80.00	60.00
Gross Labour Cost (\$\$)			1,980.00	1,540.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >