

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877

INV Date 09/10/2020

 $Reference \qquad CC4/FCI20010222/Uda3q2$

AC2006946

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. FBP 3078Z

Insured Veh. SHC 8386Z

Claim No. D20003817MFSH/1

Policy No. D-20094922MFSH

Accident Date 16/09/2020

Inspection Date 23/09/2020

Description	Total
Survey Inspection	294.00
Digital Photographs	
Transportation	
Subtotal	294.00
GST (7%)	20.58
Grand Total	314.58

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

	Affiliated to Federation Internationale Des Experts En Automobile			
MS F	FIRST CAPITAL INSURANCE LTD Ref : CC4/FCl20010222/Uda3q2			
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date: 09-10-2020 Code: FCI2		
1.		Policy Particulars	:- THIRD PARTY CLAIM	
	Insured Veh.	SHC 8386Z	Veh. Inspected	FBP 3078Z
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20003817MFSH/1	Excess (\$)	0.00
	Assign From	CHRIS LIM	Assign Date	23/09/2020
2.		Vehicle Partic	culars & Condition	
	Make & Model	HONDA CB300R	c.c	286
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MLHNC5578J5002287	Colour	RED
	Odometer	12012	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3.		Condition	ons of Tyres	
		Size	Make	Balance
	R/H Front Tyre	110-70 R17	DUNLOP	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	150-60 R17	DUNLOP	7 mm
	L/H Rear Tyre			mm
4.		•	on of Damages	
	THE VEHICLE SU	STAINED DAMAGES AT THE N/S	FRONT PORTION AND O/S	BODY.
	DAMAGES SEE D	ETAILS.		
5.		General	Information	
	Accident Date	16/09/2020	Inspection Date	23/09/2020
	Survey held at	BAN HOCK HIN CO.PTE LTD		
		NO 6 DEFU LANE 4 SINGAPORE 539410		
5a.		Re	emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		REPAIRS.
5b.	b. Estimate Days of Repair			
	ESTIMATED NORI	MAL PERIOD FOR REPAIR:	4 Working Days	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBP 3078Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	AXLE FRONT WHEEL	CUT	58.00	58.00
2	BALANCER HANDLE @\$33.00	CUT	66.00	66.00
1	BAR HANDLE	BENT	159.00	159.00
2	BOLT ONE -WAY 8MM @\$13.00	NECESSARY	26.00	26.00
1	BOX REAR (KAPPA) K-VENTURE 48L	CUT	871.00	871.00
1	BRACKET UNDER FORK	BENT	241.00	241.00
1	COVER 1 EXHAUST	CUT	229.00	229.00
1	COVER 2 EXHAUST	CUT	174.00	174.00
1	COVER HEADLAMP	* CHECK	66.00	-
1	COVER LH FUEL TANK RED	CUT	195.00	195.00
1	COWLING LH FRONT	* CHECK	35.00	-
1	COWLING RH FRONT	* CHECK	35.00	-
1	CROWN HANDLE	BENT	133.00	133.00
1	EXHAUST ASSY	TO REPAIR SEE LABOUR	1,596.00	-
1	FOOTREST SET FRONT (GTR) RED	TO REPAIR SEE LABOUR	503.00	-
1	FORK FRONT LH ASSY	BENT / TWISTED	1,022.00	1,022.00
1	FORK FRONT RH ASSY	BENT / TWISTED	1,022.00	1,022.00
1	GASKET EXHAUST	NOT NECESSARY	19.00	-
1	GROMMET REAR COWLING	NOT NECESSARY	19.00	-
1	HEADLAMP ASSY	* CHECK	615.00	-
1	HOLDER HANDLE LOWER	* CHECK	31.00	-
1	LEVER SET (GTR) (BLACK)	SCRATCHED	324.00	324.00
1	MIRROR RH ASSY	CUT	174.00	174.00
1	MUDGUARD FRONT BLACK	CRACKED	115.00	115.00
1	PLATE DIS BRAKE FRONT	* CHECK	252.00	-
1	RIM FRONT ASSY	BENT	583.00	583.00
1	RUBBER PROTECTOR MOUNT	NECESSARY	8.00	8.00
1	SCREW ,PAN (6X12)	NECESSARY	13.00	13.00
1	STAY COWLING FRONT	NECESSARY	58.00	58.00

Report Ref No. CC4/FCI20010222/Uda3q2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
1	SET STEERING CONE	NECESSARY	47.00	47.00
2	STICKER 'ABS'@\$42.00	NECESSARY	84.00	84.00
	LESS 10% DISCOUNT		-	-560.20
			8,773.00	5,041.80
	LABOUR LABOUR QUOTED FOR DISMANTLING AND INSTALLTION OF PARTS.INCLUSIVE OF THE REPAIR OF EXHAUST ASSY AND FOOTREST SET FRONT (GTR) RED.		504.00	350.00
			504.00	350.00
	GRAND TOTAL		9,277.00	5,391.80

RECOMMENDED COST OF REPAIRS		5,391.80
(REPAIR COST NOT CONCLUDE)		
(EXCLUDE CHECK ITEMS S\$1,034.00 NETT)		

Report Ref No. CC4/FCI20010222/Uda3q2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBP 3078Z


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Sngapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315


















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933




















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315

















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3581 F.AX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933



