

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010227/R1QF3Q2**Date:** 10/11/2020**REFERENCE**

Insured/Claimant: MOEY HON MENG Policy No: 1700078587
Date of Loss: 22/09/2020 Nature of Claim: OD Claim No: 1100676085SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT9102H**
Make & Model: CITROEN GRAND C4 PICASSO, 1.6 BLUEHDI EAT6 (A) Engine No: 10JBHD3086899
Reg. Date: 16/11/2017 (Man. Year: 2017) Chassis No: VF73ABHZTHJ767307
Colour: Blue Odometer: 41478 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$73,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,796.40	5,368.40	2,428.00	31.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,875.00	2,955.00	920.00	23.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,671.40	8,323.40	3,348.00	28.69
+ GST 7.00/7.00% (S\$)	817.00	582.64	234.36	28.69
Nett Amount (S\$)	12,488.40	8,906.04	3,582.36	28.69

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 24/09/2020 Inspected At:

Cycle & Carriage France Pte Ltd
(Pandan Gardens) (HQ)
209 PANDAN GARDENS
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,109.00 FL	*1,109.00 FL
2	1		*BUMPER BRACKET	Bent	335.00 FL	*335.00 FL
3	1		*BUMPER SKIRT	Deformed	367.00 FL	*367.00 FL
4	1		*BRACKET SET	Serviceable	137.00 FL	*- FL
5	1		*BRACKET SET LAT	Serviceable	137.00 FL	*- FL
6	1		*BUMPER BRACKET	Cracked	331.00 FL	*331.00 FL
7	1		*STIFFENER LH	Serviceable	85.00 FL	*- FL
8	1		*STIFFENER RH	Serviceable	85.00 FL	*- FL
9	1		*ECU	Serviceable	496.00 FL	*- FL
10	1		*BUMPER BRACKET	Serviceable	89.00 FL	*- FL
11	1		*LOW RR PAN FIX	Necessary	168.00 FL	*168.00 FL
12	1		*WHL OPEN MECH	Serviceable	355.00 FL	*- FL
13	1		*TAILGATE	Deformed	2,667.00 FL	*2,667.00 FL
14	1		*TLGT EXT PANEL	Deformed	613.00 FL	*613.00 FL
15	1		*TLGATE MOULDING	Deformed	266.00 FL	*266.00 FL
16	1		*WEATHERSTRIP	Serviceable	179.00 FL	*- FL
17	1		*TAILGATE MODULE	Serviceable	435.00 FL	*- FL
18	1		*LOWER TRIM	Serviceable	455.00 FL	*- FL
19	1		*TAILGATE FIX	Necessary	362.00 FL	*362.00 FL
20	1		*BADGE	Not Necessary	66.00 FL	*- FL
21	1		*BADGE	Necessary	66.00 FL	*66.00 FL
22	1		*BADGE	Necessary	72.00 FL	*72.00 FL
23	1		*TAILGATE LOCK	Serviceable	138.00 FL	*- FL
24	1		*TAIL-LIGHT RH COMPLEMENTAIRE	Cracked	217.00 FL	*217.00 FL
25	2		*SENSOR	Serviceable	378.00 FL	*- FL
26	1		*REAR NUMBER PLATE WITH FRAME	Cracked	50.00 FS	*50.00 FS
27	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
28	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	9,718.00	6,683.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,921.60	1,314.60
Total Parts (\$\$)	7,796.40	5,368.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW REAR BUMPER, TAILGATE, TAILGATE LOWER PANEL, REPAIR REAR END PANEL	New	1,500.00	1,000.00
2	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
3	REMOVE & INSTALL TAILGATE GLASS	New	240.00	240.00
4	APPLY SEALANT FOR REAR WINDSCREEN	New	80.00	80.00
5	REMOVE & INSTALL TAILGATE TRIMS	New	200.00	160.00
6	SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, TAILGATE, TAILGATE LOWER PANEL	New	1,520.00	1,140.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	50.00	50.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	225.00	225.00
Gross Labour Cost (\$\$)			3,875.00	2,955.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >