

Exceptional Journeys

Surveyor: RASUL LKK

Claim : AIG OD

DOA : 22.09.2020

Emailed : 12.10.2020, 4.20pm

Date Survey : 24.09.2020

VEHICLE NO	: SLT 9102 H				
		-			
MODEL	: CITROEN C4 1.6				

WIP : 15670

:<u>\$</u> 5,258.40 Material : \$ 3,065.00 Labour :_\$ 8,323.40 Sub-Total Less Excess : \$:_\$ 8,323.40 Total : \$ 582.64 **GST 7%** :_\$_ 8,906.04 **Grand Total** LOI / 12/10/2020 Finalise By/Date

✓	REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING	
	SURVEYOR'S REPORT REQUIRED	
	REPAIR TOOK 0 WORKING DAYS + 0 Days (0) + 0 Days (0) TOTAL DAYS REPAIR TOOK = 0	Weekends Public Holiday
	TP claim	
	Claim GIA / LTA fee	
	Claim Loss of Use / Rental	
	Claim Medical Fee / Others	
	Third Party Report -	



CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240

PRO-FORMA INVOICE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info				
A.1	C Acia Da	cific Insurance Pte.		Cust No/Name		EY HON MENG		MMING)
	d Asia Pa :d.	Citte insurance rec.		Reg No/Reg Date	SLT9102H	/ 16/11/203	L7	
		DEPARTMENT		Date In/Mileage	25/09/2020/	41480		
		WAY #08-16		Chassis/Package	VF73ABHZTHJ	767307 /	CC17S5	
	G BUILDIN				10JBHD30868			
S	NGAPORE O	79120		Engine No			ATC INTE	NETUE MI
С	ontact No	6419 1000		Make/Model	•	6 BLUEHDI E		
11				Colour/Trim	EBM LAZULI	BLUE / I	XF YATAG	O GREY
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Invoice/	Credit Note No
AX00001	Credit	12/10/2020/ 12:19	BLC	260 / AiTing		15670	_	0
AA00001	Ciedic	Description of Good			Qty	Unit Price	Disc%	Amount
DUTOOOO		Boodinpalent of Good						1000.00
E PNT88000	NAMAGED DA	ARTS, REPLACE REAR BUI	MPFR. TAILO	ATE. TAILGATE			1	
I OUED DA	VANAGED FA NEL REAR	BUMPER SKIRT, REPAIR	ALL OTHER	AFFECTED AREAS,				
A TRIILA	ND ALTEN E	BODY GAPS ALIGNMENT T	O THE SAME					/ co o
F PNT88000							-	60.0
REMOVE &	INSTALL F	PARKING SENSOR TO FAC	ILITATE REF	PAIR				/ 240.0
F PNT88000							j	240.0
REMOVE &	INSTALL 7	FAILGATE GLASS AND CO	NDUCT WATER	FEAK IF21			1	. / 80.0
M SUNDRY								V
	ALANT ON F	REAR WINDSCREEN GLASS						40.0
M SUNDRY	*C 10C0							^
SUPPLY C E PNT88000	ac Logo							160.0
REMOVE &	INSTALL F	REAR TAILGATE TRIMS A	ND ALL OTH	ER ATTACHMENTS TO			İ	
	TE REPAIR	TEME THE BUTTER OF					1	1140.0
E PNT98000								1140.0
RESPRAY	ON REAR BI	UMPER, TAILGATE, TAIL	GATE LOWER	PANEL, AND ALL			Ì	,
		EAS TO THE SAME					1	50.0
A 54900099								
	RING & ELI	ECTRICAL SYSTEM						225.0
A 10028901	D * 4 ON OCT 1	O OUTON AND OLDAD TRO	MIDIE CODE				1	/
	DIAGNOSTI	C CHECK AND CLEAR TRO	JUBLE CODE					20.
M SUNDRY								
SUNDRIES S SPECIALIS							1	50.
SUPPLY 8	REPLACE	REAR LICENSE PLATE WI	TH FRAME			Z		097
X REAR BUN					1.00	1109.00	20.00	887. 293.
X BUMPER S					1.00	367.00	20.00	134.
X LOW RR F	AN FIX				1.00	168.00	20.00	2133.
X TAILGATE					1.00	2667.00 613.00	20.00	490.
					1.00 1.00	266.00	20.00	212.
X TLGT EXT								
	OULDING				1.00	362.00	20.00	289.


Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.



CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE





Company Reg No. 200609327M

PRO-FOF	RMA INVO	ICE						y Reg No. 200609327N g No. MR-8500111-X
	Invo	pice Name & Address	Frank.			Name & Vehicle		
	Ltd.	IG		Cust No/Name Reg No/Reg Date Date In/Mileage Chassis/Package Engine No Make/Model Colour/Trim	SLT9102H 25/09/2020 VF73ABHZTH 10JBHD3086	J767307 / 899 .6 BLUEHDI E	17 CC17S5	IVE ML
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	Invoice/Cr	edit Note No
FAX00001	Credit	12/10/2020/ 12:19	BLC	260 / AiTing		15670	0	VI
FAXUUUUI	- Creuit	Description of Goods		,	Qty	Unit Price	Disc%	Amount
X BUMPER X BUMPER Z TEXT AIG OD DOA: SURVEY	IGHT RH COMI BRACKET BRACKET CLAIM. 22.09.20 OR RASUL NO : 17000	LKK 24.09.20	canty, Mai	ntain with Cycle &	1.00 1.00 1.00 1.00 1.00	217.00 335.00	20.00 20.00	57.60 173.60 268.00 264.80
Diagno: Sundry	ist Job stics Job	50	.00 .00 .00 .00		7% GST	on 8323. Total Payab	ole iid	8,323.40 582.64 8,906.04 0.00 8,906.04

Payment should be made strictly by cash, NETS or credit cards. Thank you.

Any dispute to the invoice must be made within 3 days. This is a computer generated document, no signature is required.

SLT 9102H

After wany DECESSE to clock and Esse of

: DA11572

iicle: C4 PICASSO C4 SPACETOURER/C4

,PACETOURER (B78) VIN: VF73ABHZTHJ767307 Print date: Tuesday, 29 September 2020 6:30:45 PM Start of vehicle session: 29/09/2020 - 18:17

: 29/09/2020 - 18:17 Tool version : 09.76

Global test

Expert/Global test

Vehicle\menu_tgref.s : 81_02

FAMILY NO.

CONTROL UNIT

1

Built-in systems interface

BSI2010_EV (1 Faults)

B1003 00

Configuration fault (warning, this fault may be a phantom fault)

Properties

Cause

Local

Status

Intermittent

Features

Engine management ECU

EDC17C60 (1 Faults)

P02D3 00

Combustion of cylinder N° 4

Properties

Cause

Local

Status

Permanent

Characterisation of the fault

Correction of the quantity of fuel injected

insufficient

List of associated variables

Total distance covered

41479

km

Date

7197355

S

Crankshaft engine speed

0

Rpm

;		
Position of the accelerator pedal	0	%
Vehicle speed	0	kph
Engine coolant temperature	46	°C
Engine management ECU supply voltage	12.12	v
Fuel pressure measured in the high pressure rail	3	bar
Fuel rail pressure reference value	322	bar
Fuel pressure	1.01	bar
Pressure regulator opening cyclic ratio	10	%
Flow regulator current	0	A
Temperature of the fuel	38	°C
Water in diesel	Absence of water	
Calculated flow injected	0.00	mg/stroke
Minimum fuel level	Minimum level not reached	



Anti-lock Braking System (ABS) or Electronic Stability

Program (ESP)

Automatic or piloted manual gearbox


BVA_AM6_AT6_UDS



Controls under the steering wheel

ECU not recognised

Down-grade mode: this information is not guaranteed



Controls on the steering wheel / integral controls steering wheel

VCI

ESP90




Left-hand windscreen wiper motor

MOTEV_UDS



Right-hand windscreen wiper motor

MOTED_UDS



Air conditioning




Important, ECU present on the vehicle but configured absent



Instrument panel

CIROCCO



Rain and brightness sensor

PLUIE_LUMINOSITE_UDS




Airbags and pretensioners ECU RBG_UDS



Battery charge status control unit

BECB_GEN2



Multifunction control panel

FMUX



Parking assistance

ECU not recognised

Down-grade mode: this information is not guaranteed



Telematic unit (RTx) or audionavigation

Communication error




Electronic key reader

Communication error



Electric steering lock


AVE



Signalling fuse box

BSG_S

Important, ECU present on the vehicle but configured absent




Driver's door module

PDPC_UDS




Automatic gearbox electric control ECU

COMELEC2



Power steering


DAE_BVH2



Voltage maintaining device

DMTC

Important, ECU present on the vehicle but configured absent



Motorised Boot Unit

VERINS_MOTORISES (1 Faults)

B1003 55

Configuration fault

Properties

Status

Characterisation of the fault

Permanent

Configuration incorrect or not carried out

P …

Diesel additive pump

PADDGO_INERGY




Additional heating

Communication error



Hands full access ECU, right-hand side or rear

BAAST



Touch screen

EMF_DGT_LVDS_BD Important, ECU present on the vehicle but configured absent




Engine wiring housing

Not present



Trailer relay unit

Not present



External CD player

Not present




Audio amplifier

Not present



Multifunction video camera (CMF)

Not present



Anti-theft alarm

Not present




Intrusion alarm siren

Not present



Vehicle Distance Assistance

Not present



Help