



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2102666

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 15/04/2021
Reference CC4/FCI20010234/Epa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. GBJ 4485G
Insured Veh. SHD 3169L
Claim No. D20003847MFSH
Policy No. D-20094922MFSH
Accident Date 19/09/2020
Inspection Date 23/09/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI20010234/Epa3q2	
			Date: 15/04/2021	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 3169L	Veh. Inspected	GBJ 4485G
	Policy No.	D-20094922MFSH	Coverage (\$)	0.00
	Claim No.	D20003847MFSH	Excess (\$)	0.00
	Assign From	VIC	Assign Date	23/09/2020
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HIACE	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JTFHT02P500248661	Colour	WHITE
	Odometer	40817 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185 R15C	BRIDGESTONE	5 mm
	L/H Front Tyre	185 R15C	BRIDGESTONE	5 mm
	R/H Rear Tyre	185 R15C	BRIDGESTONE	5 mm
	L/H Rear Tyre	185 R15C	BRIDGESTONE	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	19/09/2020	Inspection Date	23/09/2020
	Survey held at	EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD 56 LOYANG WAY #06-07 LOYANG ENTERPRISE BUILDING SINGAPORE 508775		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBJ 4485G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DENTED	496.00	496.00
1	FRONT BUMPER GRILLE	NOT NECESSARY	170.00	-
1	FRONT BUMPER SIDE RETAINER	BROKEN	193.00	118.45
1	FRONT BUMPER FOG LAMP COVER	CRUSHED	105.00	105.00
1	FRONT BUMPER CROSS MEMBER	NOT NECESSARY	160.00	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	302.00	-
1	FRONT GRILLE UPPER	NOT NECESSARY	220.00	-
1	FRONT GRILLE LOWER	NOT NECESSARY	330.00	-
1	FRONT GRILLE INNER	NOT NECESSARY	491.00	-
1	HEADLAMP ASSY RH	BROKEN	750.00	750.00
1	HEADLAMP BRACKET RH	NOT NECESSARY	25.00	-
1	HARNESS ASSY WIRING COWL TO H/LAMP	NOT NECESSARY	1,510.00	-
1	HARNESS ASSY WIRING CASING RH	BROKEN	74.00	74.00
1	FRONT CORNER PANEL RH	NOT NECESSARY	195.00	-
1	FRONT DOOR RH	DENTED	1,800.00	1,794.00
2	FRONT DOOR HINGE RH @\$85.00	DENTED	170.00	170.00
1	FRONT DOOR CHECKER RH	NOT NECESSARY	140.00	-
1	FRONT DOOR WEATHERSTRIP RH	TORN	185.00	185.00
1	FRONT DOOR WEATHERSTRIP RH NO.2	NOT NECESSARY	65.00	-
1	FRONT DOOR WINDOW REGULATOR	NOT NECESSARY	220.00	-
1	FRONT DOOR REGULATOR MOTOR	NOT NECESSARY	650.00	-
1	FRONT STEP GARNISH LH	BROKEN	150.00	150.00
1	FRONT STEP UPPER PANEL LH	NOT NECESSARY	60.00	-
1	FRONT STEP LOWER PANEL LH	NOT NECESSARY	85.00	-
1	AIR FILTER BOX	BROKEN	650.00	650.00
	LESS 25% DISCOUNT		-2,299.00	-1,123.12
			6,897.00	3,369.33
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	50.00	30.00
1	COMPANY REGISTRATION STICKER (SN)	NECESSARY	30.00	30.00

Report Ref No. CC4/FCI20010234/Epa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NOT NECESSARY	50.00	-
1	SET FRONT GRILLE CLIP (SN)	NOT NECESSARY	20.00	-
1	SEALANT FOR DOOR (SN)	NECESSARY	80.00	30.00
			230.00	90.00
	LABOUR			
	TO PANEL BEAT & ALIGN REAR PORTION ,TO REMOVE & REPLACE DAMAGED PARTS.		1,200.00	600.00
	TO TRANSFER DOOR COMPONENTS TO NEW DOOR .		120.00	50.00
	TO APPLY ANTI RUST COAT AND TUFF KOTE REPAIRED AREAS.		100.00	30.00
	TO CHECK AND RECTIFY LIGHTING & WIRING .		60.00	30.00
	TO PUTTY ,SPRAY PAINTING FRONT PORTIONS & OTHER AFFECTED AREAS.		800.00	600.00
	TO CONDUCT WATER LEAK TEST TO ENSURE PROPER AIR & WATER SEALING.		80.00	30.00
			2,360.00	1,340.00
GRAND TOTAL			9,487.00	4,799.33

RECOMMENDED COST OF REPAIRS				4,799.33
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/FCI20010234/Epa3q2

CHEN TSUE YEE

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 4485G

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. GBJ 4485G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

