

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/EGI20010236/R1VD3E2

**Date:** 03/02/2021

### REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMFG20005536  
Claimant Vehicle No: SJU1819U Insured Vehicle No: GBB6998Y  
Date of Loss: 21/09/2020 Nature of Claim: TP Claim No: CDMFG20001334

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJU1819U  
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11AD0394  
Reg. Date: 06/08/2019 (Man. Year: 2018) Chassis No: GF7W0600756  
Colour: Red Odometer: 25797 km  
Engine Capacity: 1998 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R18 Rear Tyre Size: 225/55 R18  
Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm  
Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,039.02	4,724.00	1,315.02	21.78
Miscellaneous Items	0.00	0.00	0.00	
Labour	576.00	576.00	0.00	0.00
Paintwork Labour	456.62	456.62	0.00	0.00
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>7,071.64</b>	<b>5,756.62</b>	<b>1,315.02</b>	<b>18.60</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>495.01</b>	<b>402.96</b>	<b>92.05</b>	<b>18.60</b>
<b>Nett Amount (S\$)</b>	<b>7,566.65</b>	<b>6,159.58</b>	<b>1,407.07</b>	<b>18.60</b>

### INSPECTION

Date of Assignment: 28/09/2020 Present Location: Mova Automotive Pte Ltd  
Date Inspected: 24/09/2020 Inspected At: 15 Fan Yong Road  
Estimated Period of Repair: 5.0 days Singapore 629792

**Adjuster:** MOHD RASUL

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 03 Feb 2021)
<b>Parts:</b>	M1-SUV	mitsubishi OUTLANDER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJU1819U)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	<b>*BADGE "MITSUBISHI"</b> (WCP)	Not Necessary	0.00 F	*- F
2	1	NA	<b>*BADGE MODEL</b> (WCP)	Necessary	50.00 F	*50.00 F
3	1	NA	<b>*BADGE SPORT</b> (WCP)	Not Necessary	0.00 F	*- F
4	1	NA	<b>*BOOT/TAILGATE TRIM</b> (WCP)	Deformed	200.00 F	*200.00 F
5	1	NA	<b>*BOOTLID/TAILGATE</b> (WCP)	Bent	750.00 F	*750.00 F
6	1	NA	<b>*L/LWR BUMPER BRACKET</b> (WCP)	Bent	60.00 F	*60.00 F
7	1	NA	<b>*L/R BUMPER BRACKET</b> (WCP)	Bent	15.00 F	*15.00 F
8	1	NA	<b>*L/R LAMP</b> (WCP)	Cracked	240.00 F	*240.00 F
9	1	NA	<b>*LOWER TAILGATE LOCK</b> (WCP)	Bent	280.00 F	*280.00 F
10	1	NA	<b>*LOWER TAILGATE SEAL</b> (WCP)	Necessary	90.00 F	*90.00 F
11	1	NA	<b>*R/LWR BUMPER BRACKET</b> (WCP)	Bent	60.00 F	*60.00 F
12	1	NA	<b>*R/R BUMPER BRACKET</b> (WCP)	Necessary	15.00 F	*15.00 F
13	1	NA	<b>*R/R LAMP</b> (WCP)	Cracked	240.00 F	*240.00 F
14	1	NA	<b>*R/R OUTER LAMP</b> (WCP)	Not Necessary	380.00 F	*- F
15	1	NA	<b>*REAR BUMPER</b> (WCP)	Deformed	650.00 F	*650.00 F
16	1	NA	<b>*REAR MANUFACT BADGE</b> (WCP)	Not Necessary	0.00 F	*- F
17	1	NA	<b>*REAR SCREEN</b> (WCP)	Broken	600.00 F	*600.00 F
18	1	NA	<b>*REAR SCREEN BOND KIT</b> (WCP)	Not Necessary	0.00 F	*- F
19	1	NA	<b>*REAR SCREEN CLAMPS</b> (WCP)	Not Necessary	0.00 F	*- F
20	1	NA	<b>*REAR SCREEN FIX SET</b> (WCP)	Not Necessary	0.00 F	*- F
21	1	NA	<b>*REAR SPACER</b> (WCP)	Not Necessary	0.00 F	*- F
22	1	NA	<b>*REAR WIPER BLADE</b> (WCP)	Necessary	30.00 F	*30.00 F
23	1	NA	<b>*RR CTR BUMPER PANEL</b> (WCP)	Scratched	230.00 F	*230.00 F
24	1	NA	<b>*TAILGATE</b> (WCP)	Scratched	350.00 F	*350.00 F
25	1	NA	<b>*TAILGATE SEAL</b> (WCP)	Necessary	170.00 F	*170.00 F
26	1	NA	<b>*SUNDRY PARTS</b>	Not Necessary	97.02 FS	*- FS
27	1	NA	<b>*CAMERA REAR</b>	Serviceable	450.00 FS	*- FS
28	1	NA	<b>*FEE AUDATEX</b>		40.00 FS	*40.00 FS
29	1	NA	<b>*FEE MERIMEN</b>		11.00 FS	*11.00 FS

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
30	1	NA	*GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
31	1	NA	*PARKING SENSOR	Serviceable	200.00 FS	*- FS
32	1	NA	*REAR GLASS SOLAR FILM	Necessary	300.00 FS	*200.00 FS
33	1	NA	*REAR NO PLATE	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett.

<b>Sub Total (\$)</b>	<b>5,598.02</b>	<b>4,321.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$)</b>	441.00	403.00
<b>Total Parts (\$)</b>	<b>6,039.02</b>	<b>4,724.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	Total Paint Labour	New	297.00	297.00
2	Total Paint Materials	New	159.62	159.62
<b><u>Labour Items</u></b>				
3	Total Panel/Mechanical Labour	New	576.00	576.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,032.62</b>	<b>1,032.62</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >