

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 02 Oct 2020

**Preliminary Advice**

Insured Vehicle No : YN2200G  
TP Vehicle No : YN7947C  
Make : MITSUBISHI FUSO  
Date of Inspection : 24/09/2020  
Inspection At : LIU'S BROTHER AUTO ENGINEERING WORKSHOP (KAKI BUKIT) (HQ)  
BLK 1 KAKI BT AVE 6 #01-01 AUTO BAY @ KAKI BT SINGAPORE 417883, KAKI BUKIT  
SINGAPORE 417883  
Accident Date : 18/09/2020  
Assignment Date : 24/09/2020  
Est. Duration of Repair : 4

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,534.50
Revised Amount	:S\$	6,274.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,274.00

Lump Sum Repair	:S\$
-----------------	------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : The above survey was conduct without "prejudice" basis.