

Hsiao Tong (LKKAuto)

From: Oi Sun Pin (LKK Auto)
Sent: Monday, 19 October 2020 11:30 AM
To: Hsiao Tong (LKKAuto)
Subject: RE: SHC 4845S
Attachments: google map.png

Hi Hsiao Thong,

My opinion: based on the OI report can see **OI vehicle** left side collided with **TP taxi** rear right bumper when overtake the **TP taxi**.

TP taxi is waiting at the junction (please refer attachment: around white colour car place), **OI vehicle** is overtake then collided.

Thank you

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)
Sent: Monday, October 19, 2020 11:01 AM
To: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Subject: FW: SHC 4845S

Hi Sun Pin,

May I get your opinion, likely which part of OI vehicle collided onto third party taxi? OI report is abit different with TP GIA. Attached is a copy of OI GIA report for your ref.

Thanks.

Best Regards,

Hsiao Tong, Chew (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | Email: chewht@lkkauto.com | Fax: 6741 4108

HQ : Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |

S(408933)

From: Oi Sun Pin (LKK Auto) <sunpin@lkkauto.com>
Sent: Friday, 16 October 2020 5:54 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: SHC 4845S

Hi Hsiao Tong,

Already confirm with workshop.

Finalize amount \$850. Repair day 3 days. (L/S, before gst).

Please refer attachment.

Thank you

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)