

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010239/T1ES3Q2
Date: 07/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900155836
Claimant Vehicle No :	SHA3884X	Insured Vehicle No :	SFT796K
Date of Loss:	23/09/2020	Nature of Claim:	TP
		Claim No:	2563354629SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA3884X		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	HIDDEN
Reg. Date:	18/06/2015 (Man. Year: 2015)	Chassis No:	KMHLB41UMFU069545
Colour:	Blue	Odometer:	573024 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,767.68	2,199.68	568.00	20.52
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	940.00	290.00	23.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,997.68	3,139.68	858.00	21.46
Approved Total (Overridden) (S\$)		2,500.00		

(S\$)	3,997.68	2,500.00	1,497.68	37.46
+ GST 7.00/7.00% (S\$)	279.84	175.00	104.84	37.46
Nett Amount (S\$)	4,277.52	2,675.00	1,602.52	37.46
+ Loss of Use (2.5 x S\$50.00/day) (S\$)		125.00		
+ Car Rental (2.5 x S\$123.93/day) (S\$)		309.83		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,111.83		
Global Sum Settlement (S\$)		3,110.00		

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER W LIP & FOG	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*BRKT ASSY -FR BPR UP	Not Necessary	22.40 FL	*- FL
3	1		*BRACKET -FR BUMPER S	Not Necessary	24.60 FL	*- FL
4	10		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
5	1		*PANEL -FENDER LH	Repair	663.00 FL	*- FL
6	1		*GUARD ASSY -FRONT W/H	Deformed	174.90 FL	*174.90 FL
7	1		*LAMP ASSY -HEAD LH	Cut	1,388.00 FL	*1,388.00 FL
8	1		*CAP ASSY -WHEEL HUB	Cut	112.50 FL	*112.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	3,459.60	2,749.60
- List Item Discount on L Items 20.00/20.00% (\$)	691.92	549.92
Total Parts (\$)	2,767.68	2,199.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	420.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
3	CHECK ALL LIGHTING	New	50.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	50.00	30.00
5	ADJUST FRONT WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (S\$)			1,230.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >