

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20010240/KSD3Q2

**Date:** 25/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCNSA00000772001	
Claimant Vehicle No : SDV1095G	Insured Vehicle No : SJM4941X	
Date of Loss: 20/09/2020	Nature of Claim: TP	Claim No: SNM20D203445/C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV1095G		
Make & Model:	TOYOTA HARRIER, 2.0 Elegance (A)	Engine No:	3ZRB604852
Reg. Date:	08/10/2015 (Man. Year: 2015)	Chassis No:	ZSU600051619
Colour:	Metallic Black	Odometer:	153747 km
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/65R17	Rear Tyre Size:	225/65R17
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,016.00	1,601.50	414.50	20.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,100.00	470.00	630.00	57.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>3,116.00</b>	<b>2,071.50</b>	<b>1,044.50</b>	<b>33.52</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>3,116.00</b>	<b>1,650.00</b>	<b>1,466.00</b>	<b>47.05</b>

### INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 28/09/2020 Inspected At:

Tat Heng Motor Works (HQ)  
Blk 10 Ang Mo Kio Ind Park 2A, #02-09  
AMK Autopoint  
Singapore 568047

Estimated Period of Repair: 2.0 days

**Adjuster:** KENNETH KONG

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 24 Nov 2020)
<b>Parts:</b>	M1-SUV	TOYOTA HARRIER 2.0 Elegance (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SDV1095G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Mtg Cracked	1,386.00 FL	*1,386.00 FL
2	1		*REAR BUMPER INNER SPONGE	Cracked	118.00 FL	*118.00 FL
3	2		*REAR BUMPER SIDE BRACKET	Serviceable	118.00 FL	*- FL
4	2		*REAR BUMPER BRACKET	Repair	102.00 FL	*- FL
5	2		*REAR BUMPER REFLECTOR	Serviceable	78.00 FL	*- FL
6	1		*REAR BUMPER LOWER COVER	Dented/Distorted	318.00 FL	*318.00 FL
7	1		*SET REAR BUMPER CLIP	Necessary	35.00 FS	*35.00 FS
8	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	35.00 FS	*- FS
9	1		*SET REVERSE SENSOR	Dented	250.00 FS	*200.00 FS
					<b>Sub Total (S\$)</b>	<b>2,440.00</b>
					<b>- List Item Discount on L Items 20.00/25.00% (S\$)</b>	<b>424.00</b>
					<b>Total Parts (S\$)</b>	<b>2,016.00</b>
						<b>1,601.50</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO CHECK WIRING FOR PROPER FUNCTION INCLUDING REMOVE AND REFIX REVERSE SENSOR	New	150.00	50.00
2	TO REPLACE,REPAIR,STRAIGHTEN & RE-ALIGN ALL DAMAGED PARTS	New	450.00	200.00
3	TO SPRAY PAINT ON ALL AFFECTED AREAS	New	500.00	220.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,100.00</b>	<b>470.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >