

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010245/R1QD3E2

Date: 16/10/2020

REFERENCE

Insured/Claimant:	LIM CHIEW ENG	Policy No:	1800042986	
Date of Loss:	24/09/2020	Nature of Claim:	OD	Claim No: 4149391076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMT8966B			
Make & Model:	KIA SORENTO, 2.2 (A)	Engine No:	D4HBJH364677	
Reg. Date:	07/05/2018 (Man. Year: 2018)	Chassis No:	KNAPH81BMJ5448538	
Colour:	Black	Odometer:	42406 km	
Engine Capacity:	2199 cc			
Market Value/New Car Price:	S\$116,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/60 R18	Rear Tyre Size:	235/60 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,380.80	8,684.80	3,696.00	29.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,980.00	3,850.00	2,130.00	35.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,360.80	12,534.80	5,826.00	31.73
+ GST 7.00/7.00% (S\$)	1,285.26	877.44	407.82	31.73
Nett Amount (S\$)	19,646.06	13,412.24	6,233.82	31.73

INSPECTION

Date of Assignment:	24/09/2020	
Date Inspected:	24/09/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339
Estimated Period of Repair:	8.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS
2	1		*PANEL ASSY-TAIL GATE	Bent	1,445.00 FL	*1,445.00 FL
3	1		*PANEL ASSY -BACK	Serviceable	526.00 FL	*- FL
4	1		*GLASS ASSY -TAILGATE GATE	Serviceable	690.00 FL	*- FL
5	1		*EMBLEM -SORENTO	Necessary	28.00 FL	*28.00 FL
6	1		*EMBLEM -ECO DYNAMICS	Necessary	37.00 FL	*37.00 FL
7	1		*COVER -RR BUMPER ,UPR	Cracked	605.00 FL	*605.00 FL
8	1		*COVER -RR BUMPER LWR	Cracked	565.00 FL	*565.00 FL
9	1		*SKID PLATE -RR BUMPER	Cracked	103.00 FL	*103.00 FL
10	1		*COVER ASSY -RR BPR UNDER	Serviceable	30.00 FL	*- FL
11	1		*COVER -BLANKING RR FOG ,LH	Deformed	11.00 FL	*11.00 FL
12	1		*LAMP ASSY-REAR FOG & R/REFL LH	Scratched	129.00 FL	*129.00 FL
13	1		*BRACKET -RR BPR SIDE REINF ,LH	Serviceable	5.00 FL	*- FL
14	1		*BRACKET -RR BPR SIDE REINF ,RH	Serviceable	5.00 FL	*- FL
15	1		*RETAINER -BUMPER MTG	Not Necessary	2.00 FL	*- FL
16	1		*WIRING HARNESS -R.P.A.S	Serviceable	240.00 FL	*- FL
17	1		*RAIL ASSY -REAR BUMPER	Serviceable	341.00 FL	*- FL
18	1		*ANTENNA ASSY -SMARTKEY	Serviceable	53.00 FL	*- FL
19	1		*BRACKET ASSY -RR BUMPER SIDE ,LH	Serviceable	25.00 FL	*- FL
20	1		*BRACKET ASSY -RR BUMPER SIDE ,RH	Serviceable	25.00 FL	*- FL
21	1		*ULTRASONIC SENSOR ASSY -BWS	Not Working	187.00 FL	*187.00 FL
22	1		*ULTRASONIC SENSOR ASSY -BWS	Serviceable	187.00 FL	*- FL
23	1		*MUFFLER ASSY -REAR	Serviceable	1,177.00 FL	*- FL
24	1		*GASKET -EXHAUST PIPE	Not Necessary	13.00 FL	*- FL
25	1		*W/STRIP -TAIL GATE OPNG	Serviceable	128.00 FL	*- FL
26	1		*PANEL ASSY -HOOD	Bent	1,654.00 FL	*1,654.00 FL
27	1		*BEAM COMPLETE -FR BUMPER	Bent	551.00 FL	*551.00 FL
28	1		*CARRIER ASSY -FRONT END MODULE	Serviceable	760.00 FL	*- FL
29	1		*COVER -FR BUMPER UPR	Cracked	561.00 FL	*561.00 FL
30	1		*GRILLE ASSY -RADIATOR	Cracked	673.00 FL	*673.00 FL
31	1		*MOULDING -FRT BPR LICENSE PLATE	Deformed	20.00 FL	*20.00 FL
32	1		*LIP FRONT BUMPER	Serviceable	56.00 FL	*- FL
33	1		*SKID PLATE-FR BUMPER	Serviceable	111.00 FL	*- FL
34	1		*COVER ASSY-RADIATOR GRILLE UPR	Cracked	186.00 FL	*186.00 FL
35	1		*GRILLE-FRONT BUMPER	Cracked	191.00 FL	*191.00 FL
36	1		*ABSORBER-FRONT BUMPER ENERGY	Cracked	117.00 FL	*117.00 FL
37	1		*BRACKET-FR BUMPER SIDE, LH	Serviceable	17.00 FL	*- FL
38	1		*BRACKET-FR BUMPER SIDE, RH	Serviceable	17.00 FL	*- FL
39	1		*ULTRASONIC SENSOR ASSY-BWS	Serviceable	187.00 FL	-
40	1		*FRT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
41	1		*STRIP ASSY FR - HOOD	Necessary	27.00 FL	*27.00 FL
42	1		*CONDENSER ASSY - COOLER	Bent	784.00 FL	*784.00 FL
43	1		*HEADLAMP LH	Cracked	2,743.00 FL	*2,743.00 FL
44	1		*BUMPER CLIP	Necessary	20.00 FL	*20.00 FL
45	1		*KIA LOGO	Necessary	69.00 FL	*69.00 FL
46	1		*C&C EMBLEM	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **15,441.00** **10,826.00**
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,060.20 2,141.20

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					Total Parts (S\$)	12,380.80
						8,684.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE REAR BUMPER, TAILGATE & AFFECTED AREA REPAIR ON END PANEL	New	1,600.00	800.00
2	PAING WORK ON REAR BUMPER, TALGATE & END PANEL	New	1,050.00	700.00
3	TO REPLACE FRT BUMPER, BONNET, SUPPORT & AFFECTED AREA	New	1,200.00	800.00
4	PAING WORK ON FRT BUMPER & BONNET	New	700.00	700.00
5	TO REMOVE & INSTALL REAR BOOT COMPARTMENT FOR FACILITATE REPAIR	New	120.00	120.00
6	TO REMOVE & INSTALL REAR WINDSCREEN FOR FACILITATE REPAIR	New	240.00	240.00
7	TO APPLY SEALANT ON WINDSCREEN	New	80.00	80.00
8	TO TRANSFER REAR TAILGATE ATTACHMENT TO NEW PANEL	New	120.00	60.00
9	REPLACE REAR EXHAUST MUFFLER	New	400.00	0.00
10	TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR	New	120.00	80.00
11	TO TOP UP AIRCON GAS	New	80.00	80.00
12	TO APPLY SEALANT ON AFFECTED AREA	New	40.00	0.00
13	PERFORM RUST PREVENTION	New	80.00	40.00
14	CHECK WIRING & CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
15	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (S\$)			5,980.00	3,850.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >