

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010246/R1QD3Q2**Date:** 11/11/2020**REFERENCE**

Insured/Claimant: TOH MENG TIAK Policy No: 1800110326
Date of Loss: 23/09/2020 Nature of Claim: OD Claim No: 9251091310SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMD9942Y**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGJH707254
Reg. Date: 14/09/2018 (Man. Year: 2018) Chassis No: KNAF3416MK5015071
Colour: Black Odometer: 22186 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$72,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16
Front Left Side: Nexen 6 mm Rear Left Side: Nexen 6 mm
Front Right Side: Nexen 6 mm Rear Right Side: Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,043.20	4,345.60	2,697.60	38.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,050.00	6,020.00	2,030.00	25.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,093.20	10,365.60	4,727.60	31.32
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	14,793.20	10,065.60	4,727.60	31.96
+ GST 7.00/7.00% (S\$)	1,035.52	704.59	330.93	31.96
Nett Amount (S\$)	15,828.72	10,770.19	5,058.53	31.96

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 13.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER-FR BUMPER	Deformed	633.00 FL	*633.00 FL
2	1		*GRILLE-FRONT BUMPER	Cracked	262.00 FL	*262.00 FL
3	1		*COVER-FR BUMPER FOG LAMP,RH	Serviceable	15.00 FL	*- FL
4	1		*COVER-FR BUMPER FOG LAMP,LH	Serviceable	15.00 FL	*- FL
5	1		*GRILLE ASSY-RADIATOR	Cracked	328.00 FL	*328.00 FL
6	1		*MOULDING-FRONT BUMPER,RH	Serviceable	36.00 FL	*- FL
7	1		*MOULDING-FRONT BUMPER,LH	Serviceable	36.00 FL	*- FL
8	1		*ABSORBER-FRONT BUMPER ENERGY	Cracked	84.00 FL	*84.00 FL
9	1		*COVER-RR BUMPER	Deformed	651.00 FL	*651.00 FL
10	1		*COVER-RR BUMPER LWR (5 Pcs)	Cracked (1pc only)	1,205.00 FL	*241.00 FL
11	1		*COVER-RR BUMPER UNDER,LH	Cracked	33.00 FL	*33.00 FL
12	1		*COVER-RR BUMPER FOG LAMP,RH	Cracked	19.00 FL	*19.00 FL
13	1		*COVER-RR BUMPER FOG LAMP,LH	Serviceable	19.00 FL	*- FL
14	1		*LAMP ASSY-SIDE T/SIGNAL,RH	Cracked	181.00 FL	*181.00 FL
15	1		*LAMP ASSY-SIDE T/SIGNAL,LH	Serviceable	181.00 FL	*- FL
16	1		*EXTN WIRING ASSY-BWS	Serviceable	207.00 FL	*- FL
17	1		*BRACKET-RR BEAM UPR MTG,RH	Serviceable	9.00 FL	*- FL
18	1		*BRACKET-RR BEAM UPR MTG,LH	Serviceable	9.00 FL	*- FL
19	1		*BRACKET-RR BEAM LWR,CTR	Serviceable	6.00 FL	*- FL
20	2		*BRACKET-RR BEAM LWR,MTG	Serviceable	12.00 FL	*- FL
21	1		*BEAM-RR BUMPER	Cracked	318.00 FL	*318.00 FL
22	1		*ANTENNA ASSY-SMARTKEY	Serviceable	46.00 FL	*- FL
23	1		*STAY-RR BUMPER RH	Bent	65.00 FL	*65.00 FL
24	1		*STAY-RR BUMPER LH	Bent	65.00 FL	*65.00 FL
25	1		*BRACKET-ASSY RR BPR SIDE UPR,R	Serviceable	31.00 FL	*- FL
26	1		*BRACKET-ASSY RR BPR SIDE UPR,L	Serviceable	25.00 FL	*- FL
27	1		*PANEL ASSY-TRUNK LID	Repair	1,297.00 FL	*- FL
28	1		*PANEL ASSY-BACK	Bent	324.00 FL	*324.00 FL
29	1		*LOGO ASSY-KIA SUB	Necessary	32.00 FL	*32.00 FL
30	1		*EMBLEM-CERATO	Necessary	28.00 FL	*28.00 FL
31	1		*W/STRIP-TRUNK LID OPNG	Serviceable	100.00 FL	*- FL
32	1		*LATCH ASSY-TRUNK LID	Serviceable	112.00 FL	*- FL
33	1		*PANEL ASSY-REAR FLOOR,RR	Bent	219.00 FL	*219.00 FL
34	1		*TRIM ASSY-RR TRANSVERSE	Serviceable	41.00 FL	*- FL
35	1		*MAT ASSY-LUGGAGE COVERING	Serviceable	211.00 FL	*- FL
36	1		*PROTECTOR-HEAT REAR	Bent	136.00 FL	*136.00 FL
37	1		*MUFFLER ASSY-REAR	Bent	757.00 FL	*757.00 FL
38	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
39	1		*REINF-RR SPARE TIRE WELL CROSS	Dented	41.00 FL	*41.00 FL
40	1		*HOOK-TOWING	Necessary	16.00 FL	*16.00 FL
41	1		*REINF-TOWING HOOK	Dented	14.00 FL	*14.00 FL
42	1		*BRACKET ASSY-SPACE TIRE MTG	Necessary	15.00 FL	*15.00 FL
43	1		*SILENCER, FLOOR	Necessary	13.00 FL	*13.00 FL
44	1		*MUFFLER COMPLETE-CENTER	Bent	907.00 FL	*907.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,794.00	5,422.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,750.80	1,076.40
Total Parts (\$\$)	7,043.20	4,345.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	*OD/TP Case (Insurer)	-	0.00
Sub Total (\$\$)			0.00	0.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT BUMPER	New	400.00	400.00
2	SPRAY PAINT FOR FRT BUMPER	New	350.00	350.00
3	FRT NUMBER PLATE WITH FRAME	New	50.00	50.00
4	RENEW REAR BUMPER,REAR END PANEL,REAR COMPARTMENT BOOTLID	New	4,000.00	2,400.00
5	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
6	REMOVE & INSTALL REAR COMPARTMENT TRIMS AND SEATS	New	200.00	160.00
7	SPRAY PAINT FOR REAR BUMPER,REAR END PANEL,REAR COMPARTMENT BOOTLID	New	1,750.00	1,400.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	80.00
11	RENEW EXHAUST SYSTEM	New	200.00	200.00
12	SUPPLY PARKING SENSOR	New	220.00	220.00
13	REMOVE & INSTALL FUEL TANK TO FACILITATE REPAIR.	New	200.00	200.00
14	RESPRAY ON RH REAR FENDER.	New	350.00	350.00
Gross Labour Cost (\$\$)			8,050.00	6,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >