

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010247/KRA3Q2
Date: 28/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800024244
Claimant Vehicle No :	SLA728L	Insured Vehicle No :	SLX1792Y
Date of Loss:	19/09/2020	Nature of Claim:	TP
		Claim No:	4339428934SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLA728L	Engine No:	27492030509996
Make & Model:	MERCEDES-BENZ C200 AMG LINE, 2.0 (A)	Chassis No:	WDD2050422R132892
Reg. Date:	15/03/2016 (Man. Year: 2016)	Odometer:	49335 km
Colour:	Metallic Grey		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 8 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,345.90	4,194.00	7,151.90	63.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,380.00	570.00	810.00	58.70
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	12,725.90	4,764.00	7,961.90	62.56
Approved Total (Overridden) (\$\$)		3,800.00		
(\$\$)	12,725.90	3,800.00	8,925.90	70.14
+ GST 7.00/7.00% (\$\$)	890.81	266.00	624.81	70.14
Nett Amount (\$\$)	13,616.71	4,066.00	9,550.71	70.14
+ Car Rental (3.0 x S\$130.00/day) (\$\$)		390.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		4,458.00		
Global Sum Settlement (\$\$)		4,450.00		

INSPECTION

Date of Assignment:	24/09/2020		
Date Inspected:	21/12/2020	Inspected At:	MBM Wheelpower Pte Ltd (HQ) 160 Sin Ming Drive #06-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	2.0 days		

Adjuster: KENNETH KONG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,850.00 FL	*1,510.00 FL
2	1		*FRONT BUMPER LOWER GRILLE	Serviceable	165.00 FL	*- FL
3	1		*BUMPER LOWER CHROME TRIM CENTRE	Serviceable	320.00 FL	*- FL
4	1		*BUMPER LOWER CHROME TRIM LH	Serviceable	185.00 FL	*- FL
5	1		*BUMPER LOWER CHROME TRIM RH	Serviceable	185.00 FL	*- FL
6	1		*BUMPER LOWER MOULDING CONSOLE	Serviceable	265.00 FL	*- FL
7	1		*BUMPER SIDE RETAINER LH	Serviceable	95.00 FL	*- FL
8	1		*BUMPER SIDE RETAINER RH	Serviceable	95.00 FL	*- FL
9	1		*RADIATOR GRILLE CHROME	Serviceable	426.00 FL	*- FL
10	1		*RADIATOR GRILLE BASE	Serviceable	235.00 FL	*- FL
11	1		*GRILLE EMBLEM	Serviceable	105.00 FL	*- FL
12	1		*HEADLAMP LH	Mtg Cracked	3,650.00 FL	*3,150.00 FL
13	1		*HEADLAMP RH	Serviceable	3,650.00 FL	*- FL
14	2		*FRONT DISTANT SENSORS	Serviceable	500.00 FL	*- FL
15	1		*FRONT REINFORCEMENT	Repair	480.00 FL	*- FL
16	1		*FRONT NUMBER PLATE BASE	Serviceable	155.00 FL	*- FL
17	1		*FRONT BUMPER SPONGE	Serviceable	190.00 FL	*- FL
18	1		*NUMBER PLATE W/HOLDER	Serviceable	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,601.00	4,660.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,255.10	466.00
Total Parts (\$\$)	11,345.90	4,194.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS	New	600.00	220.00
2	TO RESET ENGINE WARNING LIGHT (ABS,SRS,ECU MEMORY & ETC)	New	120.00	100.00
3	TO REMOVE & REPLACE BUMPER SENSORS	New	60.00	0.00
4	TO SPRAY PAINT ON THE AFFECTED AREAS	New	600.00	250.00
Gross Labour Cost (\$\$)			1,380.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >