

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010248/R1QD3E2

Date: 29/10/2020

REFERENCE

Insured/Claimant:	SHAWN ANG AH SENG	Policy No:	1900108982
Date of Loss:	19/09/2020	Nature of Claim:	OD
		Claim No:	3327728610SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM3996J	Engine No:	4J11BD7303
Make & Model:	mitsubishi OUTLANDER, 2.0 (A)	Chassis No:	GF7W0601698
Reg. Date:	27/06/2019 (Man. Year: 2019)	Odometer:	17356 km
Colour:	Grey		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	S\$98,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Toyo 6 mm	Rear Left Side:	Toyo 6 mm
Front Right Side:	Toyo 6 mm	Rear Right Side:	Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,409.49	3,883.04	4,526.45	53.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	1,810.00	2,660.00	59.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,879.49	5,693.04	7,186.45	55.80
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	12,579.49	5,393.04	7,186.45	57.13
+ GST 7.00/7.00% (S\$)	880.56	377.51	503.05	57.13
Nett Amount (S\$)	13,460.05	5,770.55	7,689.50	57.13

INSPECTION

Date of Assignment:	24/09/2020	
Date Inspected:	25/09/2020 Inspected At:	Cycle & Carriage KIA Pte Ltd (Pandan Gardens) 209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PNL, HEADLAMP SUPT, UPR RH	Serviceable	58.00 FL	*- FL
4	1		*PANEL, HEADLAMP SUPPORT, UPR	Serviceable	182.00 FL	*- FL
5	1		*PNL, HEADLAMP SUPT, UPR LH	Serviceable	58.00 FL	*- FL
6	1		*PANEL, HEADLAMP SUPPORT, LWR	Serviceable	107.00 FL	*- FL
7	1		*CONDENSER ASSY, A/C REFRIGE	Serviceable	857.00 FL	*- FL
8	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
9	1		*HEADLAMP ASSY, RH	Cracked	1,938.00 FL	*1,938.00 FL
10	1		*HEADLAMP ASSY, LH	Serviceable	1,938.00 FL	*- FL
11	1		*COVER, FR BUMPER	Serviceable	25.00 FL	*- FL
12	1		*GRILLE ASSY, RADIATOR	Scratched	548.00 FL	*548.00 FL
13	1		*BRACKET, FR BUMPER SIDE, LH	Serviceable	18.00 FL	*- FL
14	1		*BRACKET, FR BUMPER SIDE, RH	Serviceable	18.00 FL	*- FL
15	1		*FACE, FR BUMPER	Cracked	859.00 FL	*859.00 FL
16	1		*COVER, FR BUMPER	Deformed	359.00 FL	*359.00 FL
17	1		*GARNISH, FR BUMPER SIDE	Serviceable	48.00 FL	*- FL
18	1		*GARNISH, FR BUMPER SIDE	Serviceable	48.00 FL	*- FL
19	1		*GARNISH, FR BUMPER SIDE	Serviceable	220.00 FL	*- FL
20	1		*GARNISH, FR BUMPER SIDE	Serviceable	220.00 FL	*- FL
21	1		*GARNISH, FR BUMPER SIDE	Serviceable	112.00 FL	*- FL
22	1		*GARNISH, FR BUMPER SIDE	Serviceable	112.00 FL	*- FL
23	1		*GARNISH, FR BUMPER, LH	Serviceable	48.00 FL	*- FL
24	1		*GARNISH, FR BUMPER, RH	Serviceable	48.00 FL	*- FL
25	1		*EXTENSION, FR BUMPER	Scratched	515.00 FL	*515.00 FL
26	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
27	1		*REINFORCEMENT, FR BUMPER	Bent	490.00 FL	*490.00 FL
28	1		*REINF, FR BUMPER SIDE, RH	Bent	69.00 FL	*69.00 FL
29	1		*REINFORCEMENT, FR Bmpr SIDE	Serviceable	22.00 FL	*- FL
30	1		*REINF, FR BUMPER SIDE, LH	Serviceable	60.00 FL	*- FL
31	1		*BODY KIT, OUTLANDER	Serviceable	1,554.00 FN	*- FN
32	1		*REINFORCEMENT, FR BUMPER	Bent	134.00 FL	*134.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$)	10,831.00	5,022.00
- List Item Discount on L Items 23.00/23.00% (\$)	2,110.71	1,138.96
- Nett Item Discount on N Items 20.00/20.00% (\$)	310.80	0.00
Total Parts (\$)	8,409.49	3,883.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER FACE, REPAIR FRONT BONNET, REPAIR RH FRONT FENDER	New	2,250.00	900.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK	New	100.00	0.00
3	TOP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	0.00
4	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, RH FRONT FENDER AND AFFECTED PORTION	New	1,750.00	700.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY BODY KITS SEALANT	New	60.00	60.00
8	PERFORM RUST PREVENTION	New	80.00	0.00
Gross Labour Cost (S\$)			4,470.00	1,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >