



ALG - OD CLAIM
SURVEY: 25/09/20
LKK - Rasul

VEHICLE NO : SMM 3996 J

MODEL : MIT/OUTLANDER 2.0

WIP : 57731

Material	:	\$	<u>3,813.04</u>
Labour	:	\$	<u>1,880.00</u>
Sub-Total	:	\$	<u>5,693.04</u>
Less 2% Disc	:	\$	<u>—</u>
Less Excess	:	\$	<u>300.00</u>
Total	:	\$	<u>5,393.04</u>
GST 7%	:	\$	<u>377.51</u>
Grand Total	:	\$	<u>5,770.55</u>
Finalise By/Date	:	<u>Army on 09/10/20</u>	

REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 05 WORKING DAYS + 2 days (wk-end)



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11583/SHAWN ANG AH SENG Reg No/Reg Date SMM3996J / 27/06/2019 Date In/Mileage 03/10/2020/ 17650 Chassis/Package GF7W0601698 /DC17P Engine No 4J11BD7303 Make/Model MIT/19MY OUTLANDER 2.0 STYLE(994) Colour/Trim U01 TITANIUM GREY M/ BK BLACK
02/10/2020	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	09/10/2020/ 10:06	BLD	884 / Lauro Songcuan	57731

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW DAMAGED PARTS ON COVER, FRONT BUMPER, REPAIR FRONT BUMPER FACE, REPAIR FRONT BONNET				900.00 ✓
E PNT98000 SPRAY PAINT FRONT BONNET, FRONT BUMPER AND AFFECTED PORTIONS				700.00 ✓
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00 ✓
M SUNDRY APPLY BODY KITS SEALANT				60.00 ✓
M SUNDRY SUNDRIES				20.00 ✓
S SPECIALISTJOB SUPPLY FRONT LICENSE PLATE WITH FRAME (RECTANGULAR & BLACK)				50.00 ✓
X EXC INSURANCE EXCESS				-300.00
X HEADLAMP ASSY,RH ?	1.00	1938.00	23.00	1492.26 ?
X GRILLE ASSY,RADIATOR ✓	1.00	548.00	23.00	421.96
X FACE,FR BUMPER X	1.00	859.00	23.00	661.43 ?
X COVER,FR BUMPER ✓	1.00	359.00	23.00	276.43 ✓
X EXTENSION,FR BUMPER ✓	1.00	515.00	23.00	396.55 ✓
X CLIP,FR BUMPER ✓	10.00	4.00	23.00	30.80 ✓
X REINFORCEMENT,FR BUMPER ?	1.00	490.00	23.00	377.30 ?
X REINF,FR BUMPER SIDE,RH ?	1.00	69.00	23.00	53.13 ?
X REINFORCEMENT,FR BUMPER → <i>supp</i>	1.00	134.00	23.00	103.18 X
Z TEXT OD CLAIM - AIG DOA: 19.09.2020 SURVEY: RASUL (LKK) 25.09.2020 05 DAYS				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	3,813.04		Nett	5,393.04
Labour	1,750.00			377.51
Standard Menu	0.00	7% GST on	5393.04	
Specialist Job	50.00		Total Payable	5,770.55
Diagnostics Job	0.00			
Sundry/Others	-220.00			
Total(w/o GST)	5,393.04			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMM 3996 J**

<u>Materials</u>		<u>Cost \$</u>
1	Reinforcement, FR Bumper	134.00
	23% Discount	30.82
		<u>103.18</u>
	7% GST	7.22
	Total	<u>110.40</u>

Thank You.

Yours faithfully
CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

Larry Songcuan
Customer Service
Cycle & Carriage
Pandan Gardens

CAR NO: SMN 3996J

WIP: 57731

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	REINFORCEMENT FR BUMPER SIDE RH	? / SUPP		ht ✓	6400D582
2	REINFORCEMENT FR BUMPER	? / SUPP		ht ✓	6400G574
3	REINFORCEMENT FR BUMPER	? / SUPP		ht ✓	6400J626
4	HEADLAMP ASSY RH	? / SUPP		can ✓	8301D330
5	FRONT FR BUMPER	? / SUPP		de ✓	6400K786
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	5/10	
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: OUTLANDER 2.0

SURVEYOR: RASUL @ LKX

SMM3996J

Before using MUT-3 VCI unit to check all TSS panel.

All DTCs

2020.10.07

Item	Setting Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	DBA-GF7W 2019MY

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS	
AT/CVT/A-MT/T/C-SST	CVT_14080300		No DTCS	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCS	
ABS/ASC/ASTC/MSS	ASC_4208000F		No DTCS	
SRS-AIR BAG	ORC_81047302		No DTCS	
Air Conditioner	AC_80080011	U0184	AUDIO CAN timeout	Active
ETACS	ETACS_83040801	B16A4 U0184	Turn signal(RH) bulb outage AUDIO CAN timeout	Active Active
Meter	MTR_84084001	U0184	AUDIO CAN timeout	Active
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active
KOS/IMMO/keyless	KOS_8A880020	U0184	AUDIO CAN timeout	Active
OSS	OSS_9588000B	U0184	AUDIO CAN timeout	Active
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSFCM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCS	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	

All DTCS

Item	Setting	Information
M.U.T.-3 Version		SEW20011-00
V.C.I. Version		B177
Vehicle Information		DBA-GF7W 2019MY

SM11139965

After using PAS-3x VCI unit to erase all gas send
BT to Done by Z/H

2020.10.07

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	GAS_0E640000		No DTCS	
Auto Stop & Go (AS&G)	ASG_25080000		No DTCS	
AT/CVT/A-MT/T/C-SST	CVT_14080300		No DTCS	
AUTO CRUISE	GAS_0E640000		Non-target System	
4WS/Electric Power Steering	EPS_45880040		No DTCS	
ABS/ASC/ASTC/WSS	ASC_4208000F		No DTCS	
SRS-AIR BAG	ORC_81047302		No DTCS	
Air Conditioner	AC_80080011		No DTCS	
ETACS	ETACS_83040801		No DTCS	
Meter	MTR_84084001		No DTCS	
Steering Angle Sensor	GS_SAS_47000100		Non-target System	
AND	AND_8C080002		Non-equipped System or Communication Error	
AUDIO (Display Audio)	AUDIO_8D080002		Non-equipped System or Communication Error	
LIN	ETACS_83040801		Non-target System	
Power Gate	ETG_92080000	U0184	AUDIO CAN timeout	Active

All DTCs

2020.10.07

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
KOS/IMMO/Keyless	KOS_8A880020		No DTCs	
OSS	OSS_9588000B		No DTCs	
CORNER SENSOR/SONAR	SONAR_9D080000		Non-equipped System or Communication Error	
ACC/FCM	ACCSCFM_4B080000		Non-equipped System or Communication Error	
Multi Around Monitor	CAMERA_94080100		Non-equipped System or Communication Error	
EPB	EPB_4C080000		No DTCs	
Gateway	GW_C1000000		Non-equipped System or Communication Error	
FCM/LDW/AHB	ADAS_4B080003		Non-equipped System or Communication Error	
BSW	BSW_RAD_MASTER_A 0080000		Non-equipped System or Communication Error	
BSW(SUB)	BSW_RAD_SLAVE_A0 080000		Non-equipped System or Communication Error	