Adjuster Report Page 1 of 5

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.

Our File No: CS/AIG20010249/R1TD3E2

AIG Building, 78 Shenton Way, #09-16 Singapore 079120

Date: 16/10/2020

REFERENCE

Insured/Claimant: CHNG CHANG CHING

Policy No: 1900252127

Date of Loss: 23/09/2020 Nature of Claim: OD Claim No: 6305957708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMQ8280L

Make & Model: MITSUBISHI ATTRAGE, 1.2 CVT (A) Engine No: 3A92UJC5550

Reg. Date: 03/12/2019 (Man. Year: 2019) Chassis No: MMBSTA13AKH003684

Colour: Red Odometer: 3598 km

Engine Capacity: 1193 cc Market Value/New Car Price: \$\$58,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,303.92	5,739.44	4,564.48	44.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,770.00	3,490.00	2,280.00	39.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,073.92	9,229.44	6,844.48	42.58
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,473.92	8,629.44	6,844.48	44.23
+ GST 7.00/7.00% (S\$)	1,083.17	604.06	479.11	44.23
Nett Amount (S\$)	16,557.09	9,233.50	7,323.59	44.23

INSPECTION

Date of Assignment: 29/09/2020

Date Inspected: 24/09/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan

Gardens)

209 Pandan Gardens Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster Report Page 2 of 5

Adjuster: MOHD RASUL Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

REPAIR DETAILS

R	PCO	mm	en	പ്പ	4 P	arts
11	てしし			ucı		arto

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	50.00 F	*20.00 F
3	1		*MIRROR ASSY, DOOR, RH	Serviceable	638.00 FL	*-FL
1	1		*COVER, DOOR MIRROR, OTR RH	Serviceable	114.00 FL	*- FL
5	1		*FENDER, FR RH	Bent	497.00 FL	*497.00 FL
3	1		*EMBLEM ECO	Necessary	17.00 F	*17.00 F
7	1		*SHIELD, FR WHEELHOUSE, RH	Deformed	98.00 FL	*98.00 FL
8	10		*CLIP, FENDERSHIELD	Necessary	40.00 FL	*40.00 FL
9	1		*HEADLAMP ASSY, RH	Cracked	660.00 FL	*660.00 FL
10	1		*PANEL, HEADLAMP SUPPORT, UPR	Serviceable	65.00 FL	*- FL
11	1		*PANEL ASSY, FR END	Serviceable	1,055.00 FL	*- FL
12	1		*GRILLE, RADIATOR	Serviceable	554.00 FL	*-FL
13	1		*MARK, THREE-DIA	Serviceable	69.00 FL	*- FL
14	1		*BRACKET, FR BUMPER, LH	Serviceable	13.00 FL	*- FL
15	1		*GRILLE, FR UNDER	Serviceable	165.00 FL	*- FL
16	1		*GARNISH, FR BUMPER, RH	Scratched	127.00 FL	*127.00 FL
17	1		*AIR DAM, SIDE, FR RH	Serviceable	18.00 FL	*- FL
18	1		*AIR DAM, SIDE, FR LH	Serviceable	18.00 FL	*- FL
19	1		*COVER, HEADLAMP SUPT PANEL	Serviceable	62.00 FL	*- FL
20	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
21	1		*COVER, FR BUMPER	Serviceable	13.00 FL	*- FL
22	1		*FACE, FR BUMPER	Deformed	703.00 FL	*703.00 FL
23	1		*BODY KIT, ATTRAGE, W54	Cracked	1,643.00 F	*1,643.00 F
24	1		*WHEEL, DISC	Scratched	687.00 FL	*687.00 FL
25	1		*GEAR & LINK ASSY, STEERING	Serviceable	1,444.00 FL	*-FL
26	1		*LH END ASSY, TIE ROD	Serviceable	52.00 FL	*-FL
27	1		*RH END ASSY, TIE ROD	Serviceable	52.00 FL	*-FL
28	1		*STRUT, FR SUSP	Bent	452.00 FL	*452.00 FL
29	1		*PAD, FR SUSP SPRING	Serviceable	17.00 FL	*-FL
29 30	1		*BEARING, FR SUSP STRUT	Necessary	9.00 FL	*9.00 FL
30 31	1		*SUPPORT, FR SUSP STRUT	Serviceable	17.00 FL	*-FL
31 32	1		*INSULATOR, FR SUSP STRUT	Serviceable	83.00 FL	*-FL
32 33	1		•	Serviceable	98.00 FL	*-FL
აა 34	1		*INSULATOR, FR SUSP STRUT	Bent		
3 4 35	1		*HUB ASSY, FR WHEEL		215.00 FL	*215.00 FL *8.00 FL
			*SNAP RING, FR WHEEL HUB	Necessary	8.00 FL	
36 37	1		*BEARING, FR WHEEL HUB	Bent	121.00 FL	*121.00 FL
37 20	1		*COVER, FR BRAKE DISC	Serviceable	26.00 FL	*-FL
38	1		*KNUCKLE, RH	Bent	365.00 FL	*365.00 FL
39 40	1		*ARM ASSY, FR SUSP, LWR RH	Bent	337.00 FL	*337.00 FL
40	1		*CROSSMEMBER, FR AXLE, NO.1	Bent	864.00 FL	*864.00 FL
41	1		*SHAFT AS, FR AXLE DRIVE, RH	Serviceable	1,201.00 FL	*-FL
42	1		*BRACKET, FR BUMPER, RH	Serviceable	13.00 FL	*-FL
43	1		*SEAT, FR SUSP SPRING, UPR	Serviceable	37.00 FL	*- FL
44	1		*STOPPER,FR SUSP STRUT	Necessary	27.00 FL	*27.00 FL
45 	1		*CAP, DISC WHEEL, CTR	Necessary	22.00 FL	*22.00 FL
⊢=⊦ra	inchise p	oart. S=SpcN	lett. L=ListItemDisc.	Cub Total (Cft)	12 0EC 00	6 052 00
			Link Harm Birnarini and Little	Sub Total (S\$)	12,856.00	6,952.00
			 List Item Discount on L Ite 	ms 23.00/23.00% (S\$)	2,552.08	1,212.56

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen... 16/10/2020

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 5

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Total Parts (S\$)	10,303.92	5,739.44
	Report was unsubmitted during this print-out.					

Adjuster Report Page 5 of 5

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER, RH FRONT FENDER, RH SIDE MIRROR, REPAIR FRONT BONNET	New	2,250.00	1,125.00
2	REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK (* Check)	New	100.00	0.00
3	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM (* Check)	New	80.00	0.00
4	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, FRONT BUMPER, FRONT BODY KIT, RH FRONT FENDER, RH SIDE MIRROR AND AFFECTED PORTION	New	2,450.00	1,575.00
5	APPLY BODY KITS SEALANT	New	60.00	0.00
6	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
7	PERFORM RUST PREVENTION	New	80.00	40.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
9	RENEW FRONT UNDERCARRIAGE DAMAGES (* Check)	New	450.00	450.00
10	LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING	New	30.00	30.00
11	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
	Gross Labou	r Cost (S\$)	5,770.00	3,490.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >