

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20010251/GYD3Q2

Date: 02/11/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant

Vehicle No : SMH9617R

Insured Vehicle No : GZ5148E

Date of Loss: 21/09/2020

Nature of Claim:

TP

Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMH9617R**

Make & Model: NISSAN SYLPHY, 1.6 CVT ABS D/AIRBAG 2WD 4DR (A)

Engine No: HR16939908C

Reg. Date: 18/02/2019 (Man. Year: 2019)

Chassis No: MNTBBAB17Z0034598

Colour: Red

Odometer: 29731 km

Engine Capacity: 1598 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size:

195/60 R16

Front Left Side: Bridgestone 6 mm

Rear Left Side:

Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side:

Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	786.00	602.48	183.52	23.35
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,023.00	743.00	1,280.00	63.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,809.00	1,345.48	1,463.52	52.10
+ GST 7.00/7.00% (S\$)	196.63	94.18	102.45	52.10
Nett Amount (S\$)	3,005.63	1,439.66	1,565.97	52.10

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 25/09/2020 Inspected At:

Autolution Industrial Pte Ltd (Ubi)

19 Ubi Road 4

Singapore 408623

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2020)
Parts:	143	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMH9617R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*STAY RR BMPR RH	Not Necessary	52.00 FN	*- FN
2	1		*ABSORBER ENERGY RR BUMPER	Not Necessary	78.00 FN	*- FN
3	1		*RH REFLECTOR RR BUMPER	Not Necessary	61.90 FN	*- FN
4	1		*RH SIDE BRACKET RR BUMPER	Necessary	39.80 FN	*39.80 FN
5	6		*CLIP RR BUMPER	Necessary	8.40 FN	*8.40 FN
6	1		*REAR BUMPER	Deformed	679.90 FN	*679.90 FN
7	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
					Sub Total (\$\$)	970.00 748.10
					- Nett Item Discount on N Items 20.00/20.00% (\$\$)	184.00 145.62
					Total Parts (\$\$)	786.00 602.48

F=Franchise part. S=SpcNett. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REPAIR RR END PANEL & RH RR FENDER RENEW REAR BUMPER	New	1,170.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	750.00	250.00
3	REMOVE AND INSTALL REVERSE SENSOR	New	55.00	55.00
4	REMOVE AND INSTALL BOTH RR COMB LAMP	New	48.00	48.00
Gross Labour Cost (\$\$)			2,023.00	743.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >