

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20010255/AVF3Q2

Date: 09/03/2021

REFERENCE

Insured/Claimant: KARUPPANAN KARMEHAN
Date of Loss: 08/09/2020

Policy No: 1800111412
Nature of Claim: OD

Claim No: 0675388894SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SME2218X | | |
| Make & Model: | AUDI A4, 2.0 TFSI QU S-TRONIC (A) | Engine No: | CVK068319 |
| Reg. Date: | 21/09/2018 (Man. Year: 2018) | Chassis No: | WAUZZZF46JA231800 |
| Colour: | White | Odometer: | 29654 km |
| Engine Capacity: | 1984 cc | | |
| Market Value/New Car Price: | S\$123,000.00 | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size: | 205/60 R16 | Rear Tyre Size: | 205/60 R16 |
| Front Left Side: | Continental 6 mm | Rear Left Side: | Continental 6 mm |
| Front Right Side: | Continental 6 mm | Rear Right Side: | Continental 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 6,762.00 | 4,383.20 | 2,378.80 | 35.18 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 10,622.00 | 7,222.00 | 3,400.00 | 32.01 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 17,384.00 | 11,605.20 | 5,778.80 | 33.24 |
| + GST 7.00/7.00% (S\$) | 1,216.88 | 812.36 | 404.52 | 33.24 |
| Nett Amount (S\$) | 18,600.88 | 12,417.56 | 6,183.32 | 33.24 |

INSPECTION

Date of Assignment: 23/09/2020

Date Inspected: 23/09/2020 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. Particulars | Condition | Repairer's | Amount |
|-----|-----|---------------------------------------|---------------|-------------|--------------|
| 1 | 1 | *SILL PANEL WITH B-PILLAR-RH | DENTED | 2,149.00 FS | *1,719.20 FS |
| 2 | 1 | *SILL TRIM STRIP-RH | NECESSARY | 119.00 FS | *94.80 FS |
| 3 | 1 | *REAR DOOR-RH | DENTED | 2,354.00 FS | *1,883.20 FS |
| 4 | 1 | *REAR DOOR OUTER SEAL | NECESSARY | 203.00 FS | *162.00 FS |
| 5 | 1 | *BONDING AGENT | NOT NECESSARY | 47.00 FS | - |
| 6 | 1 | *CLEANING SOLUTION | NOT NECESSARY | 65.00 FS | - |
| 7 | 1 | *SEALING STRIP | NOT NECESSARY | 16.00 FS | - |
| 8 | 1 | *REAR DOOR ATTACHMENT PARTS | NOT NECESSARY | 563.00 FS | - |
| 9 | 1 | *REAR DOOR CATCH | NOT NECESSARY | 119.00 FS | - |
| 10 | 1 | *WHEEL HOUSING LINER-RH | NOT NECESSARY | 237.00 FS | - |
| 11 | 1 | *WHEEL HOUSING LINER ATTACHMENT PARTS | NOT NECESSARY | 90.00 FS | - |
| 12 | 1 | *CAVITY WAX | NECESSARY | 140.00 FS | *140.00 FS |
| 13 | 1 | *ACRYLIC SEALANT | NECESSARY | 180.00 FS | *180.00 FS |
| 14 | 1 | *STONE CHIP | NECESSARY | 180.00 FS | *180.00 FS |
| 15 | 1 | *SUNDRIES | NECESSARY | 300.00 FS | *24.00 FS |

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **6,762.00** **4,383.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|---|----------|------------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REMOVE AND TRANSFER RHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGES | New | 280.00 | 280.00 |
| 2 | TO DISMANTLE RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY | New | 350.00 | 250.00 |
| 3 | TO REMOVE AND REINSTALL RHS FRONT SEAT ASSY,RHS REAR SEAT ASSY,ABCD PILLAR TRIMS,SILL TRIMS,FLOOR CARPETS,ELECTRONIC COMPONENTS AND FUSE TRAYS.DISENGAGE RHS SEAT BELT AND HEAD AIRBAG. | New | 1,800.00 | 1,800.00 |
| 4 | TO DISMANTLE AND RENEW RHS REAR DOOR. TO CUT OUT AND WELD RHS SILL PANEL WTH RHS B-PILLAR.RE-ORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED. | New | 3,500.00 | 2,500.00 |
| 5 | TO RESPRAY RHS REAR DOOR,RHS FRONT DOORM RHS SILL PANEL,RHS B-PILLAR,DOOR ENTRANCES AND RHS REAR FENDER. | New | 4,500.00 | 2,200.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK. | New | 192.00 | 192.00 |
| Gross Labour Cost (\$\$) | | | 10,622.00 | 7,222.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >