

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Sep 2020		24 Sep 2020 14:58 Edit Adj Rpt	S\$5,500.00 Edit Estimates	S\$5,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	SG SAGAWA AMEROID PTE LTD, Co. Reg. No.: 199100423D, GST No.: M200978188								
Main Claimant:	AADHI INTERNATIONAL PTE LTD, Co. Reg. No.: 201432665D								
Vehicle Reg. No.:	YP3661S	Date of Loss:	22/09/2020 09:00 - :59 [50 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 247859	Policy/Cover Note No.:	30001412560 (Comprehensive) Coverage: 01/04/2020 - 31/03/2021						
Vehicle Reg. No. (Insured):	YP3479C	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Katherine Wong - 6594 2544]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 24/10/2020]								
Driver/Custodian (Insured):	ISKANDAR SHAH (36 / Male) , NRIC: S8467850C, Tel: +6591090861 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 24/09/2020. (MANUAL ASSIGN) Liab: Clear. Assign: LKK Auto Consultants. Contact: David Ang @ 9815 4655								
ASSOCIATED MAIL RECEIVED			View All Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS			View All Search Tasks Create New Task Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YP3661S (247859)**
[YP3479C]
TP
AADHI INTERNATIONAL PTE LTD
Sep 22 2020 9:00AM
[SG SAGAWA AMEROID PTE LTD]
Hup Motor Trading & Service

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Video				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	29/09/20 17:26	Video - Accident		Load MP4	
Assessment Reports				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/09/20 14:19	Accident Statement From:OD - Reg. No: YP3479C, Claimant: SG SAGAWA AMEROID PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/09/20 11:21	Adjuster Immediate Advice		Load HTM	
Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/10/20 11:07	General View		Load PDF	
Documentation				1 per page ▼	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/09/20 14:20	PRI EMAIL		Load PDF	
2	24/09/20 14:20	TP Accident Report		Load PDF	
3	24/09/20 14:20	PRI		Load PDF	
4	24/09/20 14:20	ACCIDENT PHOTO		Load JPG	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)		Thumbnail	Print
1	24/09/20 14:55	Survey Request - Manual Assigned		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG20010256/UTD3S2**Date:** 02/10/2020**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	30001412560
Claimant Vehicle No :	YP3661S	Insured Vehicle No :	YP3479C
Date of Loss:	22/09/2020	Nature of Claim:	TP
		Claim No:	247859

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP3661S		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB71ER4SDEC (M)	Engine No:	4P10C27715
Reg. Date:	18/07/2016 (Man. Year: 2016)	Chassis No:	FEB71EA20289
Colour:	White	Odometer:	204267 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5 (D)
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6/6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,316.80	4,989.88	7,326.92	59.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,890.00	2,360.00	55.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,566.80	6,879.88	9,686.92	58.47
Approved Total (Overridden) (S\$)		5,500.00		
Nett Amount (S\$)	16,566.80	5,500.00	11,066.80	66.80

INSPECTION

Date of Assignment:	24/09/2020		
Date Inspected:	24/09/2020	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Oct 2020)	
Parts:	N/A	mitsubishi canter 3.0 D FEB71ER4SDEC (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YP3661S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented / Bent	1,117.00 FL	*1,010.33 FL
2	1		*FRONT BUMPER N/S SIDE PAD	Distorted	328.00 FL	*328.00 FL
3	1		*FRONT BUMPER N/S BRACKET STAY	Not Necessary	189.00 FL	*- FL
4	1		*FRONT GRILLE	Not Necessary	1,102.00 FL	*- FL
5	1		*FRONT GRILLE LOGO EMBLEM	Not Necessary	60.00 FL	*- FL
6	1		*FRONT GRILLE CANTER EMBLEM	Not Necessary	76.00 FL	*- FL
7	1		*FRONT WINDSCREEN GLASS WEATHERSTRIP	Not Necessary	365.00 FL	*- FL
8	1		*FRONT WINDSCREEN SEALANT	Not Necessary	60.00 FL	*- FL
9	20		*FRONT GRILLE CLIPS	Not Necessary	160.00 FL	*- FL
10	1		*FRONT TOP PANEL	Not Necessary	2,459.00 FL	*- FL
11	1		*FRONT TOP PANEL FUSO EMBLEM	Not Necessary	151.00 FL	*- FL
12	1		*FRONT N/S CORNER PANEL	Cracked	486.00 FL	*486.00 FL
13	1		*FRONT N/S SIDE MIRROR (STRAIGHT)	Scratched	106.00 FL	*106.00 FL
14	1		*FRONT N/S SIDE MIRROR BRACKET	Not Necessary	422.00 FL	*- FL
15	1		*N/S HEAD LAMP ASSY	Cracked	558.00 FL	*501.41 FL
16	1		*FRONT N/S SIDE LAMP ASSY	Broken	214.00 FL	*214.00 FL
17	1		*FRONT N/S SIGNAL LAMP ASSY	Broken	294.00 FL	*294.00 FL
18	1		*FRONT N/S DOOR	Dented / Bent	1,915.00 FL	*1,915.00 FL
19	2		*FRONT N/S DOOR TOP & LOW HINGE	Not Necessary	232.00 FL	*- FL
20	1		*FRONT N/S DOOR WEATHERSTRIP	Not Necessary	190.00 FL	*- FL
21	1		*FRONT N/S DOOR CHECKER	Not Necessary	95.00 FL	*- FL
22	20		*FRONT N/S DOOR TRIM BOARD CLIPS	Not Necessary	160.00 FL	*- FL
23	1		*FRONT N/S DOOR PILLAR PANEL	Bent / Twisted	1,340.00 FL	*1,340.00 FL
24	1		*FRONT N/S DOOR PILLAR WHEEL GARNISH	Not Necessary	155.00 FL	*- FL
25	1		*FRONT N/S STEP PANEL	No such part	557.00 FL	*- FL
26	1		*FRONT N/S STEP PANEL GARNISH	Broken	647.00 FL	*415.44 FL
27	1		*AIR COND CONDENSER	Not Necessary	1,915.00 FL	*- FL
28	1		*N/S HEAD LAMP LOWER RUBBER	Torn	25.00 FL	*25.00 FL
29	3		*N/S HEAD LAMP LOWER RUBBER CLIPS	Necessary	18.00 FL	*18.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	15,396.00	6,653.18
- List Item Discount on L Items 20.00/25.00% (\$\$)	3,079.20	1,663.30
Total Parts (\$\$)	12,316.80	4,989.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP FOR AFFECTED WIRING SYSTEM.	New	60.00	30.00
2	TO REMOVE & REFIX AIR COND CONDENSER, BLOWER MOTOR, CONSWL BOX & NECESSARY PARTS, INCLUDING TOP UP AIR COND GAS.	New	150.00	0.00
3	TO REMOVE & REFIX FRONT WINDSCREEN GLASS & NECESSARY PARTS, TO ENABLE REPAIR FRONT N/S DOOR PILLAR PANEL.	New	150.00	0.00
4	TO REMOVE & REFIX FRONT N/S DOOR INNER LOCK, GLASS, REGULATOR, MOULDING, CHANNEL, MOTOR & NECESSARY PARTS.	New	200.00	60.00
5	TO REMOVE & REFIX CUSHION SEAT, CARPET, FLOOR MAT, GARNISH, UPHOLSTERY & NECESSARY PARTS, TO ENABLE REPAIR FRONT N/S DOOR PILLAR & WHEEL PANEL.	New	150.00	60.00
6	TO CHECK & ADJUST FRONT WHEEL BALANCING & WHEEL ALIGNMENT.	New	120.00	80.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS.	New	120.00	60.00
8	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PANEL, TO JACK, STRAIGHTEN & KNOCKING OUT FRONT PANEL, FRONT N/S DOOR PILLAR PANEL, WHEEL PANEL & NECESSARY PARTS, TO WELD, RENEW & ALIGN ABOVE PARTS.	New	1,800.00	800.00
9	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS.	New	1,500.00	800.00
Gross Labour Cost (\$\$)			4,250.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >