

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010260/ARA3Q2

Date: 12/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900161779

Claimant
Vehicle No : SDP1948C **Insured Vehicle No :** SBU1838J

Date of Loss: 23/09/2020 Nature of Claim: TP Claim No: 2695934832SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SDP1948C**

Make & Model: TOYOTA WISH, 1.8 X (A)

Engine No: 2ZR1622668

Reg. Date: 14/01/2016 (Man. Year: 2015)

Chassis No: ZGE206025959

Colour: White

Odometer: 82132 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	40,444.15	17,722.58	22,721.57	56.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,480.00	3,550.00	4,930.00	58.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	48,924.15	21,272.58	27,651.57	56.52
Approved Total (Overridden) (S\$)		16,000.00		
(S\$)	48,924.15	16,000.00	32,924.15	67.30
+ GST 7.00/7.00% (S\$)	3,424.69	1,120.00	2,304.69	67.30
Nett Amount (S\$)	52,348.84	17,120.00	35,228.84	67.30
+ Car Rental (13.0 x S\$130.00/day) (S\$)		1,690.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		60.00		
Nett Liability (S\$)		18,906.45		

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 25/09/2020 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT BUMPER	Distorted	1,164.70 FL	*594.00 FL
2	1	*FRONT BUMPER FOGLAMP COVER	O/S Deformed	250.20 FL	*125.10 FL
3	1	*FRONT BUMPER BOTTOM GARNISH	Deformed	174.20 FL	*174.20 FL
4	1	*FRONT BUMPER LOWER SIDE GRILLE	O/S Deformed	174.60 FL	*87.30 FL
5	2	*FRONT BUMPER SIDE RETAINER	Necessary	165.80 FL	*165.80 FL
6	1	*FRONT BUMPER REINFORCEMENT	Bent	298.70 FL	*298.70 FL
7	1	*FRONT BUMPER SPONGE	Cracked	176.80 FL	*176.80 FL
8	1	*CENTRE GRILLE C/W CHROME	Cracked	385.15 FL	*385.15 FL
9	2	*HEADLAMP	Cracked	4,167.44 FL	*4,167.44 FL
10	2	*SIDE SKIRT	Not Necessary	1,790.00 FL	*- FL
11	1	*FRONT FENDER	O/S Buckled	1,688.20 FL	*645.10 FL
12	1	*FRONT FENDER COWLING	O/S S Torn	330.02 FL	*165.01 FL
13	2	*FRONT QUARTER GLASS C/W MOULDING	Not Necessary	692.20 FL	*- FL
14	1	*FRONT WHEEL HOUSE EXTEND PANEL	O/S Buckled	796.80 FL	*398.40 FL
15	1	*FRONT WHEEL RIM RH	Not Necessary	1,162.00 FL	*- FL
16	1	*FRONT ABS SENSOR	Not Necessary	450.00 FL	*- FL
17	1	*FRONT CROSSMEMBER	Not Necessary	1,984.00 FL	*- FL
18	1	*FRONT DRIVESHAFT RH	Not Necessary	1,720.00 FL	*- FL
19	1	*FRONT LINKAGE RH	Not Necessary	195.00 FL	*- FL
20	1	*FRONT KNUCKLE ARM RH	Not Necessary	560.00 FL	*- FL
21	1	*FRONT KNUCKLE BEARING RH	Not Necessary	175.00 FL	*- FL
22	1	*FRONT WHEEL HUP RH	Not Necessary	220.00 FL	*- FL
23	1	*FRONT SHOCK ABSORBER RH	Not Necessary	420.00 FL	*- FL
24	1	*FRONT LOWER ARM RH	Not Necessary	630.00 FL	*- FL
25	1	*FRONT STEERING RACK AND PINION	Not Necessary	1,670.00 FL	*- FL
26	2	*FRONT WIPER PANEL SIDE GARNISH	Not Necessary	157.42 FL	*- FL
27	1	*FRONT WIPER PANEL GARNISH	Cut	496.30 FL	*496.30 FL
28	1	*BONNET	Distorted	768.10 FL	*768.10 FL
29	1	*BONNET LOGO	Necessary	75.60 FL	*75.60 FL
30	1	*BONNET LOCK	Damaged	90.20 FL	*90.20 FL
31	1	*BONNET LOCK CABLE	Not Necessary	68.20 FL	*- FL
32	1	*BONNET INNER RUBBER	Not Necessary	24.01 FL	*- FL
33	1	*BONNET INSULATOR	Crumpled	279.01 FL	*279.01 FL
34	4	*BONNET STOPPER	Not Necessary	80.00 FL	*- FL
35	1	*BONNET STAND	Not Necessary	28.70 FL	*- FL
36	1	*BONNET STAND HOLDER CLIP	Not Necessary	11.30 FL	*- FL
37	2	*BONNET HINGE	Bent	130.00 FL	*130.00 FL
38	1	*FRONT SUPPORT PANEL	Distorted	1,156.32 FL	*874.00 FL
39	1	*FRONT SUPPORT PANEL TOP GARNISH	Deformed	155.00 FL	*155.00 FL
40	1	*FRONT BRACE PANEL	Bent	105.00 FL	*105.00 FL
41	1	*RADIATOR	Dented	1,493.70 FL	*1,493.70 FL
42	2	*RADIATOR SIDE GARNISH	Deformed	151.60 FL	*151.60 FL
43	4	*RADIATOR RUBBER MOUNTING	Necessary	160.00 FL	*160.00 FL
44	1	*RADIATOR TOP HOSE	Not Necessary	85.00 FL	*- FL
45	1	*RADIATOR OVERFLOW HOSE	Not Necessary	39.10 FL	*- FL
46	1	*RADIATOR LOWER HOSE	Not Necessary	85.00 FL	*- FL
47	2	*RADIATOR TOP BRACKET	Cracked	80.00 FL	*80.00 FL
48	1	*RADIATOR FAN MOTOR	Damaged	493.20 FL	*493.20 FL
49	1	*RADIATOR FAN COWLING	Cracked	278.60 FL	*278.60 FL
50	1	*RADIATOR FAN BLADE	Cut	178.60 FL	*178.60 FL
51	1	*RADIATOR SPARE TANK	Cracked	195.30 FL	*195.30 FL
52	1	*AIR CON CONDENSER	Dented	1,355.32 FL	*1,355.32 FL
53	2	*AIR CON CONDENSER SIDE GARNISH	Not Necessary	78.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	4		*AIR CON CONDENSER MOUNTING RUBBER	Not Necessary	98.80 FL	*- FL
55	2		*AIR CON CONDENSER BRACKET	Not Necessary	77.20 FL	*- FL
56	1		*AIR CON FAN BLADE	Cut	171.20 FL	*171.20 FL
57	1		*AIR CON FAN MOTOR	Damaged	493.70 FL	*493.70 FL
58	1		*AIR CON FAN COWLING	Repeated	278.60 FL	*- FL
59	1		*AIR CON COMPRESSOR	Not Necessary	2,762.90 FL	*- FL
60	1		*AIR CON COMPRESSOR WIRE HARNESS	Not Necessary	769.80 FL	*- FL
61	1		*AIR CON COMPRESSOR HOSE (PRESSURE)	Bent	379.20 FL	*379.20 FL
62	1		*AIR CON COMPRESSOR HOSE (SUCTION)	Not Necessary	365.90 FL	*- FL
63	1		*AIR CON PIPE (OUTLET)	Bent	380.00 FL	*380.00 FL
64	1		*FRONT TEMPERATURE SENSOR	Not Necessary	128.60 FL	*- FL
65	1		*ALTERNATOR	Cracked	1,987.50 FL	*1,987.50 FL
66	1		*HORN	O/S Damaged	241.22 FL	*120.61 FL
67	1		*ABS PUMP	Cracked	5,400.30 FL	*3,214.00 FL
68	1		*ABS PUMP BRACKET	Not Necessary	135.70 FL	*- FL
69	4		*ABS PUMP BRAKE PIPE	Not Necessary	1,000.00 FL	*- FL
70	1		*AIR CLENAER BOX (COMPLETE SET)	Not Necessary	797.93 FL	*- FL
71	1		*AIR CLENAER BRACKET	Not Necessary	87.60 FL	*- FL
72	1		*BATTERY TRAY	Not Necessary	65.10 FL	*- FL
73	1		*BATTERY BRACKET	Not Necessary	57.60 FL	*- FL
74	1		*FRONT INTAKE MANIFOLD	Cracked	987.40 FL	*738.70 FL
75	1		*SET ENGINE MOUNTING	Not Necessary	850.90 FL	*- FL
76	1		*FRONT CHASSIS MEMBER RH	Repair	1,653.10 FL	*- FL
77	1		*ENGINE BOTTOM CROSS MEMBER	Bent	1,196.80 FL	*558.00 FL
78	2		*ENGINE UNDER COVER GARNISH	Cracked	344.80 FL	*344.80 FL
79	1		*WASHER TANK	Deformed	153.20 FL	*153.20 FL
80	1		*WASHER TANK MOTOR	Not Necessary	112.40 FL	*- FL
81	1		*FUSE BOX	Not Necessary	687.90 FL	*- FL
82	1		*FRONT NUMBER PLATE	Cracked	80.00 FS	*50.00 FS
83	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
84	1		*SET CENTRE GRILLE CLIP	Necessary	60.00 FS	*20.00 FS
85	1		*SET SIDE SKIRT CLIP	Not Necessary	80.00 FS	*- FS
86	1		*SET BONNET INSULATOR CLIP	Necessary	80.00 FS	*30.00 FS
87	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	150.00 FS	*- FS
88	1		*SET FRONT SUPPORT PANEL TOP GARNISH	Necessary	80.00 FS	*20.00 FS
89	1		*SET RADIATOR SIDE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
90	1		*SET AIR CON CONDENSOR SIDE GARNISH CLIP	Necessary	50.00 FS	*10.00 FS
91	1		*SET ENGINE UNDER COVER GARNISH CLIP	Necessary	80.00 FS	*30.00 FS
92	1		*SET FRONT FENDER COWLING CLIP	Necessary	80.00 FS	*20.00 FS
93	1		*FRONT WHEEL HOUSE EXTEND PANEL SEALANT	Not Necessary	120.00 FS	*- FS
94	1		*SET FRONT WIPER PANEL GARNISH CLIP	Not Necessary	80.00 FS	*- FS
95	1		*FRONT WHEEL TYRE RH	Not Necessary	480.00 FS	*- FS
96	1		*BATTERY	Not Necessary	220.00 FS	*- FS
97	1		*COOLANT	Necessary	60.00 FS	*40.00 FS
98	1		*BRAKE OIL	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 53,295.54 23,543.44
- List Item Discount on L Items 25.00/25.00% (\$\$) 12,851.39 5,820.86

Total Parts (\$\$) 40,444.15 17,722.58

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVING AND REPLACING PARTS	New	2,500.00	1,500.00
2	SPRAY PAINTING TO AFFECTED AREA	New	2,000.00	1,400.00
3	REMOVE AND REFIX WIREHARNESS AND WIRING CHECKING	New	350.00	30.00
4	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	New	120.00	60.00
5	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	80.00	60.00
6	REFOCUS HEADLAMP BEAM	New	60.00	0.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
8	TO PRESS FRONT WHEEL BEARING	New	80.00	0.00
9	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
10	FOUR WHEEL ALIGNMENT	New	120.00	0.00
11	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
12	REMOVE AND REFIX INTEKE MANIFOLD AND ALTERNATOR	New	350.00	150.00
13	TO LIFT UP AND REFIX ENGINE	New	650.00	350.00
14	RESET ENGINE LIGHT	New	350.00	0.00
15	RESET ABS LIGHT	New	350.00	0.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	350.00	0.00
Gross Labour Cost (\$\$)			8,480.00	3,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >