

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20010267/KPA3Q2**Date:** 30/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900015988
Claimant Vehicle No :	SFN4887L	Insured Vehicle No :	SGT6883R
Date of Loss:	21/09/2020	Nature of Claim:	TP
		Claim No:	9801100772SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFN4887L	Engine No:	2GR8671444
Make & Model:	LEXUS GS450H, 3.5 GWS191 (A)	Chassis No:	JTHBC96SX05019816
Reg. Date:	24/07/2009 (Man. Year: 2009)	Odometer:	106261 km
Colour:	Metallic Black		
Engine Capacity:	3456 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/40Z R18	Rear Tyre Size:	245/40Z R18
Front Left Side:	Michelin 7 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	26,822.38	16,110.59	10,711.79	39.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,690.00	2,650.00	1,040.00	28.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	30,512.38	18,760.59	11,751.79	38.51
Approved Total (Overridden) (S\$)		14,950.00		
(S\$)	30,512.38	14,950.00	15,562.38	51.00
+ GST 7.00/7.00% (S\$)	2,135.87	1,046.50	1,089.37	51.00
Nett Amount (S\$)	32,648.25	15,996.50	16,651.75	51.00
+ Loss of Use (14.0 x S\$150.00/day) (S\$)		2,100.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		18,098.50		
Global Sum Settlement (S\$)		18,000.00		

INSPECTION

Date of Assignment:	24/09/2020	
Date Inspected:	25/09/2020 Inspected At:	K.kim Hin Auto Pte Ltd (Autocity) 160 Sin Ming Drive, #02-18/19/20/21, Sin Ming Autocity Singapore 575722
Estimated Period of Repair:	14.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*N/S FRONT FENDER	Bent	1,576.40 FL	*1,208.70 FL
2	1		*N/S FRONT FENDER WHEEL ARCH MOULDING	Distorted	114.90 FL	*114.90 FL
3	1		*N/S FRONT FENDER INNER VERTICAL GARNISH	Distorted	115.00 FL	*115.00 FL
4	1		*N/S FRONT FENDER INNER SHIELD	Cracked	464.50 FL	*464.50 FL
5	8		*N/S FRONT FENDER INNER SHIELD CLIPS	Necessary	44.00 FL	*44.00 FL
6	2		*N/S FRONT FENDER INNER SHIELD RETAINER	Serviceable	24.60 FL	*- FL
7	2		*N/S FRONT FENDER INNER SHIELD RETAINER PIN	Not Necessary	14.00 FL	*- FL
8	1		*N/S WING MIRROR ASSY	Serviceable	1,647.60 FL	*- FL
9	1		*N/S SIDE SKIRTING	Warped	1,006.50 FL	*1,006.50 FL
10	1		*N/S FRONT DOOR	Bent	2,020.60 FL	*1,340.50 FL
11	1		*N/S FRONT DOOR GLASS	Shattered	917.10 FL	*917.10 FL
12	1		*N/S FRONT DOOR GLASS RUN CHANNEL	Distorted	231.20 FL	*231.20 FL
13	1		*N/S FRONT DOOR GLASS RUN CHANNEL FRAME -FRONT	Distorted	366.70 FL	*366.70 FL
14	1		*N/S FRONT DOOR GLASS RUN CHANNEL FRAME -REAR	Dented	366.70 FL	*366.70 FL
15	1		*N/S FRONT DOOR GLASS REGULATOR	Bent	270.00 FL	*270.00 FL
16	1		*N/S FRONT DOOR GLASS REGULATOR MOTOR	Jammed	926.00 FL	*926.00 FL
17	1		*N/S FRONT DOOR HINGES -TOP	Bent	111.70 FL	*111.70 FL
18	1		*N/S FRONT DOOR HINGES -BOTTOM	Bent	111.70 FL	*111.70 FL
19	1		*N/S FRONT DOOR CHECKER	Bent	165.00 FL	*165.00 FL
20	1		*N/S FRONT DOOR CHECKER COVER	Serviceable	49.70 FL	*- FL
21	1		*N/S FRONT DOOR WEATHERSTRIP (50%)	Cut	278.55 FS	*154.75 FS
22	1		*N/S FRONT DOOR FRONT SEAL	Necessary	105.40 FL	*105.40 FL
23	1		*N/S FRONT DOOR TOP GARNISH	Cracked	201.70 FL	*201.70 FL
24	10		*N/S FRONT DOOR TOP GARNISH CLIPS	Necessary	55.00 FL	*55.00 FL
25	1		*N/S FRONT DOOR STIFFENER CUSHION	Distorted	150.60 FL	*150.60 FL
26	1		*N/S FRONT DOOR GLASS OUTER CHROME MOULDING	Bent	185.00 FL	*185.00 FL
27	1		*N/S FRONT DOOR GLASS INNER MOULDING	Bent	200.10 FL	*200.10 FL
28	1		*N/S FRONT DOOR TOP CHROME MOULDING	Necessary	170.20 FL	*170.20 FL
29	10		*N/S FRONT DOOR TOP CHROME MOULDING RIVET	Necessary	55.00 FL	*55.00 FL
30	1		*N/S FRONT DOOR INNER TRIM BOARD	Cracked	1,400.00 FL	*1,400.00 FL
31	1		*N/S FRONT DOOR INNER TRIM BOARD INNER BRACKET	Repair	95.10 FL	*- FL
32	1		*N/S FRONT DOOR INNER SIDE GARNISH	Serviceable	101.50 FL	*- FL
33	6		*N/S FRONT DOOR INNER SIDE GARNISH CLIPS	Not Necessary	33.00 FL	*- FL
34	1		*N/S FRONT DOOR INNER TRIM LAMP	Cracked	65.00 FL	*65.00 FL
35	1		*N/S FRONT DOOR POWER WINDOW SWITCH	Dented	199.90 FL	*199.90 FL
36	1		*N/S FRONT DOOR CENTRE LOCK SWITCH	Dented	280.50 FL	*280.50 FL
37	1		*N/S FRONT DOOR CONTROL UNIT	Cracked	485.00 FL	*485.00 FL
38	1		*N/S FRONT DOOR INNER STEP GARNISH -OUTER	Serviceable	200.10 FL	*- FL
39	1		*N/S FRONT DOOR INNER STEP GARNISH -INNER	Serviceable	211.70 FL	*- FL
40	1		*N/S FRONT DOOR OUTER HANDLE	Jammed	375.00 FL	*375.00 FL
41	1		*N/S FRONT DOOR OUTER HANDLE SEAL	Necessary	15.00 FL	*15.00 FL
42	1		*N/S FRONT DOOR OUTER HANDLE SIDE COVER	Serviceable	30.00 FL	*- FL
43	1		*FRT PILLAR N/S	Bent	449.40 FL	*449.40 FL
44	1		*N/S FRONT DOOR OUTER HANDLE SIDE COVER SEAL	Necessary	15.00 FL	*15.00 FL
45	1		*N/S FRONT DOOR OUTER HANDLE INNER BASE	Distorted	299.10 FL	*299.10 FL
46	1		*N/S FRONT DOOR INNER HANDLE	Serviceable	21.70 FL	*- FL
47	1		*N/S FRONT DOOR INNER HANDLE COVER	Serviceable	45.60 FL	*- FL
48	1		*N/S FRONT DOOR LOCK	Jammed	485.00 FL	*485.00 FL
49	1		*N/S FRONT DOOR LOCK CATCH	Serviceable	61.50 FL	*- FL
50	1		*N/S FRONT DOOR LOCK CATCH COVER	Serviceable	60.10 FL	*- FL
51	1		*N/S FRONT DOOR LOCK CABLE -INNER HANDLE	Jammed	65.70 FL	*65.70 FL
52	1		*N/S FRONT DOOR LOCK CABLE -REMOTE CONTROL	Dented	64.80 FL	*64.80 FL
53	1		*N/S FRONT DOOR LOCK TOP ROD	Distorted	69.80 FL	*69.80 FL
54	10		*N/S FRONT DOOR TOP VERTICAL GARNISH RIVET	Necessary	55.00 FL	*55.00 FL
55	1		*N/S FRONT DOOR PROTECTOR	Missing	298.30 FL	*298.30 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*N/S FRONT DOOR FRAME WEATHERSTRIP	Serviceable	200.00 FL	*- FL
57	1		*N/S FRONT DOOR TOP VERTICAL GARNISH	Dented	200.50 FL	*200.50 FL
58	1		*N/S FRONT PILLAR INNER GARNISH	Serviceable	195.00 FL	*- FL
59	1		*N/S FRONT PILLAR INNER TRIM	Serviceable	175.00 FL	*- FL
60	1		*N/S CENTRE PILLAR -OUTER	Bent	418.70 FL	*418.70 FL
61	1		*N/S CENTRE PILLAR INNER GARNISH -TOP	Serviceable	339.00 FL	*- FL
62	1		*N/S CENTRE PILLAR INNER GARNISH -BOTTOM	Serviceable	391.70 FL	*- FL
63	1		*N/S REAR DOOR	Bent	1,243.40 FL	*1,243.40 FL
64	1		*N/S REAR DOOR HINGES -TOP	Repair	137.30 FL	*- FL
65	1		*N/S REAR DOOR HINGES -BOTTOM	Repair	137.30 FL	*- FL
66	1		*N/S REAR DOOR CHECKER	Serviceable	302.90 FL	*- FL
67	1		*N/S REAR DOOR CHECKER COVER	Serviceable	75.00 FL	*- FL
68	1		*N/S REAR DOOR FRONT SEAL	Cut	95.00 FL	*95.00 FL
69	1		*N/S REAR DOOR WEATHERSTRIP	Serviceable	309.50 FL	*- FL
70	1		*N/S REAR DOOR GLASS OUTER MOULDING	Serviceable	280.30 FL	*- FL
71	1		*N/S REAR DOOR GLASS INNER MOULDING	Serviceable	210.50 FL	*- FL
72	1		*N/S REAR DOOR TOP CHROME MOULDING	Serviceable	261.00 FL	*- FL
73	10		*N/S REAR DOOR CHROME MOULDING RIVET	Not Necessary	55.00 FL	*- FL
74	1		*N/S REAR DOOR INNER TRIMBOARD	Serviceable	1,400.00 FL	*- FL
75	1		*N/S REAR DOOR PROTECTOR	Dented	304.30 FL	*304.30 FL
76	1		*N/S REAR DOOR FRAME WEATHERSTRIP	Serviceable	216.50 FL	*- FL
77	1		*N/S REAR DOOR TOP VERTICAL GARNISH	Serviceable	238.70 FL	*- FL
78	10		*N/S REAR DOOR TOP VERTICAL GARNISH RIVET	Not Necessary	55.00 FL	*- FL
79	1		*N/S FRONT RIM	Dented / Cut	3,787.10 FL	*1,850.00 FL
80	1		*N/S FRONT WHEEL BEARING	Not Necessary	670.30 FL	*- FL
81	1		*N/S FRONT TYRE	Serviceable	380.00 FS	*- FS
82	1		*N/S FRONT DOOR SPEAKER (50%)	Dented	200.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	29,707.25	17,872.35
- List Item Discount on L Items 10.00/10.00% (\$)	2,884.87	1,761.76
Total Parts (\$)	26,822.38	16,110.59

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CUT OUT DAMAGED PARTS,PANEL BEATING ,WELDING ,ALIGN,REFIX AND TO RENEW AFFECTED PARTS	New	1,400.00	1,000.00
2	TO REMOVE AND REFIT REAR UPHOLSTERY TRIMMING ,ROOF LINING ,SEATS ,SPEAKER BOARD IN ORDER TO FACILITATE REPAIRING WORKS	New	120.00	120.00
3	TO REMOVE AND REFIT FRONT SEAT ASSY TRIM BOARD AND CARPET TO FACILITATE REPAIRING WORKS	New	150.00	120.00
4	TO APPLY UNDERSEALING	New	160.00	90.00
5	TO REMOVE DOORS FITTINGS	New	160.00	120.00
6	TO DISMANTLE AND CHECK FRONT UNDERCARRIAGE TO REPLACE AFFECTED PORTIONS	New	120.00	0.00
7	TO CONDUCT FRONT WHEEL ALIGNMENT TEST	New	80.00	0.00
8	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	1,500.00	1,200.00
Gross Labour Cost (\$\$)			3,690.00	2,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >