

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010269/ARS3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800042986

Claimant
Vehicle No : SLT1387E **Insured Vehicle No :** SMT8966B

Date of Loss: 24/09/2020 Nature of Claim: TP Claim No: 4149391076SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLT1387E		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	HIDDEN
Reg. Date:	01/10/2017 (Man. Year: 2017)	Chassis No:	ZYX102069999
Colour:	Silver	Odometer:	397959 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	30,139.02	14,685.00	15,454.02	51.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,870.00	2,830.00	5,040.00	64.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	38,009.02	17,515.00	20,494.02	53.92
Approved Total (Overridden) (S\$)		14,000.00		
(S\$)	38,009.02	14,000.00	24,009.02	63.17
+ GST 7.00/7.00% (S\$)	2,660.63	980.00	1,680.63	63.17
Nett Amount (S\$)	40,669.65	14,980.00	25,689.65	63.17
+ Loss of Use (9.0 x S\$105.00/day) (S\$)		945.00		
+ Doc/Search Fee (S\$)		64.45		
Nett Liability (S\$)		15,989.45		
Global Sum Settlement (S\$)		15,950.00		

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 25/09/2020 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 9.0 days

Adjuster: ADRIAN LING**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	889.80 FL	*889.80 FL
2	1		*FRONT BUMPER FOGLAMP RH	Cracked	505.20 FL	*354.00 FL
3	1		*FRONT BUMPER FOGLAMP HOUSING RH	Cracked	371.70 FL	*371.70 FL
4	1		*FRONT BUMPER UPPER GRILLE	Cracked	439.60 FL	*439.60 FL
5	1		*FRONT BUMPER UPPER GRILLE		-	-
6	1		*FRONT BUMPER LOWER GRILLE	Cracked	98.50 FL	*98.50 FL
7	1		*FRONT BUMPER BOTTOM COVER GARNISH	Torn	185.30 FL	*185.30 FL
8	1		*FRONT BUMPER TOP COVER GARNISH	Deformed	160.50 FL	*160.50 FL
9	1		*FRONT BUMPER LOWER BEAM	Bent	130.10 FL	*130.10 FL
10	2		*FRONT BUMPER SIDE RETAINER	Necessary	157.00 FL	*157.00 FL
11	1		*FRONT BUMPER REINFORCEMENT	Bent	467.40 FL	*467.40 FL
12	1		*FRONT BUMPER SPONGE	Cracked	177.80 FL	*177.80 FL
13	1		*FRONT NUMBER PLATE GARNISH	Cracked	85.90 FL	*85.90 FL
14	1		*FRONT FENDER INNER COWLING	O/S Torn	478.60 FL	*239.30 FL
15	2		*FRONT FENDER ARCD GARNISH	Not Necessary	297.00 FL	*- FL
16	1		*GRILLE LOGO	Not Necessary	1,673.50 FL	*- FL
17	1		*GRILLE LOGO GARNISH BASE	Cracked	83.10 FL	*83.10 FL
18	1		*GRILLE LOGO GARNISH	Not Necessary	105.30 FL	*- FL
19	1		*HEADLAMP (LED)	O/S Cracked	8,793.60 FL	*2,721.00 FL
20	1		*FRONT MILLIME WAVE RADAR	Not Necessary	1,256.80 FL	*- FL
21	1		*HORN	Not Necessary	85.10 FL	*- FL
22	1		*AIR DUCT	Cracked	138.30 FL	*138.30 FL
23	1		*FRONT WASHER TANK	Deformed	268.50 FL	*268.50 FL
24	1		*FRONT WASHER TANK MOTOR	Not Necessary	164.30 FL	*- FL
25	1		*REAR BUMPER (UPPER)	Deformed	586.30 FL	*586.30 FL
26	1		*REAR BUMPER (LOWER)	Deformed	499.30 FL	*499.30 FL
27	1		*REAR BUMPER TOW HOOK COVER	Distorted	18.20 FL	*18.20 FL
28	1		*REAR BUMPER REFLECTOR GARNISH	O/S Cut	178.40 FL	*89.20 FL
29	1		*REAR BUMPER REINFORCEMENT	Bent	333.20 FL	*333.20 FL
30	2		*REAR BUMPER SIDE RETAINER	Necessary	200.80 FL	*200.80 FL
31	1		*TAILGATE	Dented	1,204.70 FL	*1,204.70 FL
32	2		*TAILGATE DAMPER	Not Necessary	524.40 FL	*- FL
33	1		*TAILGATE OUTER GARNISH	Cracked	891.20 FL	*891.20 FL
34	1		*TAILGATE SIDE LAMP	O/S Cracked	717.80 FL	*358.90 FL
35	1		*TAILGATE LOGO	Necessary	80.30 FL	*80.30 FL
36	1		*TAILGATE EMBLEM C-HR	Necessary	52.90 FL	*52.90 FL
37	1		*TAILGATE EMBLEM HYBRID	Necessary	65.70 FL	*65.70 FL
38	1		*TAILGATE INNER HOLDER	Not Necessary	85.30 FL	*- FL
39	2		*TAILGATE STOPPER	Not Necessary	49.00 FL	*- FL
40	1		*TAILGATE TOP LOCK	Damaged	385.70 FL	*385.70 FL
41	1		*TAILGATE LOWER LOCK	Not Necessary	38.50 FL	*- FL
42	1		*TAILGATE DETECTOR	Cracked	367.20 FL	*367.20 FL
43	1		*TAILGATE INNER TRIM	Cracked	386.70 FL	*386.70 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*TAILGATE WEATHERSTRIP STRIP	Cut	325.10 FL	*325.10 FL
45	1		*SET TAILGATE WINDSCREEN MOULDING	Necessary	133.70 FL	*133.70 FL
46	1		*TAIL LAMP	O/S Cracked	886.40 FL	*443.20 FL
47	2		*TAIL LAMP SIDE GARNISH	Not Necessary	173.00 FL	*- FL
48	2		*TAIL LAMP LOWER BRACKET	Not Necessary	105.60 FL	*- FL
49	1		*REAR FENDER INNER TRIM	O/S Cracked	773.40 FL	*386.70 FL
50	1		*REAR FENDER COWLING	O/S Torn	369.20 FL	*184.60 FL
51	2		*REAR FENDER ARCED GARNISH	Not Necessary	287.40 FL	*- FL
52	1		*REAR END PANEL	Dented	694.70 FL	*694.70 FL
53	1		*REAR END PANEL TOP GARNISH	Cracked	246.80 FL	*246.80 FL
54	1		*REAR FLOOR PANEL TOP BOARD	Deformed	625.70 FL	*385.00 FL
55	2		*REAR TOOLS SPONGE	Deformed	353.00 FL	*353.00 FL
56	1		*REAR EXHAUST PIPE	Dented	1,478.20 FL	*987.00 FL
57	1		*REAR EXHAUST INSULATOR	Not Necessary	141.70 FL	*- FL
58	6		*REAR EXHAUST MOUNTING	Not Necessary	214.20 FL	*- FL
59	1		*SET REAR EXHAUST GASKET	Necessary	32.10 FL	*32.10 FL
60	1		*FRONT NUMBER PLATE (SPECIAL TYPE)	Cracked	150.00 FS	*60.00 FS
61	1		*SET FRONT BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
62	1		*SET FRONT BUMPER FOGLAMP RING (SPECIAL TYPE)	Not Necessary	380.00 FS	*- FS
63	1		*FRONT BUMPER LED LIGHT (SPECIAL TYPE)	O/S Cracked	450.00 FS	*200.00 FS
64	1		*FRONT BUMPER CHROME MOULDING (SPECIAL TYPE)	Cut	250.00 FS	*150.00 FS
65	1		*REAR BUMPER LED LIGHT (CENTER) (SPECIAL TYPE)	Cracked	300.00 FS	*120.00 FS
66	1		*REAR BUMPER DIFFUSER (SPECIAL TYPE)	Distorted	550.00 FS	*380.00 FS
67	1		*SET REAR BUMPER SIDE LED LIGHT (SPECIAL TYPE)	O/S Cracked	350.00 FS	*200.00 FS
68	1		*SET REAR BUMPER SIDE LED LIGHT COVER (CARBON FIBER) (SPECIAL TYPE)	O/S Cut	480.00 FS	*180.00 FS
69	1		*SET FRONT NUMBER PLATE GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
70	1		*SET FRONT FENDER COWLING CLIPS	Necessary	80.00 FS	*20.00 FS
71	1		*SET FRONT FENDER ARCD GARNISH CLIP	Not Necessary	60.00 FS	*- FS
72	1		*SET GRILLE LOGO GARNISH CLIP	Not Necessary	40.00 FS	*- FS
73	1		*REAR NUMBER PLATE (SPECIAL TYPE)	Not Necessary	150.00 FS	*- FS
74	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
75	1		*REAR BUMPER CENTER CARBON STICKER (SPECIAL TYPE)	Necessary	180.00 FS	*60.00 FS
76	1		*REAR BUMPER CENTER CHROME MOULDING (SPECIAL TYPE)	Bent	380.00 FS	*100.00 FS
77	1		*SET TAIL LAMP CLIP	Necessary	60.00 FS	*20.00 FS
78	1		*SET TAILGATE INNER TRIM BOARD CLIP	Necessary	80.00 FS	*30.00 FS
79	2		*TAILGATE LAMP TOP COVER (CARBON FIBRE) (SPECIAL TYPE)	Necessary	960.00 FS	*50.00 FS
80	1		*TAILGATE OUTER TOP GARNISH (SPECIAL TYPE)	Necessary	450.00 FS	*150.00 FS
81	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
82	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS
83	1		*SET REAR FENDER INNER TRIM CLIP	Necessary	80.00 FS	*30.00 FS
84	1		*SET REAR FENDER INNER COWLING CLIP	Necessary	80.00 FS	*20.00 FS
85	1		*SET REAR END PANEL TOP GARNISH CLIPS	Necessary	30.00 FS	*10.00 FS
86	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
87	1		*REAR END PANEL TOP GARNISH (SPECIAL TYPE)	Not Necessary	550.00 FS	*- FS
88	1		*SET REVERSE SENSOR	Necessary	220.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
89	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*-FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					37,768.70	18,850.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					7,629.68	4,165.00
Total Parts (\$\$)					30,139.02	14,685.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,400.00	300.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,400.00	200.00
3	REFOCUS HEADLAMP BEAM	New	80.00	30.00
4	REMOVE AND RESET MILLIMETER WAVE RADAR	New	120.00	0.00
5	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,600.00	800.00
6	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	1,000.00
7	TUFF COAT	New	250.00	60.00
8	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
9	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	80.00	50.00
10	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	New	80.00	50.00
11	REAR CHASSIS ALIGNMENT	New	250.00	0.00
12	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
13	TRANFER TAILGATE MECHANISM	New	80.00	80.00
14	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
15	REMOVE AND REFIX REAR EXHAUST PIPE	New	180.00	80.00
16	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,870.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >