

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010276/QGA3Q2
Date: 16/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100485217
Claimant Vehicle No :	SLR4582Z	Insured Vehicle No :	SLG5124P
Date of Loss:	19/09/2020	Nature of Claim:	TP
		Claim No:	8795529970SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4582Z		
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Engine No:	P520454561
Reg. Date:	16/08/2017 (Man. Year: 2017)	Chassis No:	JM6BN22A8H0162371
Colour:	Grey	Odometer:	205803 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,632.85	17,774.25	9,858.60	35.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,360.00	3,930.00	2,430.00	38.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	33,992.85	21,704.25	12,288.60	36.15
Approved Total (Overridden) (S\$)		17,000.00		

(S\$)	33,992.85	17,000.00	16,992.85	49.99
+ GST 7.00/7.00% (S\$)	2,379.50	1,190.00	1,189.50	49.99
Nett Amount (S\$)	36,372.35	18,190.00	18,182.35	49.99
+ Loss of Use (16.0 x S\$50.00/day) (S\$)		800.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		18,992.00		

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020

Estimated Period of Repair: 14.0 days

Inspected At:

Lion City Rentals Pte Ltd (HQ)
60 Jalan Lam Huat, #04-35/36 Carros Centre
Singapore 737569

Adjuster: OI SUN PIN**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Crumpled	1,200.40 FL	*1,067.00 FL
2	1		*F/L FENDER	Dented	620.00 FL	*380.00 FL
3	1		*F/L HEADLAMP	Cracked	1,320.00 FL	*980.00 FL
4	1		*F/L FOG LAMP COVER	Serviceable	250.00 FL	*- FL
5	1		*F/L SIGNAL LAMP	Serviceable	180.00 FL	*- FL
6	1		*FRONT BUMPER	Crumpled	1,125.00 FL	*1,125.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Bent	580.00 FL	*480.00 FL
8	2		*FRONT BUMPER RETAINER	Broken	240.00 FL	*240.00 FL
9	1		*FRONT GRILLE NOSE PANEL	Bent	480.00 FL	*480.00 FL
10	1		*FRONT GRILLE BASE	Crumpled	1,400.00 FL	*650.00 FL
11	1		*FRONT GRILLE EMBLEM	Necessary	60.00 FL	*60.00 FL
12	1		*FRONT GRILLE CHROME MOULDING LH	Serviceable	280.00 FL	*- FL
13	1		*FRONT GRILLE CHROME MOULDING RH	Cracked	280.00 FL	*280.00 FL
14	1		*FRONT GRILLE ACCESS LH COVER	Scratched	120.00 FL	*120.00 FL
15	1		*FRONT GRILLE BRACKET LH	Broken	150.00 FL	*110.00 FL
16	1		*FRONT AIR GUIDE	Serviceable	110.00 FL	*- FL
17	1		*FRONT BUMPER LH TOW COVER	Missing	40.00 FL	*40.00 FL
18	1		*FRONT SUPPORT PANEL COMPLETE	Crumpled	520.00 FL	*520.00 FL
19	1		*FRONT SUPPORT PANEL TOP COVER	Crumpled	150.00 FL	*150.00 FL
20	1		*RADIATOR	Crumpled	1,118.50 FL	*1,065.00 FL
21	1		*RADIATOR FAN MOTOR	Jammed	431.80 FL	*431.80 FL
22	1		*RADIATOR FAN BLADE	Crumpled	183.60 FL	*183.60 FL
23	1		*RADIATOR FAN COWLING	Cracked	442.20 FL	*442.20 FL
24	1		*AIR CON CONDENSER	Crumpled	1,116.20 FL	*1,063.00 FL
25	1		*AIR CON CONDENSER FAN MOTOR	Crumpled	431.80 FL	*431.80 FL
26	1		*AIR CON FAN BLADE	Crumpled	186.56 FL	*186.56 FL
27	1		*AIR CON FAN SHROUD	Crumpled	442.20 FL	*442.20 FL
28	1		*PASSENGER AIR BAG	Broken	1,386.30 FL	*1,386.30 FL
29	1		*DASHBOARD	Broken	3,500.00 FL	*1,510.00 FL
30	1		*SIDE IMPACT SENSORS	Necessary	1,259.60 FL	*250.00 FL
31	1		*F/L SAFETY BELT	Jammed	1,274.30 FL	*1,174.00 FL
32	1		*F/R SAFETY BELT	Jammed	1,274.30 FL	*1,174.00 FL
33	1		*F/L SAFETY BELT BUCKLE	Serviceable	293.50 FL	*- FL
34	1		*F/R SAFETY BELT BUCKLE	Serviceable	293.50 FL	*- FL
35	1		*AIR BAG ECU	Necessary	2,808.80 FL	*1,323.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRONT WINDSCREEN GLASS	Broken	3,800.00 FL	*1,141.10 FL
37	1		*FRONT AIR BAG	Broken	3,000.00 FL	*1,785.00 FL
38	1		*FRONT HEADLAMP (RH)	Cracked	1,320.00 FL	*980.00 FL
39	1		*FRONT CLOCK SPRING	Necessary	380.00 FL	*180.00 FL
40	1		*FRONT ENGINE UNDER COVER	Deformed	280.00 FL	*280.00 FL
41	1		*SET FRONT NUMBER PLATE	Missing	50.00 FS	*35.00 FS
42	1		*SET FRONT BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
43	1		*DECAL	Necessary	20.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	34,498.56	22,196.56
- List Item Discount on L Items 20.00/20.00% (S\$)	6,865.71	4,422.31
Total Parts (S\$)	27,632.85	17,774.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO LABOUR CHARGE FOR REMOVING OUT FRONT SUPPORT PANEL ,FRONT BUMPER ,F/L FENDER OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	2,000.00	1,750.00
2	TO RESPRAY FRONT BONNET ,SUPPORT PANEL ,F/L FENDER ,FRONT BUMPER AND F/L DOOR	New	1,800.00	1,200.00
3	TO REMOVE AIR CON SYSTEM OUT TO FACILITATE REPLACEMENT OF DAMAGED PARTS AND INCLUDE VACUUM AND RENEWING AIR CON GAS	New	500.00	80.00
4	TO LABOUR CHARGE FOR REMOVING FRONT WINDSCREEN	New	160.00	120.00
5	TO RESET AND CONFIGURE SRS AIR BAG SYSTEM BACK TO FACTORY SPECIFICATION	New	500.00	100.00
6	TO REMOVE AND INSTALL FRONT DASHBOARD TO FACILITATE REPLACEMENT OF SRS AIR BAG	New	800.00	250.00
7	TO REMOVE AND INSTALL ENGINE ASSY TO FACILITATE REPLACEMENT OF DAMAGED PARTS	New	500.00	380.00
8	TO ALIGN BOTH HEADLAMPS	New	50.00	0.00
9	TOWING FEE	New	50.00	50.00
Gross Labour Cost (\$\$)			6,360.00	3,930.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >