

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 5186J

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LH SLIDING DOOR	BENT / WARPED	1,688.60	1,688.60
1	LH SLIDING DOOR RUBBER	SERVICEABLE	406.10	-
1	LH SLIDING DOOR OUTER HANDLE	SERVICEABLE	106.20	-
1	LH SLIDING DOOR LOCK	TO REPAIR SEE LABOUR	269.60	-
1	LH SLIDING DOOR INNER TRIM	SERVICEABLE	356.20	-
	LESS 25% DISCOUNT		-706.68	-422.15
			2,120.02	1,266.45
	<u>LABOUR</u>			
	CHECK ELECTRICAL WIRINGS.		60.00	15.00
	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF LH SLIDING DOOR LOCK.		580.00	400.00
	SPRAY PAINT ON AFFECTED PORTIONS.		580.00	400.00
	TRANSFER RH DOOR MECHANISMS.		100.00	60.00
	RUST PROOFING ON AFFECTED PORTIONS.		50.00	30.00
			1,370.00	905.00
	GRAND TOTAL		3,490.02	2,171.45

RECOMMENDED COST OF LUMP SUM REPAIRS		1,700.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/FCI20010282/Kqd3e2

KONG SENG CHEONG

**Licensed Appraiser**