

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: [sur@lkkauto.com](mailto:sur@lkkauto.com); [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

# VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CS/AIG20010284/R1QD3E2

**Date:** 10/11/2020

### REFERENCE

Insured/Claimant:	KARTHIK GAJENDRA SUNDAR	Policy No:	1800111894
Date of Loss:	24/09/2020	Nature of Claim:	OD
		Claim No:	0243943577SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME1566Y				
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)		Engine No:	3A92UHG6509	
Reg. Date:	20/09/2018 (Man. Year: 2018)		Chassis No:	MMBSTA13AJH003161	
Colour:	Grey		Odometer:	6978 km	
Engine Capacity:	1193 cc				
Market Value/New Car Price:	S\$54,000.00				
Sum Insured (S\$):	<b>Market Value/New Car Price</b>				

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,711.34	3,693.45	1,017.89	21.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,680.00	4,545.00	1,135.00	19.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>10,391.34</b>	<b>8,238.45</b>	<b>2,152.89</b>	<b>20.72</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	9,791.34	7,638.45	2,152.89	21.99
<b>+ GST 7.00/7.00% (S\$)</b>	685.39	534.69	150.70	21.99
<b>Nett Amount (S\$)</b>	<b>10,476.73</b>	<b>8,173.14</b>	<b>2,303.59</b>	<b>21.99</b>

### INSPECTION

Date of Assignment: 25/09/2020  
Date Inspected: 25/09/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)  
209 Pandan Gardens  
Singapore 609339

Estimated Period of Repair: 8.0 days

**Adjuster:** MOHD RASUL**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*C&C LOGO	Necessary	40.00 FS	*40.00 FS
2	1		*REAR NUMBER PLATE WITH FRAME	Not Necessary	50.00 FS	*- FS
3	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
4	1		*BODY KIT ATTRAGE, TITANLUM GREY, U17	Cracked	1,643.00 FS	*1,643.00 FS
5	1		*FACE, RR BUMPER	Deformed	748.00 FL	*748.00 FL
6	1		*BRACKET.RR BUMPER,RH	Serviceable	28.00 FL	*- FL
7	1		*BRACKET.RR BUMPER,LH	Serviceable	28.00 FL	*- FL
8	1		*PANEL, RR END	Bent	425.00 FL	*425.00 FL
9	1		*WEATHERSTRIP, TRUNK LID	Serviceable	157.00 FL	*- FL
10	1		*PANEL, TRUNK LID	Bent	791.00 FL	*791.00 FL
11	1		*HINGE, TRUNK LID, RH	Serviceable	203.00 FL	*- FL
12	1		*HINGE, TRUNK LID, LH	Serviceable	203.00 FL	*- FL
13	1		*LATCH, TRUNK LID	Serviceable	218.00 FL	*- FL
14	1		*GARNISH, RR END PANEL	Deformed	336.00 FL	*336.00 FL
15	1		*MARK, THREE-DIA	Necessary	69.00 FL	*69.00 FL
16	1		*MARK, ATTRAGE	Necessary	21.00 FL	*21.00 FL
17	1		*TRIM, RR END	Serviceable	66.00 FL	*- FL
18	1		*BOARD, TRUNK ROOM FLOOR	Cracked	195.00 FL	*195.00 FL
19	1		*REFLECTOR	Serviceable	23.00 FL	*- FL
20	1		*REFLECTOR	Serviceable	23.00 FL	*- FL
21	1		*LAMP ASSY, LICENSE PLATE	Serviceable	51.00 FL	*- FL
22	1		*BUZZER, KEYLESS OPERATIO, RR	Serviceable	91.00 FL	*- FL
23	1		*ANT, KEYLESS OPERATION, RR	Serviceable	96.00 FL	*- FL
24	1		*DUCT, RR VENTILATOR	Serviceable	30.00 FL	*- FL
25	1		*COVER, RR VENTILATOR	Serviceable	40.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,595.00</b>	<b>4,288.00</b>
<b>- List Item Discount on L Items 23.00/23.00% (\$\$)</b>	883.66	594.55
<b>Total Parts (\$\$)</b>	<b>4,711.34</b>	<b>3,693.45</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	RENEW REAR BUMPER, REAR END PANEL, REAR AIRDAM, SPOILER BOOTLID, REPAIR REAR FENDER RH & LH	New	2,250.00	1,800.00
2	REMOVE & INSTALL BODY KIT	New	100.00	60.00
3	REMOVE & INSTALL PARKING SENSOR	New	60.00	60.00
4	REMOVE & INSTALL REAR COMPARTMENT TRIMS	New	200.00	120.00
5	SPRAY PAINT FRO REAR AIRDAM, REAR BUMPER, REAR END PANEL, REAR FENDER RH & LH, BOOTLID, SPOILER	New	2,800.00	2,275.00
6	APPLY SEALANT FOR ACCIDENT PORTION	New	120.00	80.00
7	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
8	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,680.00</b>	<b>4,545.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >