

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20010285/R1SD3E2

Date: 09/11/2020

REFERENCE

Insured/Claimant:	LIM JOO YONG	Policy No:	1900247717	
Date of Loss:	24/09/2020	Nature of Claim:	OD	Claim No: 5934420050SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR3113P		
Make & Model:	MITSUBISHI ECLIPSE CROSS, 1.5 CVT S/R (A)	Engine No:	4B40HB0394
Reg. Date:	18/11/2019 (Man. Year: 2019)	Chassis No:	JMAXTGK1WLZ000609
Colour:	Blue	Odometer:	22575 km
Engine Capacity:	1499 cc		
Market Value/New Car Price:	S\$102,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R18	Rear Tyre Size:	225/55 R18
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,928.28	3,854.55	6,073.73	61.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,900.00	2,160.00	2,740.00	55.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,828.28	6,014.55	8,813.73	59.44
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	14,428.28	5,614.55	8,813.73	61.09
+ GST 7.00/7.00% (S\$)	1,009.98	393.02	616.96	61.09
Nett Amount (S\$)	15,438.26	6,007.57	9,430.69	61.09

INSPECTION

Date of Assignment: 25/09/2020
Date Inspected: 29/09/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT NUMBER PLATE WITH FRAME	Bent	50.00 FS	*50.00 FS
2	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
3	1		*PNL, HEADLAMP SUPT, UPR RH	Not Necessary	59.00 FL	*- FL
4	1		*PANEL, HEADLAMP SUPPORT, UPR	Not Necessary	171.00 FL	*- FL
5	1		*PNL, HEADLAMP SUPT, UPR LH	Not Necessary	59.00 FL	*- FL
6	1		*PANEL, HEADLAMP SUPPORT, LWR	Not Necessary	219.00 FL	*- FL
7	1		*PANEL, AIR GUIDE SIDE, RH	Not Necessary	82.00 FL	*- FL
8	1		*PANEL, AIR GUIDE SIDE, LH	Not Necessary	82.00 FL	*- FL
9	1		*CONDENSER ASSY, A/C REFRIGE	Not Necessary	701.00 FL	*- FL
10	1		*LLC 4L	Not Necessary	26.00 FL	*- FL
11	1		*COVER, FR BUMPER GRILLE	Not Necessary	302.00 FL	*- FL
12	1		*GRILLE ASSY, RADIATOR	Not Necessary	484.00 FL	*- FL
13	10		*CLIP, FR BUMPER	Necessary	40.00 FL	*40.00 FL
14	1		*BRKT, F/BMPR T/SIG LAMP, LH	Not Necessary	17.00 FL	*- FL
15	1		*BRKT, F/BMPR T/SIG LAMP, RH	Not Necessary	17.00 FL	*- FL
16	1		*FACE, FR BUMPER	Deformed	714.00 FL	*714.00 FL
17	1		*COVER, FR BUMPER	Cut	380.00 FL	*380.00 FL
18	1		*EXTENSION, FR BUMPER	Scratched	317.00 FL	*317.00 FL
19	1		*LH GARNISH, FR BUMPER SIDE	Cracked	214.00 FL	*214.00 FL
20	1		*RH GARNISH, FR BUMPER SIDE	Cracked	214.00 FL	*214.00 FL
21	1		*LH GARNISH, FR BUMPER SIDE	Not Necessary	73.00 FL	*- FL
22	1		*RH GARNISH, FR BUMPER SIDE	Cracked	77.00 FL	*77.00 FL
23	1		*REINFORCEMENT, FR BUMPER	Serviceable	552.00 FL	*- FL
24	1		*BAR, FR BUMPER GUARD	Not Necessary	100.00 FL	*- FL
25	1		*BRACKET, FR BUMPER SIDE, LH	Not Necessary	18.00 FL	*- FL
26	1		*BRACKET, FR BUMPER SIDE, RH	Not Necessary	18.00 FL	*- FL
27	1		*LH CTR SENSOR, FWD DISTANCE WARNIN	Distorted	329.00 FL	*329.00 FL
28	1		*RH CTR SENSOR, FWD DISTANCE WARNIN	Serviceable	329.00 FL	*- FL
29	1		*LH SENSOR, CORNER CLEARANCE	Serviceable	329.00 FL	*- FL
30	1		*RH SENSOR, CORNER CLEARANCE	Serviceable	329.00 FL	*- FL
31	1		*HEADLAMP ASSY, LH	Serviceable	1,976.00 FL	*- FL
32	1		*HEADLAMP ASSY, RH	Cracked	1,976.00 FL	*1,976.00 FL
33	1		*LAMP A, T/SIG & FOG, FR LH	Not Necessary	506.00 FL	*- FL
34	1		*LAMP A, T/SIG & FOG, FR RH	Not Necessary	506.00 FL	*- FL
35	1		*FRONT BUMPER GARNISH	Cut	384.00 FL	*384.00 FL
36	1		*FRONT CORNER EXTENSION	Serviceable	238.00 FL	*- FL
37	1		*FENDER, FR RH	Repair	599.00 FL	*- FL
38	1		*PAD, FR FENDER	Not Necessary	57.00 FL	*- FL
39	1		*REINFORCEMENT, FR BUMPER	Bent	235.00 FL	*235.00 FL
40	1		*REINF, FR BUMPER SIDE, RH	Bent	35.00 FL	*35.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	12,864.00	4,985.00
- List Item Discount on L Items 23.00/23.00% (\$\$)	2,935.72	1,130.45
Total Parts (\$\$)	9,928.28	3,854.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, REPAIR RH FRONT DOOR	New	2,250.00	900.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	REMOVE AND INSTALL A/CON CONDENSER AND RADIATOR TO FACILITATE REPAIR WORK	New	100.00	0.00
4	TOP UP AIR CON GAS AND CHECK A/CON SYSTEM	New	80.00	0.00
5	PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BUMPER FACE, RH FRONT FENDER, LH FRONT FENDER, RH FRONT DOOR AND AFFECTED PORTION	New	2,100.00	1,050.00
6	PERFORM RUST PREVENTION	New	80.00	0.00
7	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
8	APPLY BODY SEALANT	New	80.00	0.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
Gross Labour Cost (S\$)			4,900.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >