Adjuster Report Page 1 of 3

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010295/ATD3Q2

**Date:** 01/12/2020

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900002139

Claimant
Vehicle No: GBF1151K

GBF1151K

Insured Vehicle No: SMG545D

Date of Loss: 21/09/2020 Nature of Claim: TP Claim No: 8992660579SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBF1151K

 Make & Model:
 TOYOTA DYNA, 3.0 D (M)
 Engine No:
 1KD2607302

 Reg. Date:
 30/06/2016 (Man. Year: 2016)
 Chassis No:
 KDY2318024454

 Colour:
 Silver
 Odometer:
 100922 km

Engine Capacity: 2982 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195R15C Rear Tyre Size: 165R13C
Front Left Side: KAPSEN 6 mm Rear Left Side: SUNFULL 6 mm
Front Right Side: KAPSEN 6 mm Rear Right Side: SUNFULL 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,073.00	2,854.65	3,218.35	52.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	1,160.00	1,040.00	47.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,273.00	4,014.65	4,258.35	51.47
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	8,273.00	3,200.00	5,073.00	61.32

**INSPECTION** 

Date of Assignment: 24/09/2020

Date Inspected: 25/09/2020 Inspected At: Flying High Spray Painting (HQ)

BLK 1 Kaki Bukit Ave 6, #01-29 Auto

Bay

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NUMBER PLATE BRACKET	Not Necessary	175.20 F	*- FL
2	1		*REAR CROSS MEMBER	Not Necessary	748.10 F	*- FL
3	2		*TAILLAMP	N/s Cracked/O/s Cut	570.60 F	*570.60 FL
4	1		*TAILLAMP PANEL	N/s Bent	238.60 F	*119.30 FL
5	1		*TAILGATE	Dented	1,588.00 F	*1,588.00 FL
6	1		*TAILGATE HINGE (4 Pcs)	Bent (2 Pcs only)	304.80 F	*152.40 FL
7	1		*TAILGATE SIDE LOCK	N/s Bent	196.20 F	*98.10 FL
8	1		*TAILGATE LOWER PANEL	Repair	545.10 F	*- FL
9	1		*TAILGATE LOWER PANEL REFLECTOR	N/s Cut	130.00 F	*65.00 FL
10	1		*TOYOTA STICKER	Necessary	189.00 F	*189.00 FL
11	1		*STOPPER	N/s Cut	92.00 F	*46.00 FL
12	1		*STOPPER BRACKET	N/s Bent	475.20 F	*237.60 FL
13	1		*TAILLAMP LOWER REFLECTOR	N/s Cut	100.00 F	*50.00 FL
14	1		*REAR TOOL BOX	Bent	410.20 F	*410.20 FL
15	1		*REAR NUMBER PLATE	Not Necessary	30.00 FS	*-FS
16	1		*REAR STEP BRACKET	Bent	250.00 FS	*180.00 FS
17	1		*70KM/H STICKER	Necessary	15.00 FS	*15.00 FS
18	1		*13 PAX STICKER	Necessary	15.00 FS	*15.00 FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	'		
				Sub Total (S\$)	<b>6,073.00</b> 0.00	3,736.20
	- List Item Discount on L Items 0.00/25.00% (S\$)					881.55
				Total Parts (S\$)	6,073.00	2,854.65

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,000.00	450.00
3	WIRING	New	50.00	30.00
4	TO APPLY TUFF COAT	New	150.00	80.00
		Gross Labour Cost (S\$)	2,200.00	1,160.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.