

(08/11/13) Wef

ASS. REC. BY: *marcus*

REF:

CC6/PC120010297/UK93

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBD8959L
Mockwa

at Workshop m/s

of

Insured:

SHD 4979J

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value:

406.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

6752

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBD8959L

Yr Regn:

7 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *(M)*

Make:

Toyota hiace

C.C

2982

Colour

silver

A/C:

Insured / Std / NI / NA

Sp. Reading

248880

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT02P800162244

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

23/9/20

D.O.I.

19/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

015 P.t

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*MV 40.000**17A 24453**NV 15547**After repair photo?**5/11/20 4/5 * 3500 conf. with Angs.*

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

LKK : Khanchone

TO : 201311675Z

JESSIE CATERING PTE LTD
NO 3015 BEDOK NORTH STREET 5
#04-09 SHIMEI EAST KITCHEN
SINGAPORE 486350
TEL : 62464644 (Michelle) FAX : 62464544
PH : 96950827 (BOSS JIMMY)
ATTN :

Not Authorized
N/A
L/S # 3500/
H day 5.
19/10/20
To help Mr. Arthur repair

ESTIMATE BILL

Number : EB00005534
Date : 24/09/2020
Case No : AD00011322
Vehicle No : GBD8959L
Chassis : JTFHT02P800162244
Year of Mfr : 2015
Policy No :
Model : TOYOTA HIACE 3.0
M

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	541.20	25	405.90
2	FRONT BUMPER RETAINER RH	1.0	142.80	25	107.10
3	HEADLAMP RH	1.0	744.00	25	558.00
4	FRONT CORNER PANEL RH	1.0	268.40	25	201.30
5	FRONT DOOR RH	1.0	1,887.10	25	1,415.33
6	FRONT DOOR HINGE TOP RH	1.0	110.00	25	82.50
7	FRONT DOOR HINGE BOTTOM RH	1.0	110.00	25	82.50
8	FRONT DOOR PILLAR RH	1.0	434.20	25	325.65
9	FRONT DOOR RUBBER RH	1.0	230.10	25	172.58
10	FRONT STEP PANEL GARNISH RH	1.0	161.90	25	121.43
11	FRONT STEPPANEL RH	1.0	54.40	25	40.80
12	FRONT DOOR INNER LOCK RH	1.0	578.00	25	433.50
13	FRONT GRILLE TOP	1.0	568.60	25	426.45
14	FRONT GRILLE BOTTOM	1.0	221.70	25	166.28
15	FRONT BUMPER LOWER GRILLE	1.0	178.10	25	133.58
16	FRONT DOOR POWER WINDOW REGULATOR RH	1.0	704.80	25	528.60
17	FRONT DOOR POWER WINDOW REGULATOR MOTOR RH	1.0	704.80	25	528.60
List Price - Parts Sub Total					5,730.10
18	FRONT DOOR COMPANY DETAIL LOGO RH	1.0	30.00	0	30.00
19	FRONT FLOOR BOARD PANEL RH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					30.00
Parts Total					5,760.10
20	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
21	SPRAY PAINT ON THE AFFECTED AREAS	1.0	700.00	0	700.00
22	ANTI-RUST COATING	1.0	150.00	0	150.00
23	WIRING	1.0	40.00	0	40.00
24	TO REMOVE & REFIT DASHBOARD	1.0	250.00	0	250.00
25	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	180.00
Labour 1 Sub Total					2,220.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

Acknowledged by Repairer

Signature:

Date:

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

P- 4228-60
25%
343.95
4593.95

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 201311675Z

JESSIE CATERING PTE LTD
NO 3015 BEDOK NORTH STREET 5
#04-09 SHIMEI EAST KITCHEN
SINGAPORE 486350
TEL : 62464644 (Michelle) FAX : 62464544
PH : 96950827(BOSS JIMMY)
ATTN :

ESTIMATE BILL

Number : EB00005563
Date : 03/11/2020
Case No : AD00011322
Vehicle No : GBD8959L
Chassis : JTFHT02P800162244
Year of Mfr : 2015
Policy No :
Model : TOYOTA HIACE 3.0
M

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	AIR CLEANER 645.10	1.0	649.70	25	487.28
List Price - Parts Sub Total					487.28
Parts Total					487.28
SINGAPORE DOLLARS : FIVE HUNDRED TWENTY-ONE AND CENTS THIRTY-NINE ONLY					
Less Excess					0.00
SUBTOTAL					487.28
GST 7.00%					34.11
TOTAL					521.39

Date of accident : 23/09/2020 01:40 PM. Place : LITTLE ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST