

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010298/T1BA3Q2

Date: 16/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800135302

Claimant
Vehicle No : SHD7091A **Insured Vehicle No :** SKR2958Z

Date of Loss: 24/09/2020 Nature of Claim: TP Claim No: 1504587524SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD7091A	Engine No:	2ZRR958667
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU803536935
Reg. Date:	11/11/2016 (Man. Year: 2016)	Odometer:	540597 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,636.65	3,869.92	766.73	16.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,280.00	940.00	340.00	26.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	5,916.65	4,809.92	1,106.73	18.71
Approved Total (Overridden) (\$)		3,850.00		
(S\$)	5,916.65	3,850.00	2,066.65	34.93
+ GST 7.00/7.00% (S\$)	414.17	269.50	144.67	34.93
Nett Amount (S\$)	6,330.82	4,119.50	2,211.32	34.93
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$125.40/day) (S\$)		376.20		
(S\$)		4,645.70		
Liabile Amount (50.00%) (S\$)		2,322.85		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,324.85		
Global Sum Settlement (S\$)		2,300.00		

INSPECTION

Date of Assignment: 24/09/2020

Date Inspected: 24/09/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd
(Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	499.90 FL	*499.90 FL
2	1		*FRT BUMPER SIDE BRKT LH	Not Necessary	77.00 FL	*- FL
3	1		*HEADLAMP LH	Cut	3,455.00 FL	*3,455.00 FL
4	1		*FOGLAMP LH	Cut	920.00 FL	*920.00 FL
5	1		*FRT FENDER LH	Repair	945.30 FL	*- FL
6	1		*FRT FENDER (HYBRID)LH	Necessary	86.50 FL	*86.50 FL
7	1		*FRT FENDER SHIELD LH	Torn	198.50 FL	*198.50 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,182.20	5,159.90
- List Item Discount on L Items 25.00/25.00% (\$)	1,545.55	1,289.98
Total Parts (\$)	4,636.65	3,869.92

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	700.00	480.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	CHECK ALL LIGHTING	New	40.00	30.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	30.00
Gross Labour Cost (\$\$)			1,280.00	940.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >