LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG20010303/QTD3E2

Date: 15/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900235439

Claimant Vehicle SMB3140U Insured Vehicle No: SFX8682G

No: SIVIDS 1400 Insured Vehicle No . SPA00029

Date of Loss: 28/08/2020 Nature of Claim: TP Claim No: 1410165708SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB3140U

 Make & Model:
 MAN NL320F (A22), 10.5 D ABS TURBO (A)
 Engine No:
 50339912063991

 Reg. Date:
 02/11/2015 (Man. Year: 2014)
 Chassis No:
 WMAA22ZZ8F7002688

Colour: Multi-colour Odometer: 367231 km

Engine Capacity: 10518 cc
Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5 Rear Tyre Size: 275/70 R22.5 (D)
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6/6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6/6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|------------------------|------------|------------|------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 650.00 | 458.00 | 192.00 | 29.54 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 650.00 | 458.00 | 192.00 | 29.54 |
| + GST 7.00/7.00% (S\$) | 45.50 | 32.06 | 13.44 | 29.54 |
| Nett Amount (S\$) | 695.50 | 490.06 | 205.44 | 29.54 |

INSPECTION

Date of Assignment: 24/09/2020

SBS Transit Ltd (YCK)

Date Inspected: 29/09/2020 Inspected At: 3 Yio Chu Kang Crescent

Singapore 786010

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|------------|----------------------------------|------------------------------------|------------|--------|
| <u>Lab</u> | <u>our Items</u> | | | |
| 1 | SPRAY PAINT GREEN | New | 8.00 | 8.00 |
| 2 | CONTRACTOR LABOUR COST | New | 450.00 | 450.00 |
| 3 | WORKSHOP ADMIN COST | New | 192.00 | 0.00 |
| 4 | LIVERY / ADVERTISMENT COST (NPA) | New | 0.00 | 0.00 |
| 5 | 5 TOWING COST (NPA) | New | 0.00 | 0.00 |
| | | Gross Labour Cost (S\$) | 650.00 | 458.00 |
| | Report was | unsubmitted during this print-out. | | |

< END OF ESTIMATES >