

Accident Repair Estimate

Accident Date:

Bus Registration Number:SMB3140U

Accident Time:

Bus Type:MAN A22

Accident Report Number

Date of Survey:

3rd Party Claim against:

Section A

Parts and Material Cost			
Parts or Item Description	Price	Quantity	Total Cost
SPRAY PAINT GREEN	8	\$ 1.00	\$ 8.00
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
			\$ -
		Total Parts & Material Cost	\$ 8.00

Section B

Assessment/Repair/Spray paint (labour Cost)		
Contractor Labour Cost		\$ 450.00
Workshop Admin Cost		\$ X 192.00
Livery/Advertisement Cost		
Towing Cost		\$ -
	Total Labour Cost	\$ 642.00

Section C

Summary		
	Total Cost	\$ 650.00

Sun Pin (CHK)
08/04/2021
DOI: 29/09/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- **Parts** prices are subject to confirmation
- **Third party** survey is on a "Without Prejudice" basis
- No **illegal modification(s)** is allowed
- **Supplementary item(s)** must be resurveyed and is subject to **final approval** from Insurance Company

Acknowledged by Repairer

Signature:

Date: