

ASS. REG. BY:

Steve

REF:

CS/AIG 20010314/13

ASSIGNMENT

From:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S

Sal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Turn Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SMF 5857B

Yr Regn:

19/11/18

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Atrage

C.C.

1193

Colour:

Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

13102

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MM B5TA13AJH 004336

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orModl: ☒ NII / ☐ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

185/55R15

R:

11

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

24/9/20

D.O.A.

28/9/20

Survey held at

Cycle & carriage

Des. of Damages: ☐ Frt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ U/C / ☐ Rooftop or

Front LH.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

New car Price 70K

MK-53K

Date/Time, File Pass to?

☐

: Prelim. Report

☐

: Final Report

Date/Time, File Return to?

3)

Rep. Forms:

Lump Sum / L.E.B.:

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Insp (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/09/2020/ 15:50	QUD	247 / DonBong	57779			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								4050.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, 1/2							2250	
FRONT BONNET, LH FRONT FENDER, LH FRONT DOOR, FRONT BODY KIT								
LH SIDE SKIRTING, CUT/WELD LH FRONT CHASSIS MEMBER,								
REPAIR RH FRONT FENDER 1/2								
E PNT88000								100.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER								
TO FACILITATE REPAIR WORK								
A 55900099								80.00
TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								
A PNT88100								1000.00
TO MOUNT VEHICLE ON CELETTE BENCH TO CONDUCT CHASSIS ALIGNMENT								
A 54900099								30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
A 54900099								250.00
TO CARRY OUT REPAIR ELECTRICAL HARNESS								
M SUNDRY								160.00
APPLY BODY SEALANT								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								120.00
PERFORM RUST PREVENTION								
E PNT98000								4200.00
PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET,								
FRONT BUMPER, FRONT BODY KIT, LH FRONT FENDER, LH FRONT DOOR,								
RH FRONT FENDER, LH FRONT A PILLAR, LH SIDE SKIRTING PANEL,								
LH CHASSIS MEMBER, LH FENDER HOUSING AND AFFECTED PORTION								
A 33900099								450.00
RENEW FRONT U/CARRIAGE DAMAGES								
A WHEELALIGNMENTBP								120.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								380.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 1977014696

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
KAX00008	Credit	25/09/2020/ 15:50	QUD	247 / DonBong	57779				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount	
SUPPLY LH FRONT TIRE								30.00	
M	SUNDRY								
LABOUR RENEW LH FRONT TIRE INCLUDING BALANCING								120.00	
E	PNT88000								
REMOVE AND TRANSFER LH FRONT DOOR GLASS, TRIM AND OTHERS ATTACHMENT TO NEW DOOR PANEL								450.00	
A	11900199								
REMOVE AND INSTALL ENGINE TO FACILITATE REPAIR WORK								50.00	
M	SUNDRY								
SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00	
M	SUNDRY								
SUNDRIES									
M	FACE,FR BUMPER	/ 2R			1.00	703.00	23.00	541.31	
M	COVER,HEADLAMP SUPT PANEL	/ CH			1.00	62.00	23.00	47.74	
M	GRILLE,FR UNDER	/ BR			1.00	165.00	23.00	127.05	
M	BRACKET,FR BUMPER,LH	/ BR			1.00	13.00	23.00	10.01	
M	BRACKET,FR BUMPER,RH	/ BR			1.00	13.00	23.00	10.01	
M	GARNISH,FR BUMPER,LH	/ MIS			1.00	127.00	23.00	97.79	
M	MARK,THREE-DIA	/ MC			1.00	69.00	23.00	53.13	
M	GRILLE,RADIATOR	/ BR			1.00	554.00	23.00	426.58	
M	HOOD	/ DD			1.00	734.00	23.00	565.18	
M	HINGE,HOOD,LH	/ BT			1.00	56.00	23.00	43.12	
M	HINGE,HOOD,RH	/ BT			1.00	56.00	23.00	43.12	
M	INSULATOR,HOOD	/ CR4			1.00	177.00	23.00	136.29	
M	CLIP,HOOD INSULATOR	/ MC			8.00	3.00	23.00	18.48	
M	LATCH,HOOD	/ BT			1.00	69.00	23.00	53.13	
M	FENDER,FR LH	/ DD			1.00	497.00	23.00	382.69	
M	SHIELD,FR WHEELHOUSE,LH	/ MIS			1.00	98.00	23.00	75.46	
M	CLIP,INNERSHIELD	/ MC			13.00	4.00	23.00	40.04	
M	GARNISH,FR PILLAR,LH	/ MIS			1.00	30.00	23.00	23.10	
M	GARNISH,FR FENDER	/ MIS			1.00	65.00	23.00	50.05	
M	WHEELHOUSE,FR INR LH	/ X R			1.00	364.00	23.00	280.28	
M	PANEL ASSY,FR END	/ X R			1.00	1055.00	23.00	812.35	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	25/09/2020/ 15:50	QUD	247 / DonBong	57779			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	PANEL, HEADLAMP SUPPORT, UPR	X K			1.00	65.00	23.00	50.05
M	SIDEMEMBER ASSY, FR LH	X R			1.00	497.00	23.00	382.69
M	EMBLEM ECO	MC			1.00	17.00	00.00	17.00
M	PANEL, AIR GUIDE, LH	?			1.00	11.00	23.00	8.47
M	COVER, ENG ROOM UNDER, FR	?			1.00	99.00	23.00	76.23
M	PANEL ASSY, FR DOOR, LH	DO			1.00	996.00	23.00	766.92
M	HINGE, FR DOOR, UPR LH	X			1.00	54.00	23.00	41.58
M	HINGE, FR DOOR, LWR LH	X			1.00	54.00	23.00	41.58
M	TAPE, FR DOOR SASH, LH	MC			1.00	29.00	23.00	22.33
M	COVER, FR DECK, LH	?			1.00	16.00	23.00	12.32
M	BODY KIT, ATTRAGE	OR			1.00	1643.00	00.00	1643.00
M	CONDENSER ASSY, A/C REFRIGE	X			1.00	758.00	23.00	583.66
M	PANEL, AIR GUIDE	X			1.00	112.00	23.00	86.24
M	RADIATOR ASSY	X			1.00	967.00	23.00	744.59
M	TANK ASSY, RADIATOR COND	X			1.00	42.00	23.00	32.34
M	FAN, COOLING, LH	X			1.00	77.00	23.00	59.29
M	SHROUD, COOLING FAN	X			1.00	130.00	23.00	100.10
M	MOTOR, COOLING FAN	X			1.00	479.00	23.00	368.83
M	LLC 4L	X			1.00	26.00	23.00	20.02
M	HEADLAMP ASSY, LH	OR			1.00	660.00	23.00	508.20
M	HEADLAMP ASSY, RH	OR			1.00	660.00	23.00	508.20
M	LAMP ASSY, FOG, FR LH	CUT			1.00	303.00	23.00	233.31
M	BOX ASSY, RELAY	OR			1.00	139.00	23.00	107.03
M	COVER, RELAY BOX	CUT			1.00	64.00	23.00	49.28
M	INSULATOR, ENG MOUNTING	?			1.00	203.00	23.00	156.31
M	INSULATOR, T/M MOUNTING	?			1.00	209.00	23.00	160.93
M	ROD ASSY, ENG ROLL STOPPER	?			1.00	155.00	23.00	119.35
M	CROSSMEMBER, FR AXLE, NO.1	?			1.00	864.00	23.00	665.28
M	ARM ASSY, FR SUSP, LWR LH	?			1.00	337.00	23.00	259.49
M	STRUT, FR SUSP	?			1.00	452.00	23.00	348.04
M	DAMPER, FR SUSP STRUT	?			1.00	24.00	23.00	18.48
M	PAD, FR SUSP SPRING	?			1.00	17.00	23.00	13.09
M	SEAT, FR SUSP SPRING, UPR	?			1.00	37.00	23.00	28.49

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or by bank transfer. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /TAN YONG JIAN (CHEN YONGJIAN) Reg No/Reg Date SMF5857B / 19/11/201 Date In/Mileage / 13102 Chassis No MMBSTA13AJH004336 Engine No 3A92UHK0571 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim T06 MEDIUM BLUE MIC/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	25/09/2020/ 15:50	QUD	247 / DonBong	57779

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BEARING,FR SUSP STRUT	1.00	9.00	23.00	6.93
M SUPPORT,FR SUSP STRUT	1.00	17.00	23.00	13.09
M INSULATOR,FR SUSP STRUT	1.00	83.00	23.00	63.91
M INSULATOR,FR SUSP STRUT	1.00	98.00	23.00	75.46
M NUT,CYLINDER BLOCK	1.00	3.00	23.00	2.31
M STOPPER,FR SUSP STRUT	1.00	27.00	23.00	20.79
M KNUCKLE,LH	1.00	365.00	23.00	281.05
M COVER,FR BRAKE DISC	1.00	26.00	23.00	20.02
M BEARING,FR WHEEL HUB	1.00	121.00	23.00	93.17
M SNAP RING,FR WHEEL HUB	1.00	8.00	23.00	6.16
M HUB ASSY,FR WHEEL	1.00	215.00	23.00	165.55
M GEAR & LINK ASSY,STEERING	1.00	1444.00	23.00	1111.88
M END ASSY,TIE ROD	1.00	52.00	23.00	40.04
M END ASSY,TIE ROD	1.00	52.00	23.00	40.04
M WHEEL,DISC / C41 (F4 LH)	1.00	687.00	23.00	528.99
M SENSOR,FR ABS / TN	1.00	171.00	23.00	131.67

SURVEYOR NAME: Steve CLKK 8322 8813

SURVEYOR SIGNATURE: _____

DATE: 28/9/20, 12:00 pmREMARKS: PIP, Rej Before SprayOO - Nit AnthrimeEXCISI - ?14 days

Like this, Consurveys to be notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Authorized signatory and company stamp

Is subject to final approval from Insurance Company

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

	Nett	26,430.69
7% GST on	26430.69	1850.15
Total Payable		28,280.84