

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20010319/T1ES3Q2

Date: 22/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993863
<b>Claimant Vehicle No :</b>	SLV4243G	<b>Insured Vehicle No :</b>	SLQ2947Z
Date of Loss:	25/09/2020	Nature of Claim:	TP
		Claim No:	8784032890SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLV4243G</b>	Engine No:	38545119B38B15A
Make & Model:	BMW 318i, 1.8 (A)	Chassis No:	WBA8E36050NU82400
Reg. Date:	28/12/2017 (Man. Year: 2017)	Odometer:	17932 km
Colour:	White		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	225/50R17	Rear Tyre Size:	225/50R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,124.35	2,253.30	1,871.05	45.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,969.00	5,453.00	2,516.00	31.57
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>12,093.35</b>	<b>7,706.30</b>	<b>4,387.05</b>	<b>36.28</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	846.53	539.44	307.09	36.28
<b>Nett Amount (\$\$)</b>	<b>12,939.88</b>	<b>8,245.74</b>	<b>4,694.14</b>	<b>36.28</b>
<b>+ Car Rental (8.0 x \$80.00/day + 7.00% GST) (\$\$)</b>		684.80		
<b>+ Doc/Search Fee (\$\$)</b>		7.45		
<b>Nett Liability (\$\$)</b>		<b>8,937.99</b>		

### INSPECTION

Date of Assignment:	12/10/2020	Performance Motors Limited (Alexandra)
Date Inspected:	12/10/2020 Inspected At:	303 Alexandra Road, Sime Darby Performance Centre
Estimated Period of Repair:	6.0 days	Singapore 159941

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*SUNDRIES</b>	Necessary	150.00 FS	*80.00 FS
2	2		<b>*PLUG -IN RETAINER</b>	Not Necessary	1.70 FS	*- FS
3	10		<b>*EXPANDING NUT</b>	Necessary (2 PCS ONLY)	9.50 FS	*4.20 FS
4	1		<b>*FRT RH DOOR</b>	Bent	1,273.85 FS	*1,273.85 FS
5	1		<b>*FRT RH SIDE PANEL</b>	Bent	702.65 FS	*702.65 FS
6	1		<b>*FRT RH 2 SIDE PANEL BRACKET</b>	Not Necessary	35.10 FS	*- FS
7	1		<b>*FRT RH 1 SIDE PANEL BRACKET</b>	Not Necessary	35.10 FS	*- FS
8	1		<b>*FRT RH 3 SIDE PANEL BRACKET</b>	Not Necessary	35.10 FS	*- FS
9	1		<b>*RH UPPER FRONT DOOR HINGE</b>	Repai	56.30 FS	*- FS
10	1		<b>*RH LOWER FRT DOOR HINGE</b>	Repair	56.30 FS	*- FS
11	1		<b>*MODEL DESIGNATION LETTERING SIDE (L)</b>	Necessary	46.55 FS	*46.55 FS
12	10		<b>*RIVET</b>	Necessary (3 PCS ONLY)	5.00 FS	*1.50 FS
13	1		<b>*RETAINING RING BLACK GRAINED RH</b>	Not Necessary	53.45 FS	*- FS
14	1		<b>*HOUSING LOWER SECTION RH (GENARBT)</b>	Not Necessary	43.90 FS	*- FS
15	1		<b>*RH HEATED OUTSIDE MIRROR</b>	Repair	865.35 FS	*- FS
16	1		<b>*FRT RH DOOR BRAKE</b>	Not Necessary	77.60 FS	*- FS
17	1		<b>*FRT DOOR WEATHERSTRIP</b>	Necessary	141.40 FS	*141.40 FS
18	1		<b>*FRT RH SEALING WINDOW FRAME INTERIO</b>	Not Necessary	61.45 FS	*- FS
19	1		<b>*GASKET ,RAIL</b>	Not Necessary	6.95 FS	*- FS
20	1		<b>*FRT RH DOOR WINDOW GUIDE</b>	Not Necessary	122.90 FS	*- FS
21	1		<b>*FRT RH DOOR OUTER CHROM</b>	Not Necessary	106.75 FS	*- FS
22	1		<b>*FRT RH WHEEL HOUSING COVER</b>	Not Necessary	117.15 FS	*- FS
23	1		<b>*RH COVER BOTTOM</b>	Not Necessary	117.15 FS	*- FS
24	3		<b>*EXPANDING NUT 7X7 MM</b>	Necessary	3.15 FS	*3.15 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>4,124.35</b>	<b>2,253.30</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE RIGHT FRONT SIDE FENDER ,RIGHT FRONT DOOR INCLUDE REMOVE ATTACHMENT ETC AND REPAIR FRONT BUMPER	New	3,400.00	2,125.00
2	SPRAY PAINTING FRONT BUMPER ,RIGHT FRONT FENDER ,FRONT RIGHT DOOR ,RIGHT LOWER SIDE SKIRTING AND RIGHT MIRROR COVER	New	3,625.00	2,527.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (2 PANEL)	New	236.00	200.00
4	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDING CONDUCT CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION (1 DOOR)	New	531.00	451.00
5	TO CONDUCT CHECKS ON ALL DOORS AND BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			<b>7,969.00</b>	<b>5,453.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >