

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010321/GRA3Q2

Date: 29/03/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800117036
<b>Claimant Vehicle No :</b>	SMJ6838D	<b>Insured Vehicle No :</b>	SME5272T
Date of Loss:	24/09/2020	Nature of Claim:	TP
		Claim No:	7097266983SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMJ6838D</b>		
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Engine No:	L15B5564872
Reg. Date:	15/03/2019 (Man. Year: 2018)	Chassis No:	RU11314860
Colour:	Blue	Odometer:	30572 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,945.56	2,409.00	536.56	18.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,940.00	920.00	1,020.00	52.58
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>4,885.56</b>	<b>3,329.00</b>	<b>1,556.56</b>	<b>31.86</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	<b>341.99</b>	<b>233.03</b>	<b>108.96</b>	<b>31.86</b>
<b>Nett Amount (\$\$)</b>	<b>5,227.55</b>	<b>3,562.03</b>	<b>1,665.52</b>	<b>31.86</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (\$\$)</b>		240.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>3,804.03</b>		

### INSPECTION

Date of Assignment:	25/09/2020	Ah Lim Motor Company (AMK) 10 Ang Mo Kio Industrial Park 2A, #01-09 AMK Autopoint Singapore 568047
Date Inspected:	29/09/2020 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: XING GUO QIANG

Manager: Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING TOP ,SIDE LH & RH & LOWER	Necessary	120.00 FL	*120.00 FL
2	1		*TAILGATE	Buckled	1,050.00 FL	*1,050.00 FL
3	1		*TAILGATE EMBLEM	Not Necessary	15.70 FL	*- FL
4	1		*TAILGATE INNER LOCK	Jammed	157.10 FL	*157.10 FL
5	1		*TAILGATE RUBBER	Not Necessary	92.30 FL	*- FL
6	1		*TAILGATE INNER TRIMBOARD	Not Necessary	153.40 FL	*- FL
7	1		*REAR BUMPER	Deformed	508.50 FL	*508.50 FL
8	2		*REAR BUMPER SIDE RETAINERS LH & RH	Not Necessary	35.00 FL	*- FL
9	10		*REAR BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
10	2		*REAR BUMPER REFLECTOR LH& RH	Not Necessary	282.00 FL	*- FL
11	1		*END PANEL	Buckled	411.90 FL	*411.90 FL
12	1		*END PANEL TOP GARNISH	Not Necessary	92.30 FL	*- FL
13	2		*REVERSE SENSOR	Not Working	200.00 FS	*200.00 FS
14	1		*INNER SEAL	Necessary	20.00 FS	*20.00 FS
15	1		*SEALANT	Necessary	40.00 FS	*40.00 FS
16	1		*REAR BUMPER LOWER SPOILER	Cut	200.00 FS	*200.00 FS
17	1		*REAR BUZZER ASSY SMART	Damaged	110.00 FL	*110.00 FL
18	1		*NUMBER PLATE	Necessary	35.00 FS	*35.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>3,558.20</b>	<b>2,887.50</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	612.64	478.50
<b>Total Parts (S\$)</b>	<b>2,945.56</b>	<b>2,409.00</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO ARRANGE ,SUPPLY AND SEAL OFF PEAK CAR REGISTRATION PLATE INCLUDING INSPECTION FEES BY THE LAND TRANSPORT AUTHORITY	New	60.00	60.00
2	TO DISCONNECT AND CHECK ELECTRICAL WIRING WIRE SOCKETS AND ETC .TO REMOVE AND REINSTALL ALL DAMAGED ELECTRICAL UNITS ,TEST AND RECTIFY FOR PROPER FUNCTIONING	New	40.00	0.00
3	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR WINDSCREEN	New	120.00	120.00
4	TO REMOVE AND REINSTALL /REPLACE FRONT /REAR BUMPER SENSORS	New	60.00	40.00
5	TO SPRAY ANTI-RUST COATING ON AFFECTED AREAS	New	60.00	0.00
6	TO DISMANTLE ALL DAMAGED PARTS ,TO KNOCK & REPAIR AND PANEL ,SPARE TYRE PANEL ,INNER PANELS AND AFFECTED AREAS TO REFIT LISTED PARTS BACK SAME	New	800.00	400.00
7	TO SPRAY TAILGATE ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL	New	800.00	300.00
Gross Labour Cost (S\$)			<b>1,940.00</b>	<b>920.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >