

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20010338/AVF3E2
Date: 04/03/2021

REFERENCE

Insured/Claimant: TEO GUAT THOE Policy No: 1900150922
Date of Loss: 23/09/2020 Nature of Claim: OD Claim No: 5183782497SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKA8208E**
Make & Model: AUDI Q5 SPORT, 2.0 TFSI QU S TRONIC (A) Engine No: DAX058529
Reg. Date: 30/08/2019 (Man. Year: 2019) Chassis No: WAUZZZF1K2125852
Colour: Black Odometer: 8258 km
Engine Capacity: 1984 cc
Market Value/New Car Price: S\$170,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/55 R19 Rear Tyre Size: 235/55 R19
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,449.00	7,182.32	7,266.68	50.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,552.00	4,222.00	4,330.00	50.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,001.00	11,404.32	11,596.68	50.42
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	22,501.00	10,904.32	11,596.68	51.54
+ GST 7.00/7.00% (S\$)	1,575.07	763.30	811.77	51.54
Nett Amount (S\$)	24,076.07	11,667.62	12,408.45	51.54

INSPECTION

Date of Assignment: 28/09/2020
Date Inspected: 25/09/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR LH	Repair	3,118.00 FS	*- FS
2	1		*FRONT DOOR OUTER LH	Not Necessary	203.00 FS	*- FS
3	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
4	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
5	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
6	1		*FRONT DOOR CATCH LH	Not Necessary	144.00 FS	*- FS
7	1		*FRONT WING MIRROR MOUNT LH	Cut	1,730.00 FS	*1,384.00 FS
8	1		*FRONT WING MIRROR CAP LH	Not Necessary	467.00 FS	*- FS
9	1		*FRONT WING MIRROR GLASS LH	Shattered	1,606.00 FS	*1,284.80 FS
10	1		*FRONT DOOR COVER LH	Not Necessary	781.00 FS	*- FS
11	1		*FRONT WINDOW SLOT SEAL LH	Cut	609.00 FS	*486.80 FS
12	1		*FRONT DOOR WINDOW LH	Cut	295.00 FS	*235.60 FS
13	1		*REAR DOOR LH	Dented	3,118.00 FS	*2,494.40 FS
14	1		*REAR DOOR OUTER SEAL LH	Necessary	203.00 FS	*162.00 FS
15	1		*BONDING AGENT	Not Necessary	47.00 FS	*- FS
16	1		*CLEANING SOLUTION	Not Necessary	65.00 FS	*- FS
17	1		*APPLICATOR	Not Necessary	7.00 FS	*- FS
18	1		*REAR DOOR SEALING STRIP	Not Necessary	16.00 FS	*- FS
19	1		*REAR DOOR ATTACHMENT PARTS	Not Necessary	219.00 FS	*- FS
20	1		*REAR DOOR CATCH LH	Damaged	144.00 FS	*114.80 FS
21	1		*REAR DOOR COVER LH	Necessary	682.00 FS	*545.20 FS
22	1		*REAR WHEEL ARCH COVER LH	Necessary	576.00 FS	*461.20 FS
23	1		*SUNDRIES	Necessary	300.00 FS	*13.52 FS
Total Parts (\$)					14,449.00	7,182.32

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER LHS FRONT DOOR AND LHS REAR DOORS MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES	New	560.00	280.00
2	TO INSTALL SOLAR FILM FOR LHS FRONT DOOR WINDOW GLASS	New	400.00	400.00
3	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR. TO REPAIR LHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,800.00	1,000.00
4	TO RESPRAY LHS FRONT DOOR, LHS WING MIRROR COVER, LHS REAR DOOR, DOOR COVERS, DOOR HANDLES, LHS REAR FENDER AND LHS REAR WHEEL ARCH TRIM	New	4,600.00	2,350.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			Gross Labour Cost (\$\$)	4,222.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >