

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20010345/T1TF3E2

Date: 02/11/2020

REFERENCE

| | |
|--|--|
| Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. | Policy No: 1700092542 |
| Claimant Vehicle No : SJU4330S | Insured Vehicle No : SLV4162G |
| Date of Loss: 24/09/2020 | Nature of Claim: TP Claim No: 1048099179SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------|
| Reg No: | SJU4330S | | |
| Make & Model: | HONDA STREAM, 1.8 X (A) | Engine No: | R18A1770162 |
| Reg. Date: | 08/12/2009 (Man. Year: 2008) | Chassis No: | RN61062995 |
| Colour: | Silver | Odometer: | 145291 km |
| Engine Capacity: | 1799 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size: | 205/65 R15 | Rear Tyre Size: | 205/65 R15 |
| Front Left Side: | Goodride 6 mm | Rear Left Side: | Goodride 6 mm |
| Front Right Side: | Goodride 6 mm | Rear Right Side: | Goodride 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--------------------------|-------------|-------------|-------------|--------|
| Parts | 0.00 | 0.00 | 0.00 | |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 0.00 | 0.00 | 0.00 | |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 0.00 | 0.00 | 0.00 | |

INSPECTION

| | | |
|-----------------------------|--------------------------|---|
| Date of Assignment: | 28/09/2020 | |
| Date Inspected: | 28/09/2020 Inspected At: | 8 Kaki Bukit Avenue 4 # 04-20 Premier Repairer : A-Tec Automotive Pte Ltd (HQ) |
| Estimated Period of Repair: | 5.0 days | |

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|---------------------------|-----|----------|----------------------------|-------------|-------------|-------------|
| 1 | 1 | | *REAR BUMPER | Deformed | 0.00 F | *- F |
| 2 | 1 | | *REAR BUMPER CLIPS | Necessary | 0.00 F | *- F |
| 3 | 1 | | *REVERSE SENSOR | Not Working | 0.00 F | *- F |
| 4 | 1 | | *REAR END PANEL | Repair | 0.00 F | *- F |
| 5 | 1 | | *TAILGATE | Bent | 0.00 F | *- F |
| 6 | 1 | | *TAILGATE INNER TRIM BOARD | Cracked | 0.00 F | *- F |
| 7 | 1 | | *TAILGATE LOCK | Bent | 0.00 F | *- F |
| 8 | 1 | | *TAILGATE WEATHERSTRIP | Twisted | 0.00 F | *- F |
| 9 | 1 | | *REAR EXHAUST | Repair | 0.00 F | *- F |
| 10 | 1 | | *REAR BUMPER TOW COVER | Deformed | 0.00 F | *- F |
| F=Franchise part. | | | | | | |
| Total Parts (\$\$) | | | | | 0.00 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

< END OF ESTIMATES >