Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010350/APA3Q2

Date: 22/02/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100417209-05 Claimant SMK3505D

Insured Vehicle No: SDK6968M Vehicle No:

Date of Loss: 07/08/2020 TP Nature of Claim: Claim No: 6025585778SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SMK3505D Reg No:

Make & Model: HYUNDAI AD AVANTE, 1.6 GLS S (A) Engine No: G4FGKU117133

Reg. Date: 06/04/2019 (Man. Year: 2019) Chassis No: KMHD841CMKU885187

Colour: Odometer: 49670 km Silver

**Engine Capacity:** 1591 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15 Front Left Side: Rear Left Side: Nexen 6 mm Nexen 6 mm Front Right Side: Rear Right Side: Nexen 6 mm Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,740.72	630.00	1,110.72	63.81
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,290.00	430.00	860.00	66.67
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross	Total (S\$)	3,030.72	1,060.00	1,970.72	65.02
Approved Total (Overri	idden) (S\$)		850.00		
	(S\$)	3,030.72	850.00	2,180.72	71.95
+ GST 7.00/	7.00% (S\$)	212.15	59.50	152.65	71.95
Nett Ar	mount (S\$)	3,242.87	909.50	2,333.37	71.95
+ Car Rental (3.0 x S\$1	100.00/day + 7.	.00% GST) (S\$)	321.00		
	2.00				
	Nett Liability (S\$)		1,232.50		
	Global Sum Settlement (S\$)				

**INSPECTION** 

Date of Assignment: 28/09/2020

28/09/2020 Inspected At: Sk Automobile Pte Ltd Date Inspected:

8 Kaki Bukit Ave 4, #08-46 Premier @

Kaki Bukit

Singapore 415875

Estimated Period of Repair: 3.0 days Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

2       1       *FRONT BUMPER SIDE RETAINER RH/LH       O/S Necessary       47         3       1       *FRONT BUMPER SIDE AIR VENT RH       Deformed       35         4       1       *FRONT BUMPER SIDE AIR VENT INNER GUIDE RH       Deformed       36         5       1       *FRONT BUMPER SIGNAL LAMP RH       Cracked       164         6       1       *FRONT HEADLAMP RH       Not Necessary       1,198         7       1       *FRONT HEADLAMP LOWER BRACKET RH       Not Necessary       28         8       1       *SET FRONT BUMPER CLIPS       Necessary       80	er's	Amount						
Necessary   Necessary     Necessary	.90 FL	*474.90 FL						
4         1         *FRONT BUMPER SIDE AIR VENT INNER GUIDE RH         Deformed         38           5         1         *FRONT BUMPER SIGNAL LAMP RH         Cracked         164           6         1         *FRONT HEADLAMP RH         Not Necessary         1,198           7         1         *FRONT HEADLAMP LOWER BRACKET RH         Not Necessary         28           8         1         *SET FRONT BUMPER CLIPS         Necessary         80           9         1         *FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS         Necessary         30	.60 FL	. *23.80 FL						
5         1         *FRONT BUMPER SIGNAL LAMP RH         Cracked         164           6         1         *FRONT HEADLAMP RH         Not Necessary         1,198           7         1         *FRONT HEADLAMP LOWER BRACKET RH         Not Necessary         28           8         1         *SET FRONT BUMPER CLIPS         Necessary         80           9         1         *FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS         Necessary         30	.70 FL	*35.70 FL						
6         1         *FRONT HEADLAMP RH         Not Necessary         1,198           7         1         *FRONT HEADLAMP LOWER BRACKET RH         Not Necessary         28           8         1         *SET FRONT BUMPER CLIPS         Necessary         80           9         1         *FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS         Necessary         30	.50 FL	*38.50 FL						
Necessary	.60 FL	*164.60 FL						
8 1 *SET FRONT BUMPER CLIPS Necessary 9 1 *FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS Necessary 30	.70 FL	. *-FL						
9 1 *FRONT BUMPER SIDE AIR VENT INNER GUIDE CLIPS Necessary 30	.40 FL	. *-FL						
· · · · · · · · · · · · · · · · · · ·	.00 FS	*30.00 FS						
	.00 FS	*10.00 FS						
10 1 *FRONT HEADLAMP CLIPS SET RH Not 40 Necessary	.00 FS	s *-FS						
F=Franchise part. S=SpcNett. L=ListItemDisc.								
Sub Total (S\$) 2,138		777.50						
- List Item Discount on L Items 20.00/20.00% (S\$)397	.68	147.50						
Total Parts (S\$) 1,740	.72	630.00						
Report was unsubmitted during this print-out.								

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			-
1	TO DISMANTLE & REPLACE WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	400.00	200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	400.00	200.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	50.00	0.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	New	280.00	0.00
6	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
	Gross Labor	1,290.00	430.00	
	Report was unsubmitted duri	ng this print-out.		

< END OF ESTIMATES >