

Accident Location
City / IP / WS / IP RES / OD RES / EVA / INV / MV

To inspect Vehicle No.

At Workshop

of

Insured

Policy No.

Claims No.

Amount Insured


Excess

(If held as Freehold)

Make of Vehicle

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Balance Market Value

IDA - Accident Report

Consistent? Yes or No

GIA - PR Seen

Consistent? Yes or No

Est. Repairs

days

Res.

Yes or No

Loss claim

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle IN / OUT

Date / Time

Action / Instruction

TP A16

MV
PV
Nett

Date/Time File Entry



Prel. Report

By



Final Report

Date/Time File Production

By

Vehicle No. SMK350512

Date Recd. 2019 April

Type ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make Hyundai Avante cc 1591

Colour Silver A/C Insured / Std / Nil / NA

Sp Reading 49670 T/Radio Insured / Std / Nil / NA

Eng/Ho

C/Ho KMHD84CMKU885187

Gen Cond ☒ Good / Fair / Poor / Burnt

Steering ☒ In order / Jammed / Leaked / Burnt or

Brake ☒ In order / Jammed / Leaked / Burnt or

Modi Nil / ☒ S/Rim / STD A/Rim or

Tyre Size F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Nexen

Front

Rear

R/Bal of mm

R/Bal of mm

L/Bal of mm

L/Bal of mm

D.O.A.

D.O.I 28/09/20

Survey held at SK

Des. of Damages Frt / Rear / O/S / N/S / U/C / Rooftop or

Front of

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time File Entry



Prel. Report

By



Final Report

Date/Time File Production

By

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

Site Insp

Inspection

Production

Other

Cost Fee:



Site Insp



Inspection



Production



Other