

AJAX

Inspection Services Pte Ltd

Date : 13 December 2018

To : **NTUC Income Insurance Co-operative Limited**
73 Bras Basah Road #05-01
NTUC Trade Union House
Singapore 189556

Attn : Ms Corinne Hoo

AJAX Inspection Services Pte Ltd

120 Lower Delta Road

#08-08, Cendex Centre

Singapore 169208

Tel: +65 6255 0808

Fax: +65 6849 9155

info@ajaxinspection.com

Invoice No – AV17426

Company Reg No -201318067R

GST Reg No - 201318067R

TAX INVOICE

YOUR REF / CLAIM NUMBER : MT/1015796-001 ✓
OUR REF : AVS2018-16499/PN
TP VEHICLE NO : SJV3354A ✓
CLAIM TYPE : PRE-REPAIR SURVEY
DATE OF SURVEY : 17 October 2018

No.	Description	Amount (S\$)
1	Professional fee	100.00
	Subtotal	100.00
	GST 7.00%	7.00
	Total	107.00

Payment Terms: 30 days from date of invoice

Please remit by electronic transfer as follows:

Payee: AJAX Inspection Services Pte Ltd

United Overseas Bank Ltd

Account No: 450-309-276-4

Email remittance advice to: accounts@ajaxadjusters.com



AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155

Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

PRE-REPAIR SURVEY REPORT

NTUC Income Insurance Co-operative Ltd

73 Bras Basah Road #05-01 NTUC Trade Union House Singapore 189556

Attention: Ms Corinne Hoo

Assign Date:	16/10/2018	Survey Date:	17/10/2018	Adjustment Date:	12/12/2018
Accident Date:	11/10/2018	TP Policy No:	MT/00506715	Our Ref:	AVS2018-16499/PN
Place of Survey:	Miracle Workz Pte Ltd 48 Toh Guan Road East #04-126 Enterprise Hub Singapore 608586	Your Ref:	MT/1015796-001	Claim Type:	Third Party
		Claimant:	Ahmad Don Bin Munasip		

Description of Vehicle:

Veh. No:	SJV3354A	Make/Model:	Subaru Impreza	Sum Insured (S\$):	Market Value
Colour:	Silver	Engine No:	EL15D867941	Mkt Value (S\$):	\$16,000.00
Engine Capacity:	1498 cc	Chassis No:	JF1GH3KS59G035353	Excess (S\$):	NA
Odometer:	177855	Reg. Date:	21/01/2010		

Condition of Vehicle:

General:	Good	Modification:	No	Steering:	Serviceable
Handbrake:	Serviceable	Footbrake:	Serviceable	Paint work:	Good
Tyre Make:	Nexen				
Front Tyre Size:	225/45R17	Front Left Side:	6mm	Front Right Side:	6mm
Rear Tyre Size:	225/45R17	Rear Left Side:	6mm	Rear Right Side:	6mm

Description of Damage:

The vehicle sustained damage on the front right portion.

The front bumper and front bumper retainer were among the items affected.

Remarks:

Our recommended amount for the cost of contract lumpsum repair is S\$900.00 with approximately three (3) working days to complete. However, no finalisation was agreed with the repairer.



Adjuster:

Patrick Ng
Motor Appraiser

Date

COMPLETED 13 DEC 2018

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

<u>Adjustment of Repair Cost for Vehicle:</u>			<u>SJV3354A</u>	<u>Our Ref:</u> AVS2018-16499/PN	
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
List Items					
1	1	Front bonnet mechanism lock	Not necessary	--	--
2	4	Front bonnet rubber guide stopper L/R	Not necessary	--	--
3	1	Front grille	Not necessary	604.00	--
4	4	Front grille clips	Not necessary	26.00	--
5	1	Front air duct	Not necessary	--	--
6	2	Front air duct clips	Not necessary	13.00	--
7	1	Front LH headlamp	Not necessary	--	--
8	1	Front RH headlamp	Not necessary	874.00	--
9	1	Front RH headlamp lower bracket	Cracked	44.00	44.00
10	1	Front bumper	Damaged	654.00	654.00
11	1	Front RH bumper foglamp	Not necessary	304.00	--
12	1	Front LH bumper foglamp	Not necessary	--	--
13	1	Front bumper lower under cover	Not necessary	212.00	--
14	1	Front bumper reinforcement	Not necessary	288.00	--
15	2	Front bumper side retainer L/R	Damaged	52.00	52.00
16	1	Front bumper tow hook cover	Not necessary	19.00	--
17	1	Front support panel	Not necessary	--	--
18	1	Front RH fender	Not necessary	--	--
Sub Total:				3,090.00	750.00
Discount (less 20%):				618.00	150.00
				2,472.00	600.00

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R

AJAX

Inspection Services Pte Ltd

Adjustment of Repair Cost for Vehicle:			SJV3354A	Our Ref: AVS2018-16499/PN	
No.	Qty	Description of Parts	Condition	Third Party Surveyor's Estimate S\$	Our Recommendation S\$
Special Nett Items					
1	1	Front bumper clips - set	Necessary	30.00	30.00
2	1	Front bumper lower lip	Not necessary	400.00	--
3	1	Front bumper number plate	Not necessary	25.00	--
4	1	Front bumper number plate holder	Not necessary	50.00	--
5	1	Front RH fender inner shield clips - set	Not necessary	30.00	--
Sub Total:				535.00	30.00
Total Parts Price:				3,007.00	630.00

Labour Cost				
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp for focussing.		100.00	30.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		900.00	200.00
3	parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		1,100.00	200.00
4	To apply anti rust chemical on repaired and replaced panel.		80.00	70.00
Sub Total:			2,180.00	500.00
Grand Total:			5,187.00	1,130.00

AJAX

Note: This report is confidential and solely for the use of the client. The survey was conducted on a "Without Prejudice" basis.

AJAX Inspection Services Pte Ltd

120 Lower Delta Road, #08-08, Cendex Centre, Singapore 169208. Tel: +65 6255 0808 Fax: +65 6849 9155
Email: info@ajaxinspection.com Website: www.ajaxadjusters.com Co. Reg. No.: 201318067R