

INVOICE

TO : AHMAD DON BIN MUNASIP
C/O: MIRACLE WORKZ PTE LTD
48 TOH GUAN ROAD EAST,
#04-126 ENTERPRISE HUB,
SINGAPORE 608586

Invoice No.: 1018/MW830
Date: 30-Oct-2018

PARTICULARS

Vehicle Registration No.: SJV 3354 A
Date of Loss: 11-Oct-2018
Date of Assessment: 15-Oct-2018

SERVICES

1. Assessment with report Photographs -
Including films, developing, storage and Transport.

FEES

\$450.00

TOTAL \$450.00

SINGAPORE DOLLARS FOUR HUNDRED FIFTY ONLY

We would appreciate your cheque crossed and made payable to:
"AEON AUTO CONSULTANTS LLP" with our invoice no. written on the back of the cheque.

AEON AUTO CONSULTANTS LLP



AEON AUTO CONSULTANTS LLP

50 Chin Swee Road #09-04 Thong Chai Building Singapore 169874
Telephone +65 97687958 Facsimile +65 68264112 Email amas@aeonac.com
Reg. No. LL0701273L (registered with limited liability)

AUTOMOBILE ASSESSMENT REPORT

TO: AHMAD DON BIN MUNASIP
C/O: MIRACLE WORKZ PTE LTD
48 TOH GUAN ROAD EAST,
#04-126 ENTERPRISE HUB,
SINGAPORE 608586

Our Reference: 1018/MW830
Date: 30-Oct-2018

ASSESSMENT OF VEHICLE NO. SJV 3354 A DATE OF LOSS: 11-Oct-2018

We have carried out a physical assessment at **MIRACLE WORKZ PTE LTD**,
48 Toh Guan Road East, #04-126 Enterprise Hub, Singapore 608586, according to your instruction
on **15-Oct-2018** and are pleased to submit our report herewith.

1. VEHICLE PARTICULARS

Registration No.: SJV 3354 A
Make & Model: SUBARU IMPREZA 5D 1.5R AWD AT
Year of Registration: 2010
Engine Capacity: 1498
Chassis No.: JF1GH3KS59G035353
Engine No.: EL15D867941
Colour: SILVER
Mileage (km): 177853

2. VEHICLE CONDITION

Body Paint: GOOD
Steering: SERVICEABLE
Foot Brake: SERVICEABLE
Parking Brake: SERVICEABLE
Modification: NIL

3. TYRE PARTICULARS & CONDITION


Front
RH Make/Size/Thread: ACHILLES 225/45 R17 – 75%
LH Make/Size/Thread: ACHILLES 225/45 R17 – 75%
Rear
RH Make/Size/Thread: ACHILLES 225/45 R17 – 75%
LH Make/Size/Thread: ACHILLES 225/45 R17 – 75%

4. DESCRIPTION OF DAMAGE

At the time of the inspection, the vehicle sustained damages to the FRONT portion.

5. REMARKS

Market Value:	Na
Salvage Value:	Na
Repair Limit:	Na
Estimated Amount:	\$7,409.16
Adjusted Amount:	\$5,187.00
Lump Sum:	\$4,500.00
Estimated Repair Days:	6 days



Pursuant to your instruction, we have **NOT AUTHORISED** repair.
The assessment was conducted on a "**Without Prejudice**" basis.
If we are not notified of anything to the contrary within **14 days** from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by Aeon Auto Consultants LLP for any reliance on this report by any third party.

ASSESSMENT REPORT FOR VEHICLE NO. SJV 3354 A

PARTS (LIST ITEMS)

Qty	Description	Condition	Workshop's Estimate	Our Assessment
1	FRONT BONNET MECHANISM LOCK	Repair	84.00	-
4	FRONT BONNET RUBBER GUIDE STOPPER L/R	Repair	35.60	-
1	FRONT GRILLE	Cracked	604.00	604.00
4	FRONT GRILLE CLIPS	Necessary	26.00	26.00
1	FRONT AIR DUCT	Repair	56.00	-
2	FRONT AIR DUCT CLIPS	Necessary	13.00	13.00
1	FRONT LH HEADLAMP	Repair	874.00	-
1	FRONT RH HEADLAMP	Cut	874.00	874.00
1	FRONT RH HEADLAMP LOWER BRACKET	Bent	44.00	44.00
1	FRONT BUMPER	Cracked	654.00	654.00
1	FRONT RH BUMPER FOGLAMP	Cracked	304.00	304.00
1	FRONT LH BUMPER FOGLAMP	Repair	304.00	-
1	FRONT BUMPER LOWER UNDER COVER	Cracked	212.00	212.00
1	FRONT BUMPER REINFORCEMENT	Bent	288.00	288.00
2	FRONT BUMPER SIDE RETAINER L/R	Bent	52.00	52.00
1	FRONT BUMPER TOW HOOK COVER	Necessary	19.00	19.00
1	FRONT SUPPORT PANEL	Repair	636.60	-
1	FRONT RH FENDER	Repair	300.00	-
			5,380.20	3,090.00
		Less 20% discount	1,076.04	618.00
		Parts Total:	4,304.16	2,472.00

ASSESSMENT REPORT FOR VEHICLE NO. SJV 3354 A

SPECIAL NETT ITEMS

1	FRONT BUMPER CLIPS - SET	Necessary	30.00	30.00
1	FRONT BUMPER LOWER LIP	Cracked	400.00	400.00
1	FRONT BUMPER NUMBER PLATE	Bent	25.00	25.00
1	FRONT BUMPER NUMBER PLATE HOLDER	Bent	50.00	50.00
1	FRONT RH FENDER INNER SHIELD CLIPS - SET	Cracked	30.00	30.00
Special Nett Total :			535.00	535.00

LABOUR

S/N	Description		Workshop's Estimate	Our Assessment
1	To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing.		120.00	100.00
2	To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.		1,050.00	900.00
3	To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.		1,300.00	1,100.00
4	To apply anti-rust chemical on repaired and replaced panel.		100.00	80.00
Labour Total :			2,570.00	2,180.00
TOTAL (PARTS & LABOUR) \$			7,409.16	5,187.00

The workshop has agreed to undertake the repair on a Lump Sum basis.

The final adjusted Lump Sum contract amount is

\$4,500.00

(SINGAPORE DOLLARS FOUR THOUSAND FIVE HUNDRED ONLY)



Amas Ong
Automobile Assessor