



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

AlG
Admin
LKC

26/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAIG.
Khanchaa.

Accident date: 24/09/2020

Estimated repair cost for vehicle no: GBK1536H TOYOTA HIACE VAN TURBO 5DR 20'

CHASSIS: JTFHT02P600250001

S/n	Qty	Items / List	U/price	Amount
1	1	Rear Boot Lid <i>Dented.</i>		\$1,712.45 ✓
2	2	Rear Boot Lid Hinge <i>Not new</i>	\$171.70	\$343.40 +
3	2	Rear Boot Lid Shock Absorber <i>Damaged.</i>	\$374.45	\$748.90 ✓
4	1	Rear Boot Lid Toyota Hiace Sticker <i>new</i>		\$57.60 ✓
5	1	Rear Boot Lid 8Pax Sticker <i>new</i>		\$30.00 (d/su)
6	1	Rear Boot Lid Emblem Logo <i>new</i>		\$41.10 ✓
7	1	Rear Boot Lid Centre Moulding <i>new</i>		\$281.90 x.
8	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$374.25 ✓
9	1	Rear Boot Lid Inner Power Lock <i>new</i>		\$276.20 +
10	1	Rear Boot Lid Inner Rubber <i>ut</i>		\$381.90 ✓
11	1	Rear Boot Lid Inner Aluminum Panel <i>new</i>		\$1,000.00 250(su)
12	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$105.00 ✓
13	1	Rear R/H Tail Lamp <i>ut</i>		\$371.45 ✓
14	1	Rear R/H Tail Lamp Panel <i>Dented</i>		\$355.80 ✓
15	1	Rear R/H Tail Lamp Lower Cover <i>new</i>		\$182.10 ✓
16	1	Rear R/H Tail Lamp Lower Cover Retainer <i>new</i>		\$171.45 +
17	2	Rear R/H Tail Lamp Clip <i>new</i>	\$8.00	\$16.00 ✓
18	1	Rear R/H Fender <i>Repair</i>		\$1,989.90 x.
19	1	Rear R/H Fender Air Duct <i>2 x 1</i>		\$172.45 +
20	1	Rear R/H Fender Inner Panel <i>new</i>		\$631.35 x.
21	1	Rear Bumper <i>Dented</i>		\$374.45 ✓
22	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00 30.
23	1	Rear R/H Bumper Side Retainer <i>new</i>		\$131.35 65
24	1	Rear End Panel Outer <i>Dented</i>		\$581.10 ✓
25	1	Rear End Panel Inner <i>Dented</i>		\$591.25 ✓
26	8	Rear End Panel Top Clip <i>new</i>	\$6.50	\$52.00 x.
27	1	Rear Floor Panel <i>Repair</i>		\$1,850.00 x.

28	1	Rear Floor Panel Top Moulding	314	\$174.10	X
29	8	Rear Floor Panel Top Moulding Clip	314	\$6.50	\$52.00 X
30	1	Rear R/H Inner Aluminium Panel	Buckled	\$2,000.00	500(SN) X
31	1	Rear Floor Panel Aluminium (Special Nett)	XHP new	\$3,000.00	X
32	1	Rear Spare Tyre Bracket	XHP new	\$172.10	X
33	1	Rear Exhaust	Bent	\$1,712.85	725 X
34	1	Rear Centre Exhaust	XHP new	\$1,829.10	X
35	1	Rear Boot Lid Windscreen Seal	Replaced	\$105.00	X

6713.35
5035.01
Subtotal :- \$21,933.50
S-N: 750

S/n	Qty	Items / Special Nett	U/price	Amount
36	1	Rear Boot Lid 70km/H Sticker	XHP	\$20.00 10
37	1	Rear Boot Lid Number Plate	XHP new	\$50.00 X
38	1	Rear Bumper Reverse Sensor	Damaged	\$350.00 200

210
Subtotal :- \$420.00

Labour charges

To remove & refit reverse sensor	\$100.00 50
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30
Tuff kote	\$150.00 80
Panel beating	\$1,400.00 1000
Spray painting	\$1,400.00 800

Subtotal :- \$3,320.00

Supplementary: 123.75
Total:- \$25,673.50

total 8248.76

L/S: 66K

07 Days

66K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com Website: www.nhtmotor.com

Tel: 6747 9241 Fax: 6741 7276

UEN: 201718370K GST Reg No.: 201718370K

02/09/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 24/09/2020

Supplementary repair cost for vehicle no: GBK1536H TOYOTA HIACE VAN TURBO 5DR 20'

CHASSIS: JTFHT02P600250001

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid Inner Trimboard <i>torn</i>		\$372.50 165
Subtotal :-				\$372.50

165
Supplementary: 123.75