

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20010354/EBA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MCV0004636
Claimant Vehicle No :	SKF6182G	Insured Vehicle No :	GBD4537Y
Date of Loss:	25/09/2020	Nature of Claim:	TP
		Claim No:	MCV2020D0001885

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKF6182G	Engine No:	170825W0062204DTD
Make & Model:	JAGUAR XE, 2.0 D L I4D (A)	Chassis No:	SAJAB4AN2JCP29845
Reg. Date:	07/11/2017 (Man. Year: 2017)	Odometer:	71305 km
Colour:	White		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	225/45 R18
Front Left Side:	Goodyear 5 mm	Rear Left Side:	Goodyear 5 mm
Front Right Side:	Goodyear 5 mm	Rear Right Side:	Goodyear 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	24,054.25	15,865.08	8,189.17	34.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	22,110.00	12,800.00	9,310.00	42.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	46,164.25	28,665.08	17,499.17	37.91
+ GST 7.00/7.00% (S\$)	3,231.50	2,006.56	1,224.94	37.91

Nett Amount (S\$)	49,395.75	30,671.64	18,724.11	37.91
+ Medical Costs (S\$)		254.15		
+ Car Rental (12.0 x S\$130.00/day + 7.00% GST) (S\$)		1,669.20		
Nett Liability (S\$)		32,594.99		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020

Estimated Period of Repair: 12.0 days

Inspected At: Wearnes Automotive Pte Ltd (Leng Kee)
28 Leng Kee Road
Singapore 159105

Adjuster: CHEN TSUE YEE**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Apr 2021)
Parts:	143	JAGUAR XE 2.0 D L I4D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKF6182G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*NUMBER PLATE & HOLDER (FRONT & BACK)	Cut	120.00 FS	*60.00 FS
2	1		*COVER- BUMPER	Dented	1,861.00 FS	*1,674.90 FS
3	1		*GRILLE -RADIA	Broken	473.50 FS	*426.15 FS
4	1		*BRACKET -FEND RH	Not Necessary	37.10 FS	*- FS
5	1		*BRACKET -FEND LH	Not Necessary	37.10 FS	*- FS
6	1		*PANEL -NOSE	Not Necessary	97.30 FS	*- FS
7	1		*INSERT -FOAM	Not Necessary	57.50 FS	*- FS
8	1		*JT2H25309/BEAM BUMPE	Not Necessary	953.90 FS	*- FS
9	1		*WHEEL -18 REAR TEM	Cut	857.60 FS	*771.84 FS
10	1		*COVER BUMPER REAR	Broken	1,068.20 FS	*961.38 FS
11	1		*PANEL -VALANC	Cut	491.50 FS	*442.35 FS
12	1		*MOUNTING -BRACKET LHR	Not Necessary	115.80 FS	*- FS
13	1		*MOUNTING -BRACKET RR	Broken	97.20 FS	*87.48 FS
14	1		*MOUNTING -BRACKET RH	Broken	115.80 FS	*104.22 FS
15	1		*BUMPER BEAM REAR XE	Not Necessary	607.30 FS	*- FS
16	1		*PARKING AID SENSOR R (6 PCS)	Broken (1 PCS ONLY)	1,419.00 FS	*212.85 FS
17	1		*QUARTER PANEL REAR R	Dented	1,672.10 FS	*1,504.89 FS
18	1		*REAR WINDSCREEN XE	Necessary	1,183.20 FS	*1,064.88 FS
19	4		*WINDSCREEN SPACER	Necessary	32.80 FS	*29.52 FS
20	2		*JC2D7026/SEALANT WIN	Necessary	319.00 FS	*287.10 FS
21	1		*PRIMER	Necessary	185.60 FS	*167.04 FS
22	1		*FLAP -FUEL FILLER	Repair	227.50 FS	*- FS
23	1		*PANEL -REAR XE	Repair	647.60 FS	*- FS
24	1		*PANEL -REAR OUTER	Repair	1,818.60 FS	*- FS
25	1		*TAILLAMP RH XE	Broken	430.20 FS	*387.18 FS
26	1		*REAR LAMP FOG RH XE	Not Necessary	347.20 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*SOUND DEADENING PAD	Necessary	525.40 FS	*472.86 FS
28	1		*3M07333 IMPACT RESIS	Necessary	84.10 FS	*75.69 FS
29	1		*3M08115 PANEL BONDIN	Necessary	68.30 FS	*61.47 FS
30	1		*VLINDER -WHEELARCH RHR	Crushed	259.90 FS	*233.91 FS
31	1		*DUCT GRILLE RHR	Broken	52.80 FS	*47.52 FS
32	1		*ADHESIVE SEALER FL2	Necessary	703.00 FS	*632.70 FS
33	1		*BODY PANEL SEALANT	Not Necessary	928.00 FS	*- FS
34	1		*GESTURE MODULE -CONTR	Broken	308.88 FS	*308.88 FS
35	1		*LOWER GESTURE SENSOR	Shorted	423.36 FS	*423.36 FS
36	1		*UPPER GESTURE SENSOR	Shorted	348.75 FS	*348.75 FS
37	1		*INSERT -FOAM	Broken	51.75 FS	*51.75 FS
38	1		*INSERT	Broken	21.69 FS	*21.69 FS
39	1		*BEAM -BUMPER	Bent	858.51 FS	*858.51 FS
40	1		*HEADLAMP LH	Broken	3,277.62 FS	*3,277.62 FS
41	1		*PANEL -EXTENSION	Crushed	96.30 FS	*96.30 FS
42	1		*HARNESS REAR	Torn	387.72 FS	*387.72 FS
43	1		*RIVET FSC4850 4.8X5 (30 PCS)	Necessary	81.00 FS	*81.00 FS
44	5		*RIVET FSC4870 4.8X7	Necessary	10.80 FS	*10.80 FS
45	3		*RIVET	Necessary	4.86 FS	*4.86 FS
46	8		*RIVET	Necessary	12.24 FS	*12.24 FS
47	10		*RIVET 5.3MM X 7.0MM	Necessary	16.20 FS	*16.20 FS
48	3		*RIVET	Necessary	6.48 FS	*6.48 FS
49	5		*RIVET 5.5X5	Necessary	8.10 FS	*8.10 FS
50	5		*RIVET	Necessary	14.85 FS	*14.85 FS
51	10		*RIVET	Necessary	14.40 FS	*14.40 FS
52	10		*RIVET 6.5X13X20 XJL	Necessary	55.80 FS	*55.80 FS
53	10		*RIVET 6.5X13X17.5 XJ	Necessary	30.60 FS	*30.60 FS
54	10		*RIVET 6.5X13X16 XJL	Necessary	14.40 FS	*14.40 FS
55	10		*RIVET	Necessary	29.70 FS	*29.70 FS
56	1		*SHIELD -DEFLE	Broken	85.14 FS	*85.14 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	24,054.25	15,865.08
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE FRT BUMPER ,RADIATOR GRILLE ,BUMPER BEAM,REAR BUMPER ,REAR RH QTR PANEL ,REAR VALANCE, END PANEL REPAIR REAR RH DOOR ,ETC	New	8,100.00	5,850.00
2	TO SPRAYPAINT & BLEND ON FRT BUMPER ,REAR BUMPER ,REAR END PANEL,REAR RH QTR PANEL ,REAR RH DOOR	New	5,600.00	3,200.00
3	TO REPLACE REAR WINDSCREEN	New	900.00	600.00
4	TO INSTALL REAR WINDSCREEN FIL	New	280.00	280.00
5	TO REMOVE ,REFIT CARPET LINING INTERIOR TRIMMING ,REAR BOOT INTERIOR	New	2,700.00	1,350.00
6	TO REPLACE REAR UNDERCARRIAGE	New	2,800.00	0.00
7	TO REPLACE REAR RH TYRE (70%)	New	700.00	490.00
8	TO REPLACE REAR RH RIM	New	50.00	50.00
9	WHEEL ALIGNMENT	New	280.00	280.00
10	TO FOCUS HEADLAMP	New	175.00	175.00
11	TO CHECK WIRING INCLUDE RESETING OF ALL ELECTRICAL MODULES	New	525.00	525.00
Gross Labour Cost (\$\$)			22,110.00	12,800.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >