Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010357/T1RA3Q2

Date: 20/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100455533

Claimant Vehicle No: SLE1708S Insured Vehicle No: SLA6824C

Date of Loss: 25/09/2020 Nature of Claim: TP Claim No: 5058041906SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE1708S

 Make & Model:
 HONDA VEZEL, 1.5 (A)
 Engine No:
 L15B4401623

 Reg. Date:
 12/07/2016 (Man. Year: 2016)
 Chassis No:
 RU11201623

 Colour:
 Bronze
 Odometer:
 54449 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm
Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,829.24	1,878.28	4,950.96	72.50
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,710.00	1,470.00	1,240.00	45.76
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	9,539.24	3,348.28	6,190.96	64.90
	+ GST 7.00/7.00% (S\$)	667.75	234.38	433.37	64.90
	Nett Amount (S\$)	10,206.99	3,582.66	6,624.33	64.90

+ Loss of Use (4.0 x S\$60.00/day) (S\$) 240.00 + Car Rental (1.0 x S\$110.00/day + 7.00% GST) (S\$) 117.70 + Doc/Search Fee (S\$) 2.00

Nett Liability (S\$) 3,942.36

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 01/10/2020 Inspected At: ComfortDelGro Engineering Pte Ltd

(Pandan) 45 Pandan Road Singapore 609286

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: Jaslin Kok Chin Yi

Adjuster Report Page 2 of 4

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR WINDSCREEN	Not Necessary	1,300.50 FL	*- FL	
2	1		*SET REAR WINDSCREEN MOULDING	Necessary	171.82 FL	*171.82 FL	
3	2		*SEALANT REAR WINDSCREEN	Necessary	40.00 FS	*40.00 FS	
4	1		*INNER SEAL TAPE REAR WINDSCREEN	Necessary	40.00 FS	*40.00 FS	
5	1		*TAIL GATE	Bent	1,100.90 FL	*1,100.90 FL	
6	1		*LOGO -HONDA	Necessary	27.10 FL	*27.10 FL	
7	1		*EMBLEM -VEZEL	Necessary	65.00 FL	*65.00 FL	
8	1		*REAR BUMPER	Deformed	508.72 FL	*508.72 FL	
9	10		*CLIP REAR BUMPER	Necessary	39.00 FL	*39.00 FL	
10	1		*L/ REAR SIDE RETAINER	Not Necessary	25.70 FL	*- FL	
11	1		*R/ REAR SIDE RETAINER	Not Necessary	25.70 FL	*- FL	
12	1		*REAR END PANEL	Repair	4,141.80 FL	*- FL	
13	1		*REAR END PANEL GARNISH	Not Necessary	95.00 FL	*- FL	
14	1		*SET SENSOR REAR BUMPER	Not Working	300.00 FS	*200.00 FS	
15	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	300.00 FS	*- FS	
16	1		*BODY SEALANT	Not Necessary	80.00 FS	*- FS	
17	1		*REVERSE BUZZER	Cracked	85.31 FL	*85.31 FL	
F=Fra	anchise	part. S=Spcl	Nett. L=ListItemDisc.				
				Sub Total (S\$)	8,346.55	2,277.85	
			- List Item Discount on L Items	20.00/20.00% (S\$) __	1,517.31	399.57	
				Total Parts (S\$)	6,829.24	1,878.28	
	Report was unsubmitted during this print-out.						
Report was unsubmitted during this print-out.							

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE REPACE ,STRAIGHTEN ,PANEL BEAT ,CUT,WELD ,TAIL GATE ,REAR END PANEL ,RR BUMPER AND AFFECTED AREAS	New	1,200.00	700.00
2	TO PUTTY ,SPRAY PAINT ON TAIL GAT ,END PANEL,BUMPER AND DAMAGED AFFECTED AREA	New	900.00	500.00
3	TO REMOVE ,REFIT TAIL GATE TRIME COVER ,RR WIPER MOTOR & ARM ,LOCK TO FACILITATE REPAIR	l New	200.00	60.00
4	TO CHECK WIRE	New	60.00	30.00
5	TO REMOVE ,REPLACE REAR WINDSCREEN	New	150.00	120.00
6	TO REMOVE REFIT REAR COMPARTMENT LUGGAGE COVER TO FACILITATE REPAIR	New	200.00	60.00
	Gross Labou	r Cost (S\$)	2,710.00	1,470.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >