

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20010359/T1GA3Q2

**Date:** 15/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800115456

**Claimant**  
**Vehicle No :** SH7012C **Insured Vehicle No :** SCR1881L

Date of Loss: 25/09/2020 Nature of Claim: TP Claim No: 8854774699SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7012C	Engine No:	2ZRS042641
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKB3FU103556797
Reg. Date:	25/05/2017 (Man. Year: 2017)	Odometer:	402416 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,750.06	1,951.76	798.30	29.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,360.00	990.00	370.00	27.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,110.06</b>	<b>2,941.76</b>	<b>1,168.30</b>	<b>28.43</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>(S\$)</b>	4,110.06	2,350.00	1,760.06	42.82
<b>+ GST 7.00/7.00% (S\$)</b>	287.70	164.50	123.20	42.82
<b>Nett Amount (S\$)</b>	<b>4,397.76</b>	<b>2,514.50</b>	<b>1,883.26</b>	<b>42.82</b>
<b>+ Loss of Use (5.0 x S\$50.00/day) (S\$)</b>		250.00		
<b>+ Car Rental (5.0 x S\$125.40/day) (S\$)</b>		627.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,393.50</b>		
<b>Global Sum Settlement (S\$)</b>		<b>3,300.00</b>		

### INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020 Inspected At:

ComfortDelGro Engineering Pte Ltd  
(Loyang)  
59 Loyang Drive  
Singapore 508969

Estimated Period of Repair: 3.0 days

---

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Repair	499.90 FL	*- FL
2	1		*FRONT BUMPER BRKT LH	Not Necessary	77.00 FL	*- FL
3	1		*FRONT FENDER LH	Bent	945.30 FL	*945.30 FL
4	1		*FRONT FENDER SHIELD LH	Not Necessary	199.50 FL	*- FL
5	1		*FRONT FENDER (HYBRID) LH	Necessary	86.50 FL	*86.50 FL
6	1		*FRONT WHEEL RIM LH	Cut	1,570.55 FL	*1,570.55 FL
7	1		*FRONT WHEEL TYRE LH	Not Necessary	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>3,594.75</b>	<b>2,602.35</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	844.69	650.59
<b>Total Parts (\$)</b>	<b>2,750.06</b>	<b>1,951.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING	New	700.00	480.00
2	SPRAYPAINT CHARGE	New	500.00	400.00
3	TUFF COAT ON AFFECTED PARTS	New	40.00	30.00
4	WHEEL ALIGNMENT	New	120.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,360.00</b>	<b>990.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >