

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20010361/T1ES3Q2
Date: 13/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700016386
Claimant
Vehicle No : SH6200H **Insured Vehicle No :** SLP7895L
 Date of Loss: 25/09/2020 Nature of Claim: TP Claim No: 5968222822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SH6200H**
 Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A) Engine No: D4FDHU723437
 Reg. Date: 20/12/2017 (Man. Year: 2016) Chassis No: KMHLB41UMHU098908
 Colour: Blue Odometer: 158401 km
 Engine Capacity: 1685 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
 Front Left Side: Davanti 6 mm Rear Left Side: Davanti 6 mm
 Front Right Side: Davanti 6 mm Rear Right Side: Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	337.04	337.04	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,630.00	1,230.00	400.00	24.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,967.04	1,567.04	400.00	20.34
+ GST 7.00/7.00% (S\$)	137.69	109.69	28.00	20.34
Nett Amount (S\$)	2,104.73	1,676.73	428.00	20.34
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Car Rental (4.0 x S\$116.95/day) (S\$)		467.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,346.53		
Global Sum Settlement (S\$)		2,340.00		

INSPECTION

Date of Assignment: 28/09/2020
 Date Inspected: 28/09/2020 Inspected At: ComfortDelGro Engineering Pte Ltd
 (Loyang)
 59 Loyang Drive
 Singapore 508969
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR APPS STICKER LH	Cut	80.00 FS	*80.00 FS
2	1		*REAR WHEEL CAP LH	Cut	107.10 FL	*107.10 FL
3	1		*REAR WHEEL CAP RH	Cut	107.10 FL	*107.10 FL
4	1		*FRT WHEEL CAP RH	Cut	107.10 FL	*107.10 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	401.30	401.30
- List Item Discount on L Items 20.00/20.00% (S\$)	64.26	64.26
Total Parts (S\$)	337.04	337.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING -REAR FENDER LH ETC	New	600.00	560.00
2	SPRAYPAINT -ROCKER PNL GARNISH LH ETC	New	750.00	500.00
3	TUFF COAT ON AFFECTED PARTS	New	100.00	30.00
4	WHEEL ALIGNMENT	New	120.00	80.00
5	TOWING FEE	New	60.00	60.00
			Gross Labour Cost (\$)	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >