

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20010365/UGA3Q2
Date: 18/05/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100441189
Claimant Vehicle No :	SMG1792A	Insured Vehicle No :	SKX2246M
Date of Loss:	26/09/2020	Nature of Claim:	TP
		Claim No:	3527017160SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMG1792A	Engine No:	3A92UHK0323
Make & Model:	MITSUBISHI ATTRAGE, 1.2 CVT (A)	Chassis No:	MMBSTA13AJH004354
Reg. Date:	07/12/2018 (Man. Year: 2018)	Odometer:	253014 km
Colour:	Red		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/50 R15	Rear Tyre Size:	195/50 R15
Front Left Side:	Falken 7 mm	Rear Left Side:	Falken 7 mm
Front Right Side:	Falken 7 mm	Rear Right Side:	Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,842.00	10,359.50	11,482.50	52.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	3,810.00	2,950.00	43.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	28,602.00	14,169.50	14,432.50	50.46
Approved Total (Overridden) (S\$)		11,300.00		

(S\$)	28,602.00	11,300.00	17,302.00	60.49
+ GST 7.00/7.00% (S\$)	2,002.14	791.00	1,211.14	60.49
Nett Amount (S\$)	30,604.14	12,091.00	18,513.14	60.49
+ Loss of Use (12.0 x S\$50.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,693.00		

INSPECTION

Date of Assignment: 28/09/2020

Date Inspected: 28/09/2020

Estimated Period of Repair: 10.0 days

Inspected At:

Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay
 Singapore 417883

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Distorted	781.00 F	*708.00 FL
2	1		*REAR BUMPER REFLECTORS	N/S Cracked	132.00 F	*45.00 FL
3	1		*REAR BUMPER LOWER SPOILER	Cracked	1,643.00 F	*1,000.00 FL
4	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	110.00 F	*- FL
5	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
6	1		*BOOTLID	Dented / Bent	988.00 F	*828.00 FL
7	1		*BOOTLID REAR LOGO	Necessary	45.00 F	*45.00 FL
8	1		*BOOTLID ATTRAGE EMBLEM	Necessary	48.00 F	*48.00 FL
9	1		*BOOTLID MIVEC EMBLEM	Necessary	46.00 F	*46.00 FL
10	1		*BOOTLID C&C LOGO	Necessary	45.00 F	*45.00 FL
11	1		*BOOTLID INNER LOCK	Bent	206.00 F	*206.00 FL
12	1		*BOOTLID WEATHERSTRIP	Twisted	199.00 F	*162.00 FL
13	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	345.00 F	*- FL
14	1		*REAR END PANEL	Badly Dented	515.00 F	*402.00 FL
15	1		*REAR END PANEL TOP GARNISH	Twisted	198.00 F	*98.00 FL
16	1		*REAR END PANEL OUTER AIR VENT	Distorted	68.00 F	*68.00 FL
17	1		*REAR EXHAUST	Not Necessary	755.00 F	*- FL
18	1		*REAR EXHAUST MOUNTING	Not Necessary	35.00 F	*- FL
19	1		*REAR FLOOR PANEL	Repair	885.00 F	*- FL
20	1		*REAR FLOOR PANEL TOP BOARD	Torn	299.00 F	*266.00 FL
21	2		*REAR FENDERS	Repair	1,982.00 F	*- FL
22	1		*REAR FENDER INNER TRIMS	N/S Torn	598.00 F	*242.00 FL
23	1		*REAR WINDSCREEN MOULDING	Not Necessary	68.00 F	*- FL
24	1		*REAR SMART BUZZLE	Cracked	166.00 F	*166.00 FL
25	1		*REAR SMART ANTENNA	Cracked	132.00 F	*132.00 FL
26	1		*TAILLAMPS	N/S Cracked	798.00 F	*276.00 FL
27	2		*TAILLAMP HOUSING PANELS	Repair	490.00 F	*- FL
28	1		*FRONT BUMPER	Deformed / Torn	755.00 F	*696.00 FL
29	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	50.00 F	*- FL
30	1		*FRONT BUMPER REINFORCEMENT	Dented	485.00 F	*455.00 FL
31	1		*FRONT BUMPER LOWER CENTRE GRILLE	Twisted	166.00 F	*142.00 FL
32	1		*SET FRONT BUMPER CLIPS	Necessary	35.00 F	*35.00 FL
33	1		*FRONT BUMPER LOWER SPOILER	Cracked	880.00 F	*800.00 FL
34	1		*FRONT GRILLE	Cracked	548.00 F	*548.00 FL
35	1		*FRONT GRILLE LOGO	Necessary	51.00 F	*51.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	2		*HEADLAMPS	Cracked	1,700.00 F	*1,308.00 FL
37	1		*FRONT SUPPORT PANEL	Dented / Bent	1,055.00 F	*905.00 FL
38	1		*FRONT SUPPORT PANEL TOP GRILLE	Twisted	450.00 F	*315.00 FL
39	1		*BONNET	Not Necessary	734.00 F	*- FL
40	1		*AIR CON CONDENSER	Not Necessary	759.00 F	*- FL
41	1		*RADIATOR	Cracked	967.00 F	*967.00 FL
42	1		*RADIATOR FAN ASSY	Not Necessary	850.00 F	*- FL
43	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
44	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
45	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
46	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
47	1		*SET REAR FLOOR PANEL INSULATOR	Necessary	250.00 FS	*120.00 FS
48	1		*FRONT LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,842.00	11,465.00
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	1,105.50
Total Parts (\$\$)	21,842.00	10,359.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	80.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
7	TO REFILL AIR CON GAS	New	100.00	100.00
8	TO SPRAY RUST PROOFING	New	100.00	90.00
9	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
10	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,800.00	1,600.00
11	TO PUTTY & SPRAY PAINTING	New	2,800.00	1,800.00
Gross Labour Cost (S\$)			6,760.00	3,810.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >